



CATALOG
Earthmoving & Construction Machinery



DESCRIPTION

Online thematic auction of various earthmoving and construction machines,

START

24 february 2026 to 09:00 [UTC]

END DATE

6 march 2026 from 10:00 [UTC]

VIEWING

- Lots: 1, 2
Only by appointment through the organizer.
Tuesday March 03 2026 from 09:30 until 10:00
BE-7090 BRAINE LE COMTE, CHAUSSÉE
D'ECAUSSINNES 110

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622

ISSUE - COLLECTION

- Lots: 1, 2

Thursday March 12 2026 from 09:30 until 10:00
BE-7090 BRAINE LE COMTE, CHAUSSÉE
D'ECAUSSINNES 110

Online bidding only!

Catalog created on 6 march 2026 to 04:00





AUCTIM
ONLINE AUCTIONS

AUCTIM - MOYERSON NV
Helststraat 47
2630 Aartselaar, Belgium
VAT BE 0452 153 622

www.auctim.com
info.moyersoem@auctim.be



	Item	Description	Start price
	1	<p>Brand: MECALAC Model: 11 CX Product Category: Wheeled Crane Year of Manufacture (yyyy): 1990 First Registration (dd/mm/yyyy): 27/01/1991 Operator Reading (hours): 10156 Fuel: Diesel Engine Power (kW): 56 Number of Keys: 1 Exterior Color: Yellow Unladen Weight (kg): 8500 Accessories: 0.45m Toothed Bucket, 2.20m Cleaning Bucket 2 additional hydraulic lines Side hydraulic stabilizers Bucket width (mm): 2200 Lighting: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Not present Service logbook: Not present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Description of vehicle damage: Bodywork with visible cosmetic defects (scratches, dents, dings). Condition: Used Quantity: 1</p>	1.500€
	2	<p>Make: YPM Model: WY 1.3A Year of manufacture (yyyy): 1990 Odometer reading (hours): 1918 Serial number: 90222 Fuel: Diesel Engine power (kW): 10.9 Number of keys: 1 Exterior color: Orange Unladen weight (kg): 1300 Accessories: 1 x 0.8m ditch cleaning tank, 1 x</p>	1.000€



		<p>0.26m trenching tank Additional information: No documents present (certificate of conformity, technical data sheet, etc.). Replacement: Pistons, connecting rod bearings, new cylinder head, new injectors The rebuilt engine has 300 hours since the repair. Registration certificate: Not present, see additional information Certificate of conformity: Not present. (Import within the European Union) Inspection Certificate: Not present Service Booklet: Not present Visible Vehicle Damage: Yes, you can still consult the photo report for a detailed overview of the visible damage. Description of Vehicle Damage: Plexiglass rear cab window, missing front cab window, bodywork with visible cosmetic defects (scratches, dents, dings). Condition: Used Quantity: 1</p>	
--	--	--	--