



CATALOG

Commercial vehicles



DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

15 june 2024 to 08:00 [UTC]

END DATE

25 june 2024 from 09:00 [UTC]

VIEWING

- ---
Wednesday June 19 2024 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622


ISSUE - COLLECTION

- ---
Wednesday July 03 2024 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47


Online bidding only!

Catalog created on 25 june 2024 to 04:00




	Item	Description	Start price
	3	<p>Brand: Ford Model: Ranger Version: Double Cab. Wildtrak 2.0 BiTDCi Year of construction (yyyy): 2021 Product Category: Pick-Up Truck First registration (dd/mm/yyyy): 19/05/2021 Fuel: Diesel Read odometer reading (km): 73238 Chassis number: 6FPPXXMJ2PMU72247 Number of keys: 2 Number of axles: 2 Maximum Allowable Mass (kg): 3270 Transmission: Automatic transmission Cylinder capacity cc: 1997 Engine power kW: 156 Emission class: Euro 6 Exterior color: Silver Metallic colour: Yes Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Towbar: Yes Seat heating: Yes Other options: Double cabin DAB tuner Mountain Top Roll cover Registration certificate: Not present: the buyer will receive a certificate of loss of registration</p>	100€




		<p>certificate Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 15/12/2024 Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview. condition: Used Quantity: 1</p>	
	4	<p>Brand: Renault Model: Traffic Version: Fourgon/Grand Confort L2H1 Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 01/09/2021 Fuel: Diesel Read odometer reading (km): 114944 Chassis number: VF1FL000868175588 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3050 Transmission: Automatic transmission Cylinder capacity cc: 1997 Engine power kW: 107 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes</p>	100€




		<p>Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages notifications dashboard condition: Used Quantity: 1</p>	
	7	<p>Brand: Citroen Model: Jumpy Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 07/09/2020 Fuel: Diesel Read odometer reading (km): 77264 Chassis number: VF7VFAHKKL7019735 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3100 Transmission: Manual transmission Engine capacity cc: 1997 Engine power kW: 90 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Fog lights: Yes</p>	100€




		<p>Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Towbar: Yes Other options: DAB tuner Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 10/09/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	
	8	<p>Brand: Isuzu Model: D-Max Version: LS Life Year of construction (yyyy): 2019 Product Category: Pick-Up Truck First registration (dd/mm/yyyy): 21/10/2019 Fuel: Diesel Read odometer reading (km): 136771 Chassis number: MPATFS87JKT015814 Number of keys: 1 Number of axles: 2 Maximum Allowable Mass (kg): 3000 Transmission: Automatic transmission Cylinder capacity cc: 1898 Engine power kW: 120 Emission class: Euro 6b Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning</p>	100€




		<p>Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Towbar: Yes Seat heating: Yes Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 23/10/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	9	<p>Brand: Mercedes-Benz Model: Sprinter Version: 314 CDI Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 17/05/2018 Fuel: Diesel Read odometer reading (km): 71126 Chassis number: WDB9061351N749398 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Truck Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2143</p>	100€




		<p>Engine power kW: 105 Emission class: Euro 6b Co2 emissions g/km: 203 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Towbar: Yes Additional information: including remaining contents Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 23/03/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	
	10	<p>Brand: BW Model: 02T First registration (dd/mm/yyyy): 25/10/2016 Trailer category: O2: max. mass >750kg - <3500kg Trailer type: Tipper Chassis number: YB83500KBT1638749 Maximum Allowable Mass (kg): 3500 Inner dimensions (L x W x H) in mm: L3980xW1830 Additional information: equipped with spare wheel Trailer registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate</p>	100€





		<p>Trailer conformity certificate: Not present: the buyer will receive a certificate of loss of conformity certificate Inspection certificate: Not present Number of axles: 2 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	11	<p>Brand: BW Model: 02T First registration (dd/mm/yyyy): 09/07/2014 Trailer category: O2: max. mass >750kg - <3500kg Trailer type: Tipper Chassis number: YB83000KBT1421825 Maximum Allowable Mass (kg): 3000 Inner dimensions (L x W x H) in mm: L3000xW1830 Additional information: equipped with spare wheel Trailer registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Trailer conformity certificate: Not present: the buyer will receive a certificate of loss of conformity certificate Inspection certificate: Not present Number of axles: 2 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: handbrake defective various damages including residual waste condition: Used Quantity: 1</p>	100€




	11	<p>Brand: Mercedes-Benz Model: Sprinter Version: 314 CDI Fourgon L2RWD Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 30/07/2020 Fuel: Diesel Read odometer reading (km): 96871 Chassis number: W1V9076331P253531 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2143 Engine power kW: 105 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Other options: DAB tuner Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 29/03/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	100€
---	----	--	------




	12	<p>Brand: BW Model: R/00433 First registration (dd/mm/yyyy): 30/11/2010 Trailer category: O2: max. mass >750kg - <3500kg Trailer type: Tipper Chassis number: YB8BW350020109566 Maximum Allowable Mass (kg): 3500 Inner dimensions (L x W x H) in mm: L4050xW1820 Additional information: equipped with spare wheel Trailer registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Trailer conformity certificate: Not present: the buyer will receive a certificate of loss of conformity certificate Inspection certificate: Not present Number of axles: 2 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: including waste condition: Used Quantity: 1</p>	100€
	13	<p>Brand: Marco Model: AV20TA Year of construction (yyyy): 2008 Trailer category: O2: max. mass >750kg - <3500kg Trailer type: Tipper Chassis number: MAR2769 Inner dimensions (L x W x H) in mm: L2940xW1700 Additional information: equipped with spare wheel Trailer registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Trailer conformity certificate: Not present: the</p>	100€




		<p>buyer will receive a certificate of loss of conformity certificate Inspection certificate: Not present Number of axles: 2 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	13	<p>Brand: Mercedes-Benz Model: Sprinter Version: 516 CDI L3 RWD 3.5T Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 16/09/2021 Fuel: Diesel Read odometer reading (km): 103255 Chassis number: W1V9071551N153089 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Truck Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2443 Engine power kW: 120 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Artificial leather Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Other options: Equipped with D'Hollandia tailgate without key DAB tuner</p>	100€




		<p>spare wheel Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 27/03/2023 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: cracked windshield condition: Used Quantity: 1</p>	
	14	<p>Brand: Peugeot Model: Boxer Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 01/03/2013 Fuel: Diesel Read odometer reading (km): 126648 Chassis number: VF3YBUMFB12356670 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 110 Emission class: Euro 5 Co2 emissions g/km: 199 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes</p>	100€




		<p>Rear parking sensors: Yes Radio: Yes Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 27/11/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	
	15	<p>Brand: Peugeot Model: Boxer Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 12/11/2013 Fuel: Diesel Read odometer reading (km): 183896 Chassis number: VF3YCTMFB12490272 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 96 Emission class: Euro 5 Co2 emissions g/km: 199 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes</p>	100€




		<p>Electrically folding mirrors: Yes Electric windows: Yes Radio: Yes Other options: equipped loading area Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages including gear lever etc. condition: Used Quantity: 1</p>	
	16	<p>Brand: Ford Model: Transit Version: 125 T350 Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 07/09/2012 Fuel: Diesel Read odometer reading (km): 191269 Chassis number: WF0XXXTTFXCD09299 Number of keys: 3 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 92 Emission class: Euro 5 Co2 emissions g/km: 209 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes</p>	100€




		<p>Electric windows: Yes Multifunctional steering wheel: Yes Radio: Yes Towbar: Yes Other options: equipped loading area Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 18/09/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	
	18	<p>Brand: Peugeot Model: Boxer Year of construction (yyyy): 2009 First registration (dd/mm/yyyy): 14/01/2009 Fuel: Diesel Read odometer reading (km): 115162 Chassis number: VF3YBBMFB11542557 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3300 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 88 Emission class: Euro 4 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes</p>	100€





		<p>Radio: Yes Additional information: Vehicle will not start, engine and transmission problems! Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 21/01/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Vehicle won't start, engine and transmission problems! various damages condition: Used Quantity: 1</p>	
	19	<p>Brand: Anssems Model: PLTT0 Year of construction (yyyy): 2021 Trailer category: O1: max. mass <750kg Trailer type: Open trailer Chassis number: XLJLT030400271199 Maximum Allowable Mass (kg): 740 Inner dimensions (L x W x H) in mm: 3000x1500 Additional information: Uninhibited Equipped with cage Trailer conformity certificate: Yes, available Inspection certificate: Not applicable Number of axles: 2 Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview. condition: Used Quantity: 1</p>	100€




	21	<p>Brand: Renault Model: Kangoo Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 11/04/2013 Fuel: Diesel Read odometer reading (km): 242362 Chassis number: VF1FW14BD48889850 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 1884 Transmission: Manual transmission Cylinder capacity cc: 1461 Engine power kW: 55 Emission class: Euro 5 Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Radio: Yes Other options: Roof rack Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 22/03/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: dashboard reports hole in passenger seat door handle condition: Used Quantity: 1</p>	100€
---	----	--	------




	23	<p>Brand: BW Model: 3500T First registration (dd/mm/yyyy): 27/06/2012 Trailer category: O2: max. mass >750kg - <3500kg Trailer type: Tipper Chassis number: YB8BWT35020125012 Maximum Allowable Mass (kg): 3500 Inner dimensions (L x W x H) in mm: L3980xW1870 Additional information: equipped with spare wheel Trailer registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Trailer conformity certificate: Not present: the buyer will receive a certificate of loss of conformity certificate Inspection certificate: Not present Number of axles: 2 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: including remaining contents (waste) condition: Used Quantity: 1</p>	100€
	24	<p>Brand: Mercedes-Benz Model: Sprinter Version: 314 CDI Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 07/09/2016 Fuel: Diesel Read odometer reading (km): 251796 Chassis number: WDB9062331N687810 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: van with open loading platform Number of axles: 2 Maximum Allowable Mass (kg): 3200 Transmission: Manual transmission Cylinder capacity cc: 2143</p>	100€



		<p>Engine power kW: 105 Emission class: Euro 6 Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Radio: Yes Other options: double cabin provided with net Registration certificate: Yes, available Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 18/03/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: star windshield Brake pad wear notification condition: Used Quantity: 1</p>	
	115	<p>Brand: Renault Model: Kangoo Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 10/12/2013 Fuel: Diesel Read odometer reading (km): 319152 Chassis number: VF1FW18H549974114 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 2200 Transmission: Manual transmission Cylinder capacity cc: 1461 Exterior color: White</p>	100€



		<p>Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Radio: Yes Towbar: Yes Other options: roof rack Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: dashboard report various damages condition: Used Quantity: 1</p>	
	116	<p>Brand: Volkswagen Model: Caddy Year of construction (yyyy): 2007 First registration (dd/mm/yyyy): 12/12/2007 Fuel: Diesel Read odometer reading (km): 167151 Chassis number: WV1ZZZ2KZ8X049337 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 2205 Transmission: Manual transmission Engine capacity cc: 1968 Engine power kW: 51 Emission class: Euro 4 Exterior color: Gray Metallic colour: No Interior color: Gray</p>	100€



		<p>Upholstery: Fabric Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Electrically folding mirrors: Yes Electric windows: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 04/08/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	117	<p>Brand: Renault Model: Master Version: DCI 150 F3500 Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 27/10/2011 Fuel: Diesel Read odometer reading (km): 228197 Chassis number: VF1MB14F245883104 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Truck Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 107 Emission class: Euro 5 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning</p>	100€



		<p>On-board computer: Yes Central locking: Yes Electric windows: Yes Radio: Yes Towbar: Yes Additional information: Vehicle does not start and drive!</p> <p>Includes remaining contents including dismantled bed and waste. Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 13/10/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Vehicle does not start and does not drive! Various damages Various notifications dashboard condition: Used Quantity: 1</p>	
--	--	---	--