



**CATALOG**  
Transport & Internal Logistics



**DESCRIPTION**

Auction of transport, logistics, forklifts and internal

**START**

22 june 2024 to 08:00 [UTC]

**END DATE**

2 july 2024 from 09:00 [UTC]

**VIEWING**

- ---  
Wednesday June 26 2024 from 15:00 until 17:00  
BE-2630 Aartselaar, Helststraat 47

**AUCTIM PARTNER**

**MOYERSOEN NV**

Helststraat 47, 2630 Aartselaar, Belgium  
+32 3 827 21 31 - info.moyersoen@auctim.be  
BTW BE 0452 153 622


**ISSUE - COLLECTION**

- ---  
Wednesday July 10 2024 from 10:00 until 12:00  
BE-2630 Aartselaar, Helststraat 47


**Online bidding only!**

Catalog created on 2 july 2024 to 04:00




	Item	Description	Start price
	5	<p>Brand: MAN Model: TGS Version: 18,360 Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 27/04/2012 Fuel: Diesel Read odometer reading (km): 597331 Chassis number: WMA10SZZ9CP034180 Number of keys: 1 Category: N3: max. mass &gt;12t. Truck type: Platform truck Number of axles: 2 Length (meters): 9.8 Maximum Allowable Mass (kg): 19000 Transmission: Automatic transmission Cylinder capacity cc: 10518 Engine power kW: 265 Exterior color: Red Interior color: Black Upholstery: Fabric Air conditioning: Semi-automatic air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Radio: Yes Tachograph: Yes Other options: Equipped with a working D'Hollandia sliding tailgate with key Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 07/11/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: star windshield loading floor</p>	100€




		condition: Used Quantity: 1	
	6	Brand: DAF Model: CF 85 FAN Version: 85.360 Year of construction (yyyy): 2008 First registration (dd/mm/yyyy): 22/09/2008 Fuel: Diesel Read odometer reading (km): 606170 Chassis number: XLRAS85MC0E832956 Number of keys: 2 Category: N3: max. mass >12t. Truck type: Crane truck Number of axles: 3 Length (meter): 10 Maximum Allowable Mass (kg): 26000 Transmission: Automatic transmission Cylinder capacity cc: 12902 Engine power kW: 265 Emission class: Euro 4 Exterior color: Gray Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Radio: Yes Sleeping place: Yes Tachograph: Yes Other options: Equipped with HIAB crane, type 288E6 HIPRO, series no. BL288HP00176, built in 2015 with wireless remote control (Olsbergs). Equipped with MAXISTAB stabilizers. Equipped with an open loading platform. Spare wheel. Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available	100€




		<p>Inspection certificate valid until (dd/mm/yyyy):: 15/03/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	7	<p>Brand: MAN Model: TGS Version: 35,400 Year of construction (yyyy): 2008 First registration (dd/mm/yyyy): 30/06/2008 Fuel: Diesel Read odometer reading (km): 219731 Chassis number: WMA37SZZ48M524572 Number of keys: 3 Category: N3: max. mass &gt;12t. Truck type: Crane truck Number of axles: 4 Length (meter): 9 Maximum Allowable Mass (kg): 32000 Transmission: Manual transmission Cylinder capacity cc: 10518 Exterior color: White Interior color: Gray Upholstery: Fabric Air conditioning: Fully automatic air conditioning Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Radio: Yes Tachograph: Yes Other options: Equipped with radio-controlled crane Palfinger PK 33000C, year built 1995, serial no. H 9461618 with wireless remote control. Equipped with open container system/loading body (10m<sup>3</sup>) with hook arm Leebur, capacity 26 tons.  Refrigerator compartment.</p>	100€




		<p>Support legs. Leaf-pinnate. Additional information: Equipped with new hydraulic line coupling. Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 20/10/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	10	<p>Brand: Mitsubishi Model: SBP12N2 Product category: Stacker Year of construction (yyyy): 2020 Odometer reading (hours): N/A Serial number: RFB11A 51935 Fuel: Electric Number of keys: 1 Exterior color: Green Maximum lifting capacity (kg): 1200 Clearance height (mm): 215 Lift mast: Plywood Max. Lifting height (mm): 4700 Free lift (mm): None Fork length (mm): 1150 Own weight (kg): 1100 Battery (voltage): 24 Battery charger: Yes Cabin: Open cabin Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	10€



	14	<p>Brand: Scania Model: PRT Version: R440 Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 07/03/2011 Fuel: Diesel Read odometer reading (km): 1113651 Chassis number: XLER4X20005258723 Number of keys: 1 Category: N3: max. mass &gt;12t. Tractor type: Standard tractor Number of axles: 2 Maximum Allowable Mass (kg): 20500 Transmission: Automatic transmission Cylinder capacity cc: 12740 Engine power kW: 324 Emission class: Euro 5 Exterior color: Green Interior color: Gray Upholstery: Fabric Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Other options: 2 sleeping places tachograph Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 04/10/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: star windshield lock broken condition: Used Quantity: 1</p>	100€
---	----	--	------



	16	<p>Brand: Renault Model: Midlum Version: 180 DCI Year of construction (yyyy): 2006 First registration (dd/mm/yyyy): 20/02/2006 Fuel: Diesel Read odometer reading (km): 618745 Chassis number: VF642AEA000004572 Number of keys: 1 Category: N3: max. mass &gt;12t. Truck type: Truck Number of axles: 2 Transmission: Manual transmission Exterior color: Red Interior color: Gray Upholstery: Fabric Electric windows: Yes Radio: Yes Tachograph: Yes Other options: Equipped with D'Hollandia tailgate without key. Additional information: Vehicle does not start! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Vehicle does not start! condition: Used Quantity: 1</p>	100€
---	----	--	------







	17	<p>Brand: Renault Model: Premium Version: 380 EEV Year of construction (yyyy): 2010 First registration (dd/mm/yyyy): 04/10/2010 Fuel: Diesel Read odometer reading (km): 1012316 Chassis number: VF624GPD000002237 Number of keys: 1 Category: N3: max. mass &gt;12t. Tractor type: Standard tractor Number of axles: 2 Maximum Allowable Mass (kg): 19000 Transmission: Automatic transmission Cylinder capacity cc: 10837 Engine power kW: 286 Emission class: Euro 5 Exterior color: White Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Cruise control: Yes Electric windows: Yes Radio: Yes Other options: Tachograph Spare wheel Additional information: Power steering problem: vehicle starts and drives but steering wheel does not turn.</p> <p>Start with booster! Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 12/10/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Power steering problem: vehicle starts and drives but steering wheel does not turn. Wheel covers broken.</p>	100€
--	----	--	------






		condition: Used Quantity: 1	
	30	Brand: Iveco Model: Stralis Version: 420 Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 16/07/2019 Fuel: Diesel Read odometer reading (km): 356467 Chassis number: WJMM62AS60C416299 Number of keys: 3 Category: N3: max. mass >12t. Tractor type: Standard tractor Number of axles: 2 Maximum Allowable Mass (kg): 19000 Transmission: Automatic transmission Cylinder capacity cc: 11120 Engine power kW: 309 Emission class: Euro 6 Exterior color: White Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning On-board computer: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Seat heating: Yes Other options: Tachograph spare wheel Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 26/07/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.	100€




		Vehicle damage description: driver's step various damages condition: Used Quantity: 1	
	31	Brand: Renault Model: Premium Version: 380 DXI EEV Year of construction (yyyy): 2010 First registration (dd/mm/yyyy): 04/10/2010 Fuel: Diesel Read odometer reading (km): 1199426 Chassis number: VF624GPD000002232 Number of keys: 1 Category: N3: max. mass >12t. Tractor type: Standard tractor Number of axles: 2 Maximum Allowable Mass (kg): 19000 Transmission: Automatic transmission Cylinder capacity cc: 10837 Engine power kW: 286 Emission class: Euro 5 Exterior color: White Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Radio: Yes Other options: Tachograph Spare wheel Additional information: start with booster! Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 08/10/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always	100€



		consult the photo report. Vehicle damage description: start with booster! condition: Used Quantity: 1	
	118	<p>Brand: Renault Model: Premium Version: 370 DCI Year of construction (yyyy): 2004 First registration (dd/mm/yyyy): 07/06/2004 Fuel: Diesel Read odometer reading (km): 613492 Chassis number: VF622GVA000139439 Number of keys: 3 Category: N3: max. mass &gt;12t. Tractor type: Standard tractor Number of axles: 2 Maximum Allowable Mass (kg): 19000 Transmission: Automatic transmission Cylinder capacity cc: 11116 Engine power kW: 266 Emission class: Euro 3 Exterior color: Red Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Radio: Yes Other options: Tachograph</p> <p>Additional information: Start with booster! Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 30/04/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Wheel covers broken</p>	100€



		Various damages Start with booster! condition: Used Quantity: 1	
	119	Brand: Iveco Model: Stralis Version: 420 Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 24/06/2019 Fuel: Diesel Read odometer reading (km): unknown Chassis number: WJMM62AS00C415309 Number of keys: 0 Category: N3: max. mass >12t. Tractor type: Standard tractor Number of axles: 2 Exterior color: White Interior color: Black Upholstery: Fabric Additional information: Vehicle is sold as a wreck without on-board documents, various damages!  Registration certificate: Not available, see additional information Certificate of conformity: Not present, see additional information Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Vehicle is sold as a wreck without on-board documents, various damages!  condition: Used Quantity: 1	10€



**AUCTIM**  
ONLINE AUCTIONS

**AUCTIM - MOYERSON NV**  
Helststraat 47  
2630 Aartselaar, Belgium  
VAT BE 0452 153 622

**[www.auctim.com](http://www.auctim.com)**  
[info.moyersoem@auctim.be](mailto:info.moyersoem@auctim.be)