




CATALOG

Commercial vehicles



DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

6 july 2024 to 08:00 [UTC]

END DATE

16 july 2024 from 09:00 [UTC]

VIEWING

- Lots: 20
Only by appointment through the organizer.
Thursday July 11 2024 from 09:30 until 10:30
Centrum-Zuid 3404, 3530 Houthalen-Helchteren
- ---
Wednesday July 10 2024 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSON NV

Helststraat 47, 2630 Aartselaar, Belgium
 +32 3 827 21 31 - info.moyersoenv@auctim.be
 BTW BE 0452 153 622

ISSUE - COLLECTION

- Lots: 20
Aanmelden tussen
Tuesday July 23 2024 from 10:00 until 10:30
Centrum-Zuid 3404, 3530 Houthalen-Helchteren
- ---
Wednesday July 24 2024 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47

Online bidding only!


AUCTIM - MOYERSON NV

Helststraat 47
 2630 Aartselaar, Belgium
 VAT BE 0452 153 622

www.auctim.com
 info.moyersoenv@auctim.be

Catalog created on 16 july 2024 to 04:00



	Item	Description	Start price
	2	<p>Brand: Opel Model: Movano Version: F 3500 Year of construction (yyyy): Unknown First registration (dd/mm/yyyy): 12/02/2014 Fuel: Diesel Read odometer reading (km): Unknown Chassis number: W0LMRFEDCCB034868 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 92 Emission class: Euro 5 Co2 emissions g/km: 205 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Central locking: Yes Electric windows: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 11/03/2024 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Vehicle does not start condition: Used Quantity: 1</p>	100€




4


Brand: Fiat
 Model: Ducato
 Version: 3.5T L2H2 2.3 MJET
 Year of construction (yyyy): 2022
 First registration (dd/mm/yyyy): 20/12/2022
 Fuel: Diesel
 Read odometer reading (km): 30072
 Chassis number: ZFA25000002V96454
 Number of keys: 1
 Vehicle category: N1: max. mass <3.5t.
 Construction: Closed van
 Number of axles: 2
 Maximum Allowable Mass (kg): 3500
 Transmission: Manual transmission
 Cylinder capacity cc: 2184
 Engine power kW: 103
 Emission class: Euro 6
 Exterior color: White
 Metallic colour: No
 Interior color: Black
 Upholstery: Fabric
 Air conditioning: Manual air conditioning
 On-board computer: Yes
 Central locking: Yes
 Electrically folding mirrors: Yes
 Electric windows: Yes
 Fog lights: Yes
 Multifunctional steering wheel: Yes
 Radio: Yes
 Additional information: start with booster!
 Registration certificate: Yes, available
 Certificate of conformity: Yes, available
 Identification report: Yes, present
 Inspection certificate: Yes, available
 Inspection certificate valid until (dd/mm/yyyy)::
 05/01/2024
 Maintenance booklet: Not present
 Visible vehicle damage: No, with the exception of
 general usage damage. (General usage damage
 includes all damage that may be expected given
 the age and mileage or hours.) You can always
 consult the photo report for a detailed overview.
 Vehicle damage description: start with booster!
 condition: Used
 Quantity: 1

100€




	5	<p>Brand: Mercedes-Benz Model: Sprinter Version: 314 CDI Fourgon L2 RWD Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 11/01/2021 Fuel: Diesel Read odometer reading (km): 138741 Chassis number: W1V9076351P304774 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2143 Engine power kW: 105 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Other options: DAB tuner Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 01/02/2024 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always</p>	100€




		consult the photo report. Vehicle damage description: Various heavy damage! condition: Used Quantity: 1	
	8	Brand: Iveco Model: Daily Version: 35-180 HIMATIC Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 26/10/2021 Fuel: Diesel Read odometer reading (km): 126679 Chassis number: ZCFC635D505427372 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Automatic transmission Cylinder capacity cc: 2998 Engine power kW: 132 Emission class: Euro 6 Exterior color: Gray Metallic colour: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Semi-automatic air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Radio: Yes Towbar: Yes Other options: DAB tuner Roof rack Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available	100€




		<p>Inspection certificate valid until (dd/mm/yyyy):: 27/10/2024</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p> <p>condition: Used</p> <p>Quantity: 1</p>	
	12	<p>Brand: Mercedes-Benz</p> <p>Model: Vito</p> <p>Version: 114 CDI</p> <p>Year of construction (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 29/08/2018</p> <p>Fuel: Diesel</p> <p>Read odometer reading (km): 240825</p> <p>Chassis number: WDF44760313506582</p> <p>Number of keys: 2</p> <p>Vehicle category: N1: max. mass <3.5t.</p> <p>Construction: Closed van</p> <p>Number of axles: 2</p> <p>Maximum Allowable Mass (kg): 2800</p> <p>Transmission: Automatic transmission</p> <p>Cylinder capacity cc: 2143</p> <p>Engine power kW: 100</p> <p>Emission class: Euro 6b</p> <p>Exterior color: Black</p> <p>Metallic colour: No</p> <p>Interior color: Black</p> <p>Upholstery: Artificial leather</p> <p>Air conditioning: Manual air conditioning</p> <p>Central locking: Yes</p> <p>Cruise control: Yes</p> <p>Electric windows: Yes</p> <p>Multifunctional steering wheel: Yes</p> <p>Navigation: Yes</p> <p>Radio: Yes</p> <p>Towbar: Yes</p> <p>Registration certificate: Yes, available</p> <p>Certificate of conformity: Yes, available</p> <p>CARPASS: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy)::</p>	100€




		15/02/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages including driver's seat condition: Used Quantity: 1	
	14	Brand: Opel Model: Vivaro Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 14/03/2022 Fuel: Diesel Read odometer reading (km): 81460 Chassis number: VXEVBYHVMM7866812 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 2695 Transmission: Manual transmission Cylinder capacity cc: 1499 Engine power kW: 88 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Partial leather Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available	100€




		<p>Inspection certificate valid until (dd/mm/yyyy):: 21/03/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	
	15	<p>Brand: NISSAN Model: NV400 Version: L3H1 3T5 145HP Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 18/02/2021 Fuel: Diesel Read odometer reading (km): 107485 Chassis number: VNVV2000465441264 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: box truck Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 106 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Electric windows: Yes Radio: Yes Additional information: Start with booster! without key tailgate D'HOLLANDIA Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate</p>	100€



		<p>Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Start with booster! without key tailgate D'HOLLANDIA! various damages error messages dashboard vehicle smokes condition: Used Quantity: 1</p>	
	17	<p>Brand: Citroen Model: Jumper Version: L3H2 2.0 BlueHDI Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 04/04/2017 Fuel: Diesel Read odometer reading (km): 84731 Chassis number: VF7YC3MFC12D64751 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Transmission: Manual transmission Cylinder capacity cc: 1997 Engine power kW: 120 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Central locking: Yes Electrically folding mirrors: Yes Electric windows: Yes Fog lights: Yes Navigation: Yes Radio: Yes Additional information: start with booster! Registration certificate: Not present: the buyer</p>	100€



		<p>will receive a certificate of loss of registration certificate</p> <p>Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity</p> <p>Inspection certificate: Not present</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p> <p>Vehicle damage description: start with booster!</p> <p>Various damages</p> <p>condition: Used</p> <p>Quantity: 1</p>	
	20	<p>Brand: Stevens</p> <p>Model: T 744-01</p> <p>Year of construction (yyyy): 1996</p> <p>First registration (dd/mm/yyyy): Not known</p> <p>Category semi-trailer: O3: max. mass >3500kg - <10000kg</p> <p>Semi-trailer type: Market wagon</p> <p>Chassis number: 7360</p> <p>Number of axles: 2 (separate)</p> <p>Maximum Allowable Mass (kg): 10000</p> <p>Exterior color: Brown</p> <p>Additional information: LxWxH folded: 11.25m x 2.7m x 3.05m</p> <p>LxWxH open: 16m x 6m x 3.05m</p> <p>Height adjustable when unfolded, hydraulic system legs allow adjustment. No leaks on the legs.</p> <p>All 4 pistons (hydraulic) can be operated separately and are functional.</p> <p>Even lowering is possible.</p> <p>Awning is equipped with a hydraulic pump system and functional</p> <p>Trailer is equipped with a standard Kingpin.</p> <p>Please note that the fifth wheel of the tractor must be placed as far back as possible to enable coupling and maneuvers.</p>	100€



Equipped with various counters, cupboards and shelves.

No keys available.

24V inside

Delivered to Houthalen - Helchteren

Trailer registration certificate: Yes, available

Trailer conformity certificate: Yes, available

Identification report: Yes, present

Inspection certificate: Yes, available

Inspection certificate valid until (dd/mm/yyyy)::
07/02/2024

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.

Vehicle damage description: Exterior damage is limited to scratches, dents and corrosion associated with the age and intensive use of the trailer.

The furniture inside including the floor, cupboards, drawers and shutters all have visible damage.

The damage inside includes: drawers that are difficult to open and/or do not close completely, cupboard doors that are missing and/or difficult to close, partitions that are missing or broken, broken mirrors inside, loose hanging clothes rails and others.

The electricity inside consists of 2 circuits, each supplied externally. Each of these circuits has a number of lamps and switches that are defective.

The car is equipped with a heating unit, its operation is unknown.

The accompanying rain screens all have visible signs of wear and the available number is no longer sufficient to shield the entire vehicle.

Logo must be removed by the buyer: Yes


condition: Used

Quantity: 1




	27	<p>Brand: BMW Model: X5 Version: xDrive 30D Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 23/06/2016 Fuel: Diesel Read odometer reading (km): 228376 Chassis number: WBAKS410X00H78010 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Automatic transmission Cylinder capacity cc: 2993 Engine power kW: 190 Emission class: Euro 6b Co2 emissions g/km: 156 Exterior color: Gray Metallic colour: Yes Interior color: Beige Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat heating: Yes Additional information: Vehicle registered under category N1G - Light freight (rear seat converted). Registration certificate: Yes, available Certificate of conformity: Yes, available</p>	100€




		<p>CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 14/01/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Deep scratch on hood, scratch on side condition: Used Quantity: 1</p>	
	30	<p>Brand: Ford Model: Transit Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 16/10/2013 Fuel: Diesel Read odometer reading (km): 76923 Chassis number: WF0XXXTTFXDC51139 Number of keys: 3 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3325 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 114 Emission class: Euro 5 Exterior color: White Metallic colour: No Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Rear parking sensors: Yes Radio: Yes Other options: Equipped with sockets/electricity supply in the loading area.</p>	4.000€



		<p>Light bar at the back.</p> <p>Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 27/11/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: damage left flank, star windshield condition: Used Quantity: 1</p>	
	36	<p>Brand: Nissan Model: Townstar Version: L1H1 Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 21/09/2022 Fuel gasoline Read odometer reading (km): 47726 Chassis number: VNVNFK00369610392 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Authorized Mass (kg): 1970 Transmission: Manual transmission Cylinder capacity cc: 1332 Engine power kW: 96 Emission class: Euro 6 Exterior color: Gray Metallic colour: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes</p>	100€




		<p>Electrically folding mirrors: Yes Electric windows: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: roof rack DAB tuner Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 27/01/2024 Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview. condition: Used Quantity: 1</p>	
	37	<p>Brand: Ford Model: Transit Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 04/04/2018 Fuel: Diesel Read odometer reading (km): 108867 Chassis number: WF0XXXTTGXHD58736 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 2800 Transmission: Manual transmission Engine capacity cc: 1995 Engine power kW: 96 Emission class: Euro 6b Exterior color: White Metallic colour: No</p>	100€




		<p>Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 05/01/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	38	<p>Brand: Volkswagen Model: Crafter Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 02/11/2022 Fuel: Diesel Read odometer reading (km): 104841 Chassis number: WV1ZZZSYZN9012022 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Engine capacity cc: 1968 Engine power kW: 103 Emission class: Euro 6 Exterior color: White Metallic colour: No</p>	100€



		<p>Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Navigation: Yes Radio: Yes Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 22/02/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Various damages condition: Used Quantity: 1</p>	
	39	<p>Brand: Fiat Model: Ducato Version: 120 Multijet Year of construction (yyyy): 2008 First registration (dd/mm/yyyy): 16/09/2008 Fuel: Diesel Read odometer reading (km): 163235 Chassis number: ZFA25000001512501 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 88 Emission class: Euro 4 Exterior color: Gray</p>	100€




		<p>Metallic colour: No Interior color: Gray Upholstery: Fabric Central locking: Yes Electric windows: Yes Additional information: Various damages.</p> <p>Registration certificate: Yes, available Certificate of conformity: Not present, see additional information CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 25/05/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Various damages. condition: Used Quantity: 1</p>	
	55	<p>Brand: Peugeot Model: Boxer Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 06/02/2019 Fuel: Diesel Read odometer reading (km): 177833 Chassis number: VF3YC2MFC12K29530 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 1997 Engine power kW: 96 Emission class: Euro 6b Exterior color: White Metallic colour: No Interior color: Black</p>	100€




		<p>Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 29/03/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: stone chip windshield</p> <p>various damages condition: Used Quantity: 1</p>	
	60	<p>Brand: Fiat Model: Doblo Version: Series 2 1.6 MJET Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 27/02/2023 Fuel: Diesel Read odometer reading (km): 89929 Chassis number: ZFA26300006Y36630 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 2100 Transmission: Manual transmission Cylinder capacity cc: 1598 Engine power kW: 77 Emission class: Euro 6 Exterior color: White Metallic colour: No</p>	100€




		<p>Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Radio: Yes Other options: DAB tuner Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 13/03/2024 Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview. condition: Used Quantity: 1</p>	
	61	<p>Brand: Renault Model: Traffic Version: Confort L2H1 Energy Blue Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 27/12/2023 Fuel: Diesel Read odometer reading (km): 13617 Chassis number: VF1FL000971864680 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3070 Transmission: Automatic transmission Engine capacity cc: 1997</p>	100€





		<p>Engine power kW: 110 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: DAB tuner Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 10/01/2025 Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview. condition: Used Quantity: 1</p>	
	85	<p>Quantity: 1 Product category: Trailer Brand: Eduard Model: 5 Year of construction (yyyy): 2022 Serial number: YC3EDUARD22004992 Dimensions mm (LxWxH): Loading box: 6000x2200 Weight category: more than 1,000 kg condition: Used</p>	10€




		Location: Aartselaar	
	86	<p>Brand: Citroen Model: Jumper Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 20/10/2016 Fuel: Diesel Read odometer reading (km): 173919 Chassis number: VF7YCTMFC12A69346 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 96 Emission class: Euro 5b Co2 emissions g/km: 195 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Rear parking sensors: Yes Radio: Yes Towbar: Yes Other options: equipped with a fitted loading space including remaining contents</p> <p>roof rack ladder Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available</p>	100€




		<p>Inspection certificate valid until (dd/mm/yyyy):: 01/08/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	87	<p>Brand: Citroen Model: Jumper Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 20/10/2016 Fuel: Diesel Read odometer reading (km): 168793 Chassis number: VF7YCTMFC12A73235 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 96 Emission class: Euro 5b Co2 emissions g/km: 195 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Radio: Yes Towbar: Yes Other options: Equipped loading space Roof rack</p>	10€

		<p>Additional information: Includes remaining contents and waste</p> <p>Start with booster!</p> <p>Registration certificate: Yes, available</p> <p>Certificate of conformity: Yes, available</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy):: 01/08/2024</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p> <p>Vehicle damage description: various damages</p> <p>Start with booster!</p> <p>condition: Used</p> <p>Quantity: 1</p>	
	88	<p>Brand: Citroen</p> <p>Model: Jumpy</p> <p>Year of construction (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 19/09/2018</p> <p>Fuel: Diesel</p> <p>Read odometer reading (km): 97896</p> <p>Chassis number: VF7VBBHXHRJZ054194</p> <p>Number of keys: 1</p> <p>Vehicle category: N1: max. mass <3.5t.</p> <p>Construction: Closed van</p> <p>Number of axles: 2</p> <p>Maximum Allowable Mass (kg): 2660</p> <p>Transmission: Manual transmission</p> <p>Cylinder capacity cc: 1560</p> <p>Engine power kW: 85</p> <p>Emission class: Euro 6b</p> <p>Exterior color: White</p> <p>Metallic colour: No</p> <p>Interior color: Black</p> <p>Upholstery: Fabric</p> <p>Air conditioning: Manual air conditioning</p>	10€

		<p>On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Towbar: Yes Other options: equipped loading area</p> <p>Additional information: Includes remaining contents.</p> <p>Start with booster! Registration certificate: Yes, available Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Driver's seat</p> <p>Start with booster! condition: Used Quantity: 1</p>	
	90	<p>Brand: Ford Model: Transit Version: Custom Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 15/11/2021 Fuel: Diesel Read odometer reading (km): 77901 Chassis number: WF0YXXTTGYMG60968 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2</p>	100€



		<p>Maximum Allowable Mass (kg): 3000 Transmission: Manual transmission Engine capacity cc: 1995 Engine power kW: 95 Emission class: Euro 6 Exterior color: Gray Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Semi-automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Towbar: Yes Other options: DAB tuner equipped with furnished loading space Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 17/11/2024 Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview. condition: Used Quantity: 1</p>	
	96	<p>Brand: Fiat Model: Fiorino Year of construction (yyyy): 2015 First registration (dd/mm/yyyy): 31/03/2015 Fuel gasoline</p>	100€



		<p>Read odometer reading (km): 115417 Chassis number: ZFA22500006A12549 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Construction: Closed van Number of axles: 2 Maximum Allowable Mass (kg): 1680 Transmission: Manual transmission Cylinder capacity cc: 1368 Engine power kW: 57 Emission class: Euro 6b Exterior color: Gray Metallic colour: No Interior color: Gray Upholstery: Fabric Central locking: Yes Electric windows: Yes Radio: Yes Towbar: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 20/04/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
--	--	---	--