



CATALOG

Transport - logistics - forklift - internal



DESCRIPTION

Auction of transport, logistics, forklifts and internal

START

3 august 2024 to 08:00 [UTC]

END DATE

13 august 2024 from 09:00 [UTC]

VIEWING

- ---
Wednesday August 07 2024 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV
Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622


ISSUE - COLLECTION

- ---
Wednesday August 21 2024 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47


Online bidding only!

Catalog created on 13 august 2024 to 04:00




	Item	Description	Start price
	4	<p>Brand: DAF Model: XF Version: 480 FT Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 21/02/2023 Fuel: Diesel Read odometer reading (km): 127909 Chassis number: XLRTEF5300G442183 Number of keys: 3 Category: N1: max. mass <3.5t. Tractor type: Standard tractor Number of axles: 2 Maximum Allowable Mass (kg): 19500 Transmission: Automatic transmission Cylinder capacity cc: 12902 Engine power kW: 355 Emission class: Euro 6 Exterior color: White Interior color: Black Upholstery: Fabric Air conditioning: Semi-automatic air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Radio: Yes Seat heating: Yes Other options: sleeping place DAB tuner tachograph refrigerator compartment Certificate of registration: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always</p>	100€




		consult the photo report. Vehicle damage description: Wheel covers condition: Used Quantity: 1	
	5	Brand: MAN Model: TGM Version: 15,250 Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 06/04/2020 Fuel: Diesel Read odometer reading (km): 191755 Chassis number: WMAN18ZZ6LY408658 Number of keys: 2 Category: N3: max. mass >12t. Truck type: Sliding curtain truck Number of axles: 2 Length (meters): 11.9 Maximum Allowable Mass (kg): 16000 Transmission: Automatic transmission Cylinder capacity cc: 6871 Engine power kW: 184 Emission class: Euro 6 Exterior color: White Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Cruise control: Yes Electric windows: Yes Radio: Yes Tachograph: Yes Additional information: Tire size: 295/80 R 22.5 Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 14/04/2025 Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage	100€



		<p>includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview. condition: Used Quantity: 1</p>	
	15	<p>Brand: DAF Model: CF Version: 75,250 Year of construction (yyyy): 2008 First registration (dd/mm/yyyy): 03/12/2008 Fuel: Diesel Read odometer reading (km): 583667 Chassis number: XLRAE75PC0E838073 Number of keys: 2 Category: N3: max. mass >12t. Truck type: Complete combination Number of axles: 2 Transmission: Manual transmission Emission class: Euro 5 Exterior color: Gray Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Tachograph: Yes Other options: equipped with D'Hollandia tailgate without key Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Various damages condition: Used</p>	100€



		Quantity: 1	
	16	<p>Brand: Renault Model: Midlum Version: 180 DCI Year of construction (yyyy): 2006 First registration (dd/mm/yyyy): 20/02/2006 Fuel: Diesel Read odometer reading (km): 618745 Chassis number: VF642AEA000004572 Number of keys: 1 Category: N3: max. mass >12t. Truck type: Truck Number of axles: 2 Transmission: Manual transmission Exterior color: Red Interior color: Gray Upholstery: Fabric Electric windows: Yes Radio: Yes Tachograph: Yes Other options: Equipped with D'Hollandia tailgate without key. Additional information: Vehicle does not start! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Vehicle does not start! condition: Used Quantity: 1</p>	100€



	93	<p>Brand: Renault Model: Midlum Version: 180 dci Year of construction (yyyy): 2004 First registration (dd/mm/yyyy): 27/09/2004 Fuel: Diesel Read odometer reading (km): unknown (last known 11/2022: 528810 km Chassis number: VF644AEA000003121 Number of keys: 3 Category: N3: max. mass >12t. Truck type: Truck Number of axles: 2 Length (meter): 8565 Maximum Allowable Mass (kg): 16000 Transmission: Manual transmission Cylinder capacity cc: 4116 Engine power kW: 128 Emission class: Euro 3 Exterior color: Red Interior color: Black Upholstery: Fabric Electric windows: Yes Radio: Yes Tachograph: Yes Other options: equipped with D'Hollandia tailgate without key spare wheel Additional information: Vehicle does not start, no battery present! Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 16/11/2022 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Vehicle does not start, no battery present! Various damages! condition: Used Quantity: 1</p>	100€
---	----	--	------



AUCTIM
ONLINE AUCTIONS

--	--	--	--