



CATALOG

Passenger cars



DESCRIPTION

Auction of passenger cars from various bankruptcies, seizures, breaches of contract, etc.

START

31 august 2024 to 08:00 [UTC]

END DATE

10 september 2024 from 17:00 [UTC]

VIEWING

- ---
Wednesday September 04 2024 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622


ISSUE - COLLECTION

- ---
Wednesday September 18 2024 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47


Online bidding only!

Catalog created on 10 september 2024 to 04:00




	Item	Description	Start price
	1	<p>Brand: Porsche Model: Panamera Variant: 4 E-Hybrid Platinum Edition Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 05/10/2022 Fuel: Hybrid - Electric/Petrol Read odometer reading (km's): 23348 VIN-number: WPOZZZ978PL120252 Number of keys: 2 Vehicle category: M1: passenger car Car type: coupe Transmission: automatic transmission Cylinder capacity cc: 2894 Motor power kW: 243 Emission class: Euro 6 CO2 emissions gr / km: 47 Exterior color: Silver Metallic color: Yes Specific factory color: GT Silver Metallic Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning Board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electrical windows: Yes Electric seats: Yes LED-lighting: Yes Alloy rims: Yes Fog lights: Yes Multifunctional wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Parking sensors in the front: Yes Radio: Yes Shift paddles: Yes Sports package: Yes</p>	100€



		<p>Sports seats: Yes Seat heating: Yes Other options: BOSE sound system electric seats with memory function Steering wheel heating Panamera turbo 20" rims DAB tuner Certificate of registration: Yes, present Certificate of Conformity: Yes, present Inspection certificate: Not present Maintenance book: Not present Visible vehicle damage: No, with the exception of general usage damage. (General use damage includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. Condition: Used Number: 1</p>	
	2	<p>Brand: BMW Model: 420D Version: xDrive Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 08/06/2023 Fuel: Diesel Read odometer reading (km): 22599 Chassis number: WBA21AS010CM81414 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Engine capacity cc: 1995 Engine power kW: 140 Emission class: Euro 6 Exterior color: Gray Metallic colour: No Interior color: Beige Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes</p>	100€




		<p>Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Paddle shifters: Yes Sports package: Yes Seat heating: Yes Other options: electric seats with memory function DAB tuner M package Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	4	<p>Brand: Mercedes-Benz Model: E 300 Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 30/06/2021 Fuel: Hybrid - Electric/Diesel Read odometer reading (km): 57885 Chassis number: W1K2130161A869004 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Engine capacity cc: 1950 Engine power kW: 143</p>	100€




		<p>Emission class: Euro 6 Exterior color: Gray Metallic colour: Yes Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Paddle shifters: Yes Sports seats: Yes Seat heating: Yes Other options: mood lighting Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
--	--	--	--




	5	<p>Brand: Opel Model: Corsa Version: 1.2 S&S MT5 75hp Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 27/04/2023 Fuel gasoline Read odometer reading (km): 16620 Chassis number: VXXUPHMHDP4025047 Number of keys: 2 Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Cylinder capacity cc: 1199 Engine power kW: 55 Emission class: Euro 6 Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Alloy wheels: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Other options: DAB tuner Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 27/04/2027 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	100€
---	---	---	------




	7	<p>Brand: Mercedes-Benz Model: EQB Version: 250 Business Line Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 11/01/2023 Fuel: Electric Read odometer reading (km): 33614 Chassis number: W1N9M0BB2PN021755 Number of keys: 2 Vehicle category: M1: passenger car Car type: Break / station wagon Transmission: Automatic transmission Engine power kW: 140 Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Paddle shifters: Yes Seat heating: Yes Other options: DAB tuner Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage</p>	100€
---	---	--	------




		includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview. condition: Used Quantity: 1	
	8	Brand: Skoda Model: Octavia Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 12/04/2019 Fuel: Diesel Odometer reading (km's): 198105 Chassis number: TMBJG7NE4K0176338 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Break / station wagon Transmission: Manual transmission Cylinder capacity cc: 1598 Engine power kW: 85 Emission class: Euro 6 Co2 emissions gr/km: 131 Exterior colour: Silver Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Alloy rims: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: DAB tuner Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 12/04/2024	100€




		Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	
	9	Brand: Peugeot Model: 308 Version: Puretech Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 02/03/2016 Fuel: Petrol Odometer reading (km's): 164174 Chassis number: VF3LPHNYWGS035048 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Berline Transmission: Automatic transmission Cylinder capacity cc: 1199 Engine power kW: 96 Emission class: Euro 6b Exterior colour: Grey Metallic colour: Yes Interior colour: Grey Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present	100€




		<p>Inspection certificate valid until (dd/mm/yyyy):: 08/11/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	10	<p>Brand: Skoda Model: Fabia Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 13/10/2023 Fuel gasoline Read odometer reading (km): 24271 Chassis number: TMBEE6PJ3P4066795 Number of keys: 2 Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Cylinder capacity cc: 999 Engine power kW: 59 Emission class: Euro 6 Exterior color: White Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Not present Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always</p>	100€




		consult the photo report for a detailed overview. condition: Used Quantity: 1	
	11	Brand: Ssangyong Model: Korando Version: Sapphire 1.5 P A/T 2WD Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 16/05/2020 Fuel gasoline Read odometer reading (km): 45581 Chassis number: KPT60A1YSLP026663 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Automatic transmission Cylinder capacity cc: 1497 Engine power kW: 120 Emission class: Euro 6 Co2 emissions g/km: 180 Exterior color: Red Metallic colour: Yes Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Seat ventilation: Yes Seat heating: Yes Other options: steering wheel heating	100€



		<p>Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	12	<p>Brand: Volvo Model: XC40 Version: R-Design T5 Twin Engine Hybrid Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 25/06/2020 Fuel: Hybrid - Electric/Gasoline Read odometer reading (km): 126665 Chassis number: YV1XZBBBFL2284169 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Automatic transmission Cylinder capacity cc: 1477 Engine power kW: 132 Emission class: Euro 6 Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Electric seats: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes</p>	100€




		<p>Multifunctional steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Seat heating: Yes Other options: electric seats with memory function Harman/Kardon sound system R-Design Additional information: no charging cable available. Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 20/09/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	
	13	<p>Brand: BMW Model: 530e Execution: iPerformance Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 06/05/2020 Fuel: Hybrid - Electric/Gasoline Read odometer reading (km): 67550 Chassis number: WBAJA91070CD83826 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Automatic transmission Cylinder capacity cc: 1998 Engine power kW: 135 Emission class: Euro 6</p>	100€




Exterior color: Blue
Metallic colour: Yes
Interior color: Black
Upholstery: Full leather
Reversing camera: Yes
Air conditioning: Fully automatic air conditioning
On-board computer: Yes
Central locking: Yes
Cruise control: Yes
Electrically folding mirrors: Yes
Electric windows: Yes
LED lighting: Yes
Alloy wheels: Yes
Fog lights: Yes
Multifunctional steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Paddle shifters: Yes
Sports package: Yes
Seat heating: Yes
Other options: M package
DAB tuner
Additional information: Equipped with charger with charging cable.
Registration certificate: Yes, available
Certificate of conformity: Yes, available
Inspection certificate: Yes, available
Inspection certificate valid until (dd/mm/yyyy)::
06/05/2025
Maintenance booklet: Not present
Visible vehicle damage: No, with the exception of general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) You can always consult the photo report for a detailed overview.
condition: Used
Quantity: 1



	14	<p>Brand: Volvo Model: V50 Version: Drive Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 16/02/2012 Fuel: Diesel Odometer reading (km's): 237702 Chassis number: YV1MW84F1C2682086 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Estate / station wagon Transmission: Manual transmission Cylinder capacity cc: 1560 Engine power kW: 84 Emission class: Euro 5 Co2 emissions gr/km: 99 Exterior colour: Black Metallic colour: No Interior colour: Black Upholstery: Full leather Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 10/09/2024 Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	100€
---	----	---	------




	15	<p>Brand: Saab Model: 9-3 Version: 1.9 TiD Year of construction (yyyy): 2007 First registration (dd/mm/yyyy): 31/07/2007 Fuel: Diesel Odometer reading (km's): 160891 Chassis number: YS3FB46VX71149916 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Berline Transmission: Manual transmission Cylinder capacity cc: 1910 Engine power kW: 88 Emission class: Euro 4 Exterior colour: Grey Metallic colour: No Interior colour: Beige Upholstery: Full leather Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 29/07/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	100€
---	----	---	------





	16	<p>Brand: Mercedes-Benz Model: A 200 Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 30/06/2020 Fuel: Petrol Odometer reading (km's): 77375 Chassis number: W1K1770871J235473 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Berline Transmission: Manual transmission Cylinder capacity cc: 1300 Engine power kW: 120 Emission class: Euro 6 Exterior colour: Red Metallic colour: Yes Interior colour: Black Upholstery: Partial leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat heating: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 01/03/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	100€
---	----	--	------



	17	<p>Brand: Nissan Model: Micra Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 08/12/2022 Fuel gasoline Read odometer reading (km): 16586 Chassis number: VNVK1400969934203 Number of keys: 2 Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Cylinder capacity cc: 999 Engine power kW: 68 Emission class: Euro 6 Exterior color: Black Metallic colour: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Radio: Yes Certificate of registration: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1</p>	100€
---	----	---	------




	19	<p>Brand: Daewoo Model: Lanos Year of construction (yyyy): 2001 First registration (dd/mm/yyyy): 02/05/2001 Fuel gasoline Read odometer reading (km): 84418 Chassis number: KLATF08C11B654548 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Manual transmission Cylinder capacity cc: 1349 Engine power kW: 55 Emission class: Euro 2 Exterior color: Silver Metallic colour: No Interior color: Black Upholstery: Fabric Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 06/09/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. condition: Used Quantity: 1</p>	10€
	20	<p>Brand: Volkswagen Model: Golf Version: 7 GTD Year of construction (yyyy): 2015 First registration (dd/mm/yyyy): 11/02/2015 Fuel: Diesel Read odometer reading (km): 207149 Chassis number: WVVZZZAUZFW232113 Number of keys: 2 Vehicle category: M1: passenger car</p>	100€




		<p>Car type: City car Transmission: Automatic transmission Engine capacity cc: 1968 Engine power kW: 135 Exterior color: Black Metallic colour: Yes Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Alloy wheels: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports seats: Yes Seat heating: Yes Additional information: Vehicle not subject to the obligation to be in possession of a certificate of conformity. Registration certificate: Yes, available Certificate of conformity: Not present, see additional information Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 11/02/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Various damage + rust formation condition: Used Quantity: 1</p>	
--	--	--	--




	20	<p>Brand: Porsche Model: 970 Version: Panamera Turbo S Tiptronic Year of construction (yyyy): 2010 First registration (dd/mm/yyyy): 10/06/2010 Fuel gasoline Odometer read (miles): 121730 Chassis number: WP0AA2A70BL010439 Number of keys: 2 Vehicle category: M1: passenger car Car type: Coupé Transmission: Automatic transmission Cylinder capacity cc: 3605 Engine power kW: 220 Emission class: Euro 5 Exterior color: Black Metallic colour: No Interior color: Beige Upholstery: Full leather Air conditioning: Fully automatic air conditioning Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Paddle shifters: Yes Sports package: Yes Seat ventilation: Yes Seat heating: Yes Other options: 3.6 V6 engine Additional information: Electric tailgate function defective Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy)::</p>	100€
---	----	--	------




		<p>08/01/2024 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Electric tailgate function defective condition: Used Quantity: 1</p>	
	21	<p>Brand: Volkswagen Model: Polo Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 14/12/2018 Fuel gasoline Read odometer reading (km): 70511 Chassis number: WVVZZZAWZKY021833 Number of keys: 2 Vehicle category: M1: passenger car Car type: City car Transmission: Manual transmission Cylinder capacity cc: 999 Engine power kW: 48 Emission class: Euro 6 Exterior color: Gray Metallic colour: Yes Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 14/12/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always</p>	100€



		consult the photo report. condition: Used Quantity: 1	
	27	Brand: BMW Model: X5 Version: xDrive 30D Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 23/06/2016 Fuel: Diesel Read odometer reading (km): 228376 Chassis number: WBAKS410X00H78010 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Automatic transmission Cylinder capacity cc: 2993 Engine power kW: 190 Emission class: Euro 6b Co2 emissions g/km: 156 Exterior color: Gray Metallic colour: Yes Interior color: Beige Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat heating: Yes Additional information: Vehicle registered under	100€



		<p>category N1G - Light freight (rear seat converted). Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 14/01/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Deep scratch on hood, scratch on side condition: Used Quantity: 1</p>	
	52	<p>Brand: Dacia Model: Logan Year of construction (yyyy): 2014 First registration (dd/mm/yyyy): 10/06/2014 Fuel gasoline Read odometer reading (km): 10080 Chassis number: UU14SDAG351281466 Number of keys: 2 Vehicle category: M1: passenger car Car type: Berline Transmission: Manual transmission Emission class: Euro 5b Exterior color: Beige Metallic colour: No Interior color: Black Upholstery: Fabric Central locking: Yes Electric windows: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Not available, see additional information Certificate of conformity: Not present, see additional information Inspection certificate: Not applicable</p>	100€



		Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages condition: Used Quantity: 1	
--	--	--	--