

CATALOG

Earthmoving, construction machinery and accessories







DESCRIPTION

Auction of building materials including various electric pallet trucks, a skid steer loader, various forklifts, various buckets, a hydraulic grab, various forks for forklifts and much more!

START

20 september 2024 to 08:00 [UTC]

END DATE

30 september 2024 from 12:00 [UTC]

VIEWING

• ---

Friday September 27 2024 from 10:00 until 12:00 BE-7180 SENEFFE, CHAUSSÉE DE MONS 4

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622

ISSUE - COLLECTION

Aanmelden tussen Tuesday October 08 2024 from 10:00 until 11:00 BE-7180 SENEFFE, CHAUSSÉE DE MONS 4

Online bidding only!

Catalog created on 30 september 2024 to 04:00

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622



	Item	Description	Start price
	1	Brand: Robuste Kaiser Year of construction (yyyy): Not known First registration (dd/mm/yyyy): 03/01/2001 Semi-trailer category: O3: max. mass >3500kg - <10000kg Semi-trailer type: Tipper Chassis number: VHRS3302VY2C01327 Number of axles: 2 Maximum Permissible Mass (kg): 37000 Exterior colour: Blue Trailer registration certificate: Yes, present Trailer conformity certificate: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 26/11/2021 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report consult. Condition: Used Quantity: 1	100€
	2	Brand: Genie Z-34 Model: Z-34/22BE Product category: Aerial work platform Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	100€
Trans.	3	Brand: Mustang Model: 1350R Product category: Skid steer loader Additional information: Bucket width: 1500mm Visible damage: Yes, for a detailed overview of the visible damage you can always consult the	1.000€



		photo report. Condition: Used Quantity: 1	
	4	Brand: Hyster Model: H2.00XL Product category: Forklift Additional information: Diesel Odometer reading: 8593 Drive-through height 2700mm Equipped with single mast and lighting Year of construction 1993 Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	1.000€
	5	Brand: Hyster Model: J2.50XL Product category: Forklift Additional information: Electric Battery broken Minimum clearance: 2240mm Equipped with triple mast Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	100€
IN INVENUELS	6	Brand: Komatsu Model: FD25T-12 Product category: Forklift Additional information: Diesel Odometer reading: 11846 Equipped with double mast	1.000€

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622



		Minimum driving height 2370mm Door window is broken Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	
NISSAN	7	Brand: Nissan Model: 1085 Product category: Forklift Additional information: Electric Battery broken Minimum driving height: 2080mm Equipped with triple mast Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	100€
	8	Brand: Toyota Model: 22192 Product category: Forklift Additional information: Gas Equipped with triple mast Equipped with lighting Odometer reading 16283 Minimum driving height Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	1.000€



9	Brand: . Model: . Product category: Shovel Additional information: 1900x940xH760 Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
10	Brand: . Model: . Product category: Shovel Additional information: 1300x1500xH1020 Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
11	Brand: . Model: . Product category: Shovel Additional information: 1320x1250xH940 Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
12	Brand: . Model: . Product category: Various buckets Including damaged Additional information: Largest: 900x900xH700 Smallest: 400x950xH950	10€

AUCTIM - MOYERSOEN NV Helststraat 47



	Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 3	
13	Brand: . Model: . Product category: Hydraulic breaker Additional information: H1320x400x220 Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
14	Brand: . Model: . Product category: Hydraulic grab Additional information: 1200xD900 Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
15	Brand: Franz Model: F1300 Product category: 460x580xH2160 1220Kg Year of construction 2019 Additional information: H1320x400x220 Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€

AUCTIM - MOYERSOEN NV


Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622



16	Brand: . Model: . Product category: Various forks for forklifts lying on 1 pallet Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 8	10€
17	Brand: . Model: . Product category: Various forks for forklifts lying on 1 pallet Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 5	10€
18	Brand: . Model: . Product category: Various forks for forklifts lying on 1 pallet Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 4	10€

VAT BE 0452 153 622









23 Brand: Straaltechniek international

Model: SSM2

Product category: Blasting machine

Additional information: Max pressure 4Bar

1180x720xH1940

Mobile

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 1



24 Brand: .

Model: .

Product category: Frame for trailer

Additional information: 3200x1900xH1230

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 1



25 Brand: .

Model: .

Product category: Various concrete mixers

Additional information: Scrap Largest: 1870x1000xH1500

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 2 10€

10€





26 Brand: .

Model: .

Product category: Steel cables and four-way Additional information: Consisting of: 8 cables thickness 30mm,²length approx. 4000mm

Four-way length approx. 9000m

Not approved

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 9



27

Brand: . Model: .

Product category: Various steel cables

Additional information: Approximately 3500mm

length

Diameter 30mm

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 5



28

Brand: .

Model: .

Product category: Adjustable fork board with 4

Additional information: 1200x1400xH1450

100-250Kg

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 1

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622

www.auctim.com info.moyersoen@auctim.be

10€

10€





Brand: .

Model: .

Product category: Scrap

Additional information: 900x300x1900

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 1



30

Brand: .

Model: .

Product category: Various Fuel tanks Additional information: Consisting of

2x 1250x800xH660 1x 700x750xH540

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 3



31 Brand: .

Model: .

Product category: Lot of various scrap metal Additional information: lying on 3 pallets

Excluding numbered lots

Delivery according to instructions

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 1

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622 **www.auctim.com** info.moyersoen@auctim.be

10€

10€





32 Brand: Nissan 100€

Model: 33ZRM02L25U Product category: Forklift Additional information: Electric Equipped with matching charger Odometer reading: 25001

Minimum driving height 2200mm

Tripel Mast

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 1



33 Brand: Wavin 10€

Model: B125-C250

Product category: Cast iron manhole covers Additional information: Dimensions 1 cover

390x390mm

Lot more than 1000Kg

Cast iron

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 78



Brand: . 34 10€

Model: .

Product category: Grounding loop

Additional information: Lying on wooden roll. Lead sheath, provided with copper core Total weight between 250 and 1000 kg

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 2

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622



35	Brand: Vanguard Model: 185432 Product category: Motorcycle Additional information: Equipped with extra fuel tank Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
36	Brand: Including GEWISS, Sylvania Model: . Product category: Various industrial lamps and spotlights Additional information: In various dimensions and sizes including largest: 680x370xH570 Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 6	10€
37	Brand: Ibiza Light Model: . Product category: Various party lighting Additional information: Including stand Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 7	10€



113	SP.

38 Brand: Including Halfen 10€

Model: .

Product category: Approximately various nuts and

bolts

Additional information: Including M10x30 and

M10x40

Including fitted with hammer head

Approximately 4000 pieces lying in 3 metal

containers

between 250 and 1000 kg Including 4 rack supports

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 4000



39 Brand: Avant tecno oy 100€

Model: A1194

Product category: Grain and flour distribution bin

Additional information: 1050x900xH730

between 100 - 250Kg

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 1



40 Brand: ESAB 100€

Model: Puls-aid

Product category: Welding post

Additional information: 1000x600xH2200

between 100 - 250Kg

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 1

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622



etim.coi	41	Brand: Cemont Model: Sharp 40M Product category: Plasma burner Additional information: 800x400xH800 Between 100 and 250Kg Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
	42	Brand: Crown Model: . Product category: Electric pallet truck Additional information: Equipped with charger Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
	43	Brand: Agile Model: lifter Product category: Electric pallet truck Additional information: Equipped with charger Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€



44	Brand: Agile Model: lifter Product category: Electric pallet truck Additional information: Equipped with charger Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
45	Brand: Agile Model: lifter Product category: Electric pallet truck Additional information: Equipped with charger Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
46	Brand: Caymon Model: FCDJ2100MKII Product category: Flightcases Additional information: 870x530xH190 Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 3	10€
47	Brand: RAJA Model: . Product category: Bubble wrap rolls Additional information: 2000x10000mm 13.5Kg	10€

AUCTIM - MOYERSOEN NV



	Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 3	
48	Brand: Including Verciel, WD40, Quechua, and others Model: . Product category: Remaining garage Additional information: Including: 1 Honda lawn mower, 1 wooden writing desk, various used hand tools including hammers, saws, wrenches, files, Niko switches, various spotlights, various household items including glasses, dog baskets, camping equipment, flower pots, washing lines and others Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€
49	Brand: SYM Model: GTS300Evo Product category: Motor scooter Number of wheels: 2 Additional information: Odometer reading 14179.5 Km Visible damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€





Brand: Including Tupperware, Evatronic, Domo,

Philips Model: .

Product category: Remaining stock household

goods

Additional information: Including:

3 various microwave ovens, 1 batch of various

microwave pots Tupperware

Visible damage: Yes, for a detailed overview of the visible damage you can always consult the

photo report. Condition: Used Quantity: 1

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622 **www.auctim.com** info.moyersoen@auctim.be