



CATALOG

Transport company Asanov transport - bankruptcy



DESCRIPTION

Bankruptcy auction of a transport company with a Renault T 460, a Scania R460, a Renault Premium, a DAF LF, a Renault Mégane, a Peugeot Boxer, a Volkswagen Passat, a Renault Master, the remaining warehouse contents and various IT equipment.

START

27 september 2024 to 08:00 [UTC]

END DATE

7 october 2024 from 09:00 [UTC]

VIEWING

- Lots: 94

Wednesday October 02 2024 from 15:00 until 17:00
Helststraat 47, 2630 Aartselaar
- ---
Tuesday October 01 2024 from 15:00 until 16:00
BE-9080 Zeveneken, Bastelare 110

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622

ISSUE - COLLECTION

- Lots: 94

Wednesday October 16 2024 from 10:00 until 12:00
Helststraat 47, 2630 Aartselaar
- Aanmelden tussen
Tuesday October 15 2024 from 10:00 until 11:00
BE-9080 Zeveneken, Bastelare 110

AUCTIM - MOYERSOEN NV

Helststraat 47
2630 Aartselaar, Belgium
VAT BE 0452 153 622

www.auctim.com
info.moyersoen@auctim.be




AUCTIM
ONLINE AUCTIONS


Online bidding only!

Catalog created on 7 october 2024 to 04:00




	Item	Description	Start price
	1	<p>Brand: Renault Model: T 460 Version: Comfort Year of construction (yyyy): 2015 First registration (dd/mm/yyyy): 09/12/2015 Fuel: Diesel Odometer reading (km's): 466624 Chassis number: VF611A163GD013881 Number of keys: 1 Number of axles: 2 Maximum Permissible Mass (kg): 19500 Transmission: Automatic transmission Cylinder capacity cc: 10837 Engine power kW: 345 Emission class: Euro 6 Exterior colour: Grey Metallic colour: Yes Interior colour: Brown Upholstery: Partial leather Other options: Aluminium rims, Light bar with 4 spotlights, CB President, ... See photo report for all options</p> <p>Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 04/03/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Various error messages, including "ECU Electrical Fault" Battery empty, start with booster Condition: Used Quantity: 1</p>	100€





	2	<p>Brand: Scania Model: R460 Version: LA4X2 Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 20/10/2011 Fuel: Diesel Odometer reading (km's): 911501 Chassis number: XLER4X20005276691 Number of keys: 1 Number of axles: 2 Maximum Permissible Mass (kg): 19000 Transmission: Manual transmission Cylinder capacity cc: 12700 Engine power kW: 360 Emission class: Euro 5 Exterior colour: Red Metallic colour: No Interior colour: Beige Upholstery: Artificial leather Other options: Light bar, Blind spot camera Interior mats Parking heater, For all options see photo report Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 19/11/2024 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Battery empty, start with booster Condition: Used Quantity: 1</p>	100€
---	---	---	------




	3	<p>Brand: Renault Model: Premium Version: 270 dxi Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 14/05/2012 Fuel: Diesel Odometer reading (km's): 724717 (last inspection DD. 08/01/2024) Chassis number: VF629AHA000007811 Number of keys: 1 Number of axles: 2 Maximum Permissible Mass (kg): 18000 Transmission: Automatic transmission Cylinder capacity cc: 7146 Engine power kW: 247 Exterior colour: White Metallic colour: No Interior colour: Brown Upholstery: Fabric Other options: Rear view camera Tail lift 1 solid wall with door and 1 wall with tarpaulin, For all options see photo report Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 14/11/2011 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Does not start. Presumably electrical problem (did start and drive in parking lot) Condition: Used Number: 1</p>	100€
---	---	--	------




	4	<p>Brand: DAF Model: LF Version: 55.250 Year of construction (yyyy): 2008 First registration (dd/mm/yyyy): 28/10/2008 Fuel: Diesel Odometer reading (km's): 564903 Odometer reading (miles): 351014 Chassis number: XLRAE55GF0L346910 Number of keys: 1 Number of axles: 2 Maximum Permissible Mass (kg): 19000 Transmission: Automatic transmission Cylinder capacity cc: 6693 Engine power kW: 182 Exterior colour: White Metallic colour: No Interior colour: Grey Upholstery: Fabric Other options: Tail lift Dhollandia Front all options see photo report Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 26/10/2023 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	100€
	5	<p>Brand: Renault Model: Mégane Version: 1.4 Year of construction (yyyy): 1997 First registration (dd/mm/yyyy): 12/06/1997 Fuel: Petrol Odometer reading (km's): Unknown Chassis number: VF1BA0T0E16279229 Number of keys: 2</p>	1€




		<p>Vehicle category: M1: passenger car Vehicle type: City car Transmission: Manual transmission Cylinder capacity cc: 1390 Engine power kW: 52 Exterior colour: Blue Metallic colour: No Interior colour: Grey Upholstery: Fabric Registration certificate: Yes, present Certificate of conformity: Not present. (Import within European Union) Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 23/10/2024 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Operation unknown, does not start, no battery present Condition: Used Quantity: 1</p>	
	6	<p>Brand: Peugeot Model: Boxer Version: 3.0 HDI Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 08/03/2013 Fuel: Diesel Odometer reading (km's): Unknown Chassis number: VF3YCPMFC12330126 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2999 Engine power kW: 130 Emission class: Euro 5 Exterior colour: Silver Interior colour: Grey</p>	10€





		<p>Upholstery: Fabric Additional information: Bumper and bonnet present in loading area Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of conformity Inspection certificate: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Operation unknown, Engine partly dismantled, Does not start, does not drive. Condition: Used Number: 1</p>	
	7	<p>Brand: Volkswagen Model: Passat Version: 1.9 TDI Year of construction (yyyy): 1999 First registration (dd/mm/yyyy): 03/03/1999 Fuel: Diesel Odometer reading (km's): 373695 Chassis number: WVWZZZ3BZXP251137 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Berline Transmission: Manual transmission Cylinder capacity cc: 1896 Engine power kW: 66 Exterior colour: Green Interior colour: Black Upholstery: Fabric On-board computer: Yes Central locking: Yes Electric windows: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present</p>	10€



		<p>Inspection certificate valid until (dd/mm/yyyy):: 14/11/2023 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	8	<p>Quantity: 1 Product category: remaining contents of warehouse Additional information: consisting of (including): 1 hexagonal dining table with 6 chairs, 1 side cabinet, 1 heating element PROLINE, 1 corner desk, 1 office chair, 1 dressing table, 1 coffee machine NESPRESSO, 1 bookcase, 1 office cabinet, 1 freezer case ARTIC, 1 (presumably defective) oven ROFCO, 1 three-seater sofa, 1 fitness bench, 2 various refrigerators, 1 electric stove, 1 microwave oven, 1 saw table, various chairs, various spare parts for trucks and passenger cars, 1 workbench with vice, 2 angle grinders, 2 batteries, 1 workbench with column drill and double grinder, 1 cart, 1 old diesel generator, 5 running meters of storage rack containing various spare parts, 3 opened barrels of oil MOBIL, 1 IBC container (contents unknown), 2 stepladders wo. SOLID, 1 handcart, and others</p> <p>Delivery according to instructions, excluding other goods owned by third parties, excluding goods fixed to building, excluding pallet racking, excluding IT equipment (lot 10) Weight category: more than 1,000 kg Condition: Used Location: Warehouse back</p>	1€



	9	<p>Quantity: 2 pieces Product category: various IT equipment Brand: HP Additional information: consisting of 1 laptop HP 17 X063NB (with charger) and 1 printer HP Deskjet 2630 Weight category: 0 to 23 kg Condition: Used Location: Warehouse office</p>	1€
	94	<p>Make: Renault Model: MASTER Version: DCI150 Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 23/10/2012 Fuel: Diesel Odometer reading (km's): unknown Chassis number: VF6MFF4FE47431505 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 107 Emission class: Euro 5 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Additional information: Does not start, no battery, probably defective, part of the interior is missing Registration certificate: Yes, present Certificate of conformity: Yes, present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Number: 1</p>	10€