



CATALOG

Commercial vehicles



DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

28 september 2024 to 08:00 [UTC]

END DATE

8 october 2024 from 16:30 [UTC]

VIEWING

- ---
Wednesday October 02 2024 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622


ISSUE - COLLECTION

- ---
Wednesday October 16 2024 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47


Online bidding only!

Catalog created on 8 october 2024 to 04:03




	Item	Description	Start price
	1	<p>Brand: Opel Model: Combo Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 14/06/2022 Fuel: Diesel Odometer reading (km's): 34566 Chassis number: W0VEFYHT2NJ616297 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of axles: 2 Maximum Permissible Mass (kg): 2400 Transmission: Manual transmission Cylinder capacity cc: 1499 Engine power kW: 75 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Radio: Yes Other options: DAB tuner Roof rack Q-Top - max. load 150kg Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 03/02/2025 Maintenance booklet: Not present Visible vehicle damage: No, except general wear and tear. (General wear and tear includes all damage that may be expected given the age and mileage or hours.) For a detailed overview, you can always consult the photo report. Condition: Used Quantity: 1</p>	100€




	9	<p>Brand: Fiat Model: Ducato Version: 290 2.3 MJET 140PK 35 L-H2 Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 15/06/2020 Fuel: Diesel Odometer reading (km's): 190892 Chassis number: ZFA25000002N92775 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 103 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Navigation: Yes Radio: Yes Other options: DAB tuner Additional information: start with booster! Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 22/06/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! various damages</p>	100€




		message dashboard engine Condition: Used Quantity: 1	
	19	Brand: Fiat Model: Doblo Version: 90 Multijet Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 08/02/2016 Fuel: Diesel Odometer reading (km's): 161009 Chassis number: ZFA26300006B81898 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of axles: 2 Maximum Permissible Mass (kg): 2144 Transmission: Manual transmission Cylinder capacity cc: 1248 Engine power kW: 66 Emission class: Euro 5b Co2 emissions gr/km: 136 Exterior colour: Grey Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Additional information: radio screen cracked Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy)::	100€




		<p>05/05/2024</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p> <p>Vehicle damage description: radio screen cracked various damages</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	21	<p>Brand: Citroen</p> <p>Model: Jumper</p> <p>Year of construction (yyyy): 2020</p> <p>First registration (dd/mm/yyyy): 22/10/2020</p> <p>Fuel: Diesel</p> <p>Read odometer reading (km): 147954</p> <p>Chassis number: VF7YDCNFC12R02046</p> <p>Number of keys: 1</p> <p>Vehicle category: N1: max. mass <3.5t.</p> <p>Construction: Closed van</p> <p>Number of axles: 2</p> <p>Maximum Allowable Mass (kg): 3500</p> <p>Transmission: Manual transmission</p> <p>Cylinder capacity cc: 2179</p> <p>Engine power kW: 121</p> <p>Emission class: Euro 6</p> <p>Exterior color: Gray</p> <p>Metallic colour: No</p> <p>Interior color: Black</p> <p>Upholstery: Fabric</p> <p>Reversing camera: Yes</p> <p>Air conditioning: Manual air conditioning</p> <p>Central locking: Yes</p> <p>Cruise control: Yes</p> <p>Electrically folding mirrors: Yes</p> <p>Electric windows: Yes</p> <p>Navigation: Yes</p> <p>Rear parking sensors: Yes</p> <p>Radio: Yes</p> <p>Registration certificate: Yes, available</p> <p>Certificate of conformity: Yes, available</p> <p>Identification report: Yes, present</p>	100€




		<p>Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 06/11/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: windshield cracked various damages condition: Used Quantity: 1</p>	
	23	<p>Brand: Volkswagen Model: Crafter Version: TDI Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 03/10/2016 Fuel: Diesel Odometer reading (km's): 151159 Chassis number: WV1ZZZ2EZG6046591 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 1968 Engine power kW: 100 Emission class: Euro 5b Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Leatherette Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Radio: Yes Tow bar: Yes Other options: equipped with roof rack and ladder</p> <p>Registration certificate: Yes, present Certificate of conformity: Yes, present</p>	100€




		<p>CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 22/09/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! windshield cracked body damage Condition: Used Quantity: 1</p>	
	63	<p>Make: Peugeot Model: Partner Year of construction (yyyy): 2014 First registration (dd/mm/yyyy): 29/12/2014 Fuel: Diesel Odometer reading (km's): 153803 Chassis number: VF37A9HF0EJ851875 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of axles: 2 Maximum Permissible Mass (kg): 1960 Transmission: Automatic transmission Cylinder capacity cc: 1560 Engine power kW: 66 Emission class: Euro 5b Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Radio: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available</p>	100€




		<p>CARPASS: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 13/10/2024 Maintenance booklet: Not available Visible vehicle damage: Yes, For a detailed overview of the visible damage, you can always consult the photo report. Condition: Used Quantity: 1</p>	
	69	<p>Brand: Fiat Model: Ducato Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 28/12/2017 Fuel: Diesel Odometer reading (km's): 223502 Chassis number: ZFA25000002F99811 Number of keys: 1 Construction: Panel van Number of axles: 1 Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 110 Emission class: Euro 6b Co2 emissions gr/km: 165 Exterior colour: Yellow Metallic colour: No Interior colour: Grey Upholstery: Fabric Reversing camera: Yes On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Navigation: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present</p>	100€




		<p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 24/04/2023 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Scratches all around - a few dents - broken mirror glass - loading space has enormous wear - paint cracked on rear door - plastic cover missing on rear door - holder 3rd brake light broken - stone chip at the front - 1 key present Condition: Used Quantity: 1</p>	
	72	<p>Brand: Citroen Model: Berlingo Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 19/04/2012 Fuel: Diesel Odometer reading (km's): 213048 Chassis number: VF77A9HF0CN514460 Number of keys: 1 Construction: Panel van Number of axles: 1 Transmission: Manual transmission Cylinder capacity cc: 1560 Engine power kW: 66 Emission class: Euro 5 Co2 emissions gr/km: 138 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Central locking: Yes Electric windows: Yes Fog lights: Yes Tow bar: Yes Additional information: Part 1 only - Part 1 only Registration certificate: Not present, see additional information Certificate of conformity: Yes, present</p>	100€




		<p>CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 08/01/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Scratches and dents all around - cracked windshield - loading space heavily used - rims rusted Condition: Used Quantity: 1</p>	
	74	<p>Brand: Ford Model: Transit Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 02/04/2013 Fuel: Diesel Odometer reading (km's): / Chassis number: WF0XXTTFXDU81510 Number of keys: 0 Construction: Panel van Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 114 Emission class: Euro 5 Co2 emissions gr/km: 228 Exterior colour: Yellow Metallic colour: No Interior colour: Grey Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Fog lights: Yes Multifunctional steering wheel: Yes Radio: Yes Tow bar: Yes Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present</p>	100€



		<p>CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 22/09/2024 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Scratches and dents all around - Paint damage all around - Color faded Condition: Used Quantity: 1</p>	
	79	<p>Make: Renault Model: Master Year of construction (yyyy): 2009 First registration (dd/mm/yyyy): 01/12/2009 Fuel: Diesel Odometer reading (km's): 123041 Chassis number: VF1FDC1H642273156 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2464 Engine power kW: 88 Emission class: Euro 4 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Central locking: Yes Electric windows: Yes Fog lights: Yes Radio: Yes Tow bar: Yes Other options: roof rack ladder Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available</p>	100€



		<p>Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 30/11/2023 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: does not start - possibly battery defect! Condition: Used Quantity: 1</p>	
	80	<p>Brand: Fiat Model: Ducato Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 04/01/2012 Fuel: Diesel Odometer reading (km's): 147450 Chassis number: ZFA25000002124228 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Maximum Permissible Mass (kg): 3300 Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 109 Emission class: Euro 5 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Central locking: Yes Electric windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 25/01/2024 Visible vehicle damage: Yes, for a detailed</p>	100€



		overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	
--	--	--	--