



**CATALOG**  
Passenger cars



**DESCRIPTION**

Auction of passenger cars from various bankruptcies, seizures, breaches of contract, etc.

**START**

23 november 2024 to 09:00 [UTC]

**END DATE**

3 december 2024 from 18:00 [UTC]

**VIEWING**

- Lots: 12, 14-18, 20, 24, 30  
---  
Wednesday November 27 2024 from 15:00 until 17:00  
BE-2630 Aartselaar, Helststraat 47
- Lots: 5  
Only by appointment through the organizer.  
Wednesday November 27 2024 from 08:30 until 09:00  
BE-2840 Rumst, Doelhaagstraat 77

**AUCTIM PARTNER**

**MOYERSOEN NV**

Helststraat 47, 2630 Aartselaar, Belgium  
+32 3 827 21 31 - info.moyersoen@auctim.be  
BTW BE 0452 153 622




**ISSUE - COLLECTION**

- Lots: 12, 14-18, 20, 24, 30  
---  
Wednesday December 11 2024 from 10:00 until 12:00  
BE-2630 Aartselaar, Helststraat 47
- Lots: 5  
Aanmelden tussen  
Monday December 09 2024 from 12:00 until 12:30  
BE-2840 Rumst, Doelhaagstraat 77


**Online bidding only!**

Catalog created on 3 december 2024 to 04:00




	Item	Description	Start price
	5	<p>Brand: KIA Model: C'EED Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 21/02/2012 Fuel: Diesel Odometer reading (km's): 100179 Chassis number: U5YHC816ACL236443 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Estate / station wagon Transmission: Manual transmission Cylinder capacity cc: 1582 Engine power kW: 66 Emission class: Euro 5 Co2 emissions gr/km: 122 Exterior colour: Grey Metallic colour: Yes Interior colour: Grey Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 21/02/2022 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Flat battery, mold formation inside, musty smell</p>	100€




		Condition: Used Quantity: 1	
	12	Brand: Audi Model: A4 Version: Avant TDI 2.0 Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 11/03/2019 Fuel: Diesel Odometer reading (km's): 51520 Chassis number: WAUZZZF48KA021412 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Break / station wagon Transmission: Automatic transmission Cylinder capacity cc: 1968 Engine power kW: 110 Emission class: Euro 6 Co2 emissions gr/km: 148 Exterior color: Black Metallic color: Yes Interior color: Black Upholstery: Full leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat heating: Yes Other options: Including 2 boxes of original Audi sun blinds Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present	100€




		<p>Inspection certificate valid until (dd/mm/yyyy):: 11/03/2025 Maintenance booklet: Yes, present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	14	<p>Brand: Mercedes-Benz Model: CLK 200 Year of construction (yyyy): 2000 First registration (dd/mm/yyyy): 25/01/2000 Fuel: Petrol Odometer reading (km's): 146022 Chassis number: WDB2084351T041333 Number of keys: 1+1 Vehicle category: M1: passenger car Vehicle type: Convertible Transmission: Automatic transmission Cylinder capacity cc: 1998 Engine power kW: 100 Exterior colour: Blue Interior colour: Beige Upholstery: Full leather Electric windows: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 06/09/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: windows do not close properly Condition: Used Quantity: 1</p>	10€




	15	<p>Brand: mercedes-benz Model: A 180 d Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 23/02/2019 Fuel: Diesel Odometer reading (km's): 198561 Chassis number: WDD1770031N052832 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: City car Transmission: Automatic transmission Cylinder capacity cc: 1461 Engine power kW: 85 Emission class: Euro 6b Exterior colour: Grey Upholstery: Full leather Air conditioning: Semi-automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Navigation: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Seat heating: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 24/03/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	100€
---	----	---	------




	16	<p>Brand: Fiat Model: 500 Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 29/12/2017 Fuel: Petrol Odometer reading (km's): 26312 Chassis number: ZFA3120000J911331 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: City car Transmission: Manual transmission Cylinder capacity cc: 1242 Engine power kW: 51 Emission class: Euro 6b Exterior colour: Red Metallic colour: Yes Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Multifunction steering wheel: Yes Panoramic roof: Yes Rear parking sensors: Yes Radio: Yes Other options: DAB tuner Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 29/12/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Various damages. Condition: Used Quantity: 1</p>	100€
---	----	---	------




	17	<p>Brand: BMW Model: 428i Version: Gran Coupé Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 23/02/2016 Fuel: Petrol Odometer reading (km's): 195242 Chassis number: WBA4A510X0G512430 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Coupé Transmission: Automatic transmission Cylinder capacity cc: 1997 Engine power kW: 180 Emission class: Euro 6b Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Sports seats: Yes Seat heating: Yes Other options: M package Carbon spoiler Black ALPINA alloy rims Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate</p>	100€
---	----	---	------






		<p>Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 18/05/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Various damages Condition: Used Quantity: 1</p>	
	18	<p>Brand: opel Model: corsa Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 11/09/2017 Fuel: Diesel Odometer reading (km's): 131791 Chassis number: W0V0XEP68H4305164 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: City car Transmission: Manual transmission Cylinder capacity cc: 1248 Engine power kW: 55 Emission class: Euro 6b Exterior colour: Grey Upholstery: Fabric Trip computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 31/12/2024 Visible vehicle damage: Yes, for a detailed</p>	10€




		overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	
	20	Brand: Kia Model: SORENTO Year of construction (yyyy): 2005 First registration (dd/mm/yyyy): 26/05/2005 Fuel: Diesel Odometer reading (km's): 309942 Chassis number: KNEJC521855403495 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Automatic transmission Cylinder capacity cc: 2497 Engine power kW: 103 Emission class: Euro 3 Exterior colour: Grey Upholstery: Leatherette Central locking: Yes Electric windows: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, present Certificate of Conformity: Yes, present Inspection Certificate: Yes, present Inspection Certificate Valid Until (dd/mm/yyyy):: 01/03/2024 Visible Vehicle Damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	10€



	24	<p>Brand: BMW Model: 220D Year of construction (yyyy): 2015 First registration (dd/mm/yyyy): 22/04/2015 Fuel: Diesel Odometer reading (km's): 179956 Chassis number: WBA2L71010V447217 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Convertible Transmission: Automatic transmission Cylinder capacity cc: 1995 Engine power kW: 140 Emission class: Euro 6b Co2 emissions gr/km: 113 Exterior colour: Grey Metallic colour: Yes Interior colour: Red Upholstery: Full leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central lock: Yes Cruise control: Yes Electric windows: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Sport seats: Yes Seat heating: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 22/04/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	100€
---	----	---	------



	30	<p>Brand: Renault Model: Kadjar Version: S-Edition Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 02/01/2019 Fuel: Petrol Odometer reading (km's): 131721 Chassis number: VF1RFE00661183473 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Transmission: Automatic transmission Cylinder capacity cc: 1197 Engine power kW: 96 Emission class: Euro 6b Exterior colour: Black Metallic colour: No Interior colour: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 02/01/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used</p>	100€
---	----	--	------



		Quantity: 1	
--	--	-------------	--