

CATALOGPassenger cars







DESCRIPTION

Auction of passenger cars from various breaches of contract

START

23 november 2024 to 09:00 [UTC]

END DATE

3 december 2024 from 18:30 [UTC]

VIEWING

• ---

Wednesday November 27 2024 from 15:00 until 17:00

BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622

ISSUE - COLLECTION

• ---

Wednesday December 11 2024 from 10:00 until 12:00 BE-2630 Aartselaar, Helststraat 47

Online bidding only!

Catalog created on 3 december 2024 to 04:00

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622 $\begin{tabular}{ll} www.auctim.com \\ info.moyersoen@auctim.be \\ \end{tabular}$



Item	Description	Start price
2	Brand: Tesla Model: Model Y Version: Long Range Dual Motor Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 19/09/2022 Fuel: Electric Odometer reading (km's): 50398 Chassis number: LRWYGCEK2NC460810 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Berline Transmission: Automatic transmission Engine power kW: 378 Exterior colour: Black Metallic colour: No Interior colour: Black Upholstery: Leatherette Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric seats: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat heating: Yes Other options: Autopilot Steering wheel heating Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed	100€



overview of the visible damage you can always

consult the photo report.

Condition: Used Quantity: 1



4 Brand: Porsche Model: Panamera

Version: 4 PHEV Platinum Edition Year of construction (yyyy): 2021

First registration (dd/mm/yyyy): 24/02/2022

Fuel: Hybrid - Electric/Petrol Odometer reading (km's): 59161

Chassis number: WP0ZZZ97ZNL125646

Number of keys: 2

Vehicle category: M1: passenger car

Vehicle type: Coupé

Transmission: Automatic transmission

Cylinder capacity cc: 2894 Engine power kW: 243 Emission class: Euro 6 Exterior colour: Green Metallic colour: Yes

Specific factory colour: Aventurine Green Metallic

Interior colour: Black Upholstery: Full leather Reversing camera: Yes

Air conditioning: Fully automatic air conditioning

On-board computer: Yes Central locking: Yes Cruise control: Yes

Electric folding mirrors: Yes

Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Head up display: Yes LED lighting: Yes Alloy rims: Yes Fog lights: Yes

Multifunction steering wheel: Yes

Navigation: Yes Open roof: Yes Panoramic roof: Yes

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622 **www.auctim.com** info.moyersoen@auctim.be

3/8



Rear parking sensors: Yes Front parking sensors: Yes

Radio: Yes

Shift paddles: Yes Sports package: Yes Sports seats: Yes Seat ventilation: Yes Seat heating: Yes

Other options: BOSE sound system electric seats with memory function

DAB tuner

steering wheel heating

Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Not present Maintenance booklet: Not present

Visible vehicle damage: No, except general wear and tear. (General wear and tear includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview,

you can always consult the photo report. Invoice amount (€ incl. VAT): 144235.18 Invoice date (dd-mm-yyyy): 14/04/2022

Condition: Used Quantity: 1



4 Brand: Volkswagen

Model: Arteon

Version: R-Line 2.0 TDI 4 Motion Year of construction (yyyy): 2021

First registration (dd/mm/yyyy): 11/08/2021

Fuel: Diesel

Odometer reading (km's): 66562

Chassis number: WVWZZZ3HZME010771

Number of keys: 2

Vehicle category: M1: passenger car

Vehicle type: Berline

Transmission: Automatic transmission

Cylinder capacity cc: 1968 Engine power kW: 147 Emission class: Euro 6

AUCTIM - MOYERSOEN NV

www.auctim.com info.moyersoen@auctim.be



Co2 emissions gr/km: 128

Exterior color: Gray Metallic color: Yes Interior color: Black Upholstery: Full leather Reversing camera: Yes

Air conditioning: Fully automatic air conditioning

On-board computer: Yes Central locking: Yes Cruise control: Yes

Electric folding mirrors: Yes

Electric tailgate: Yes
Electric windows: Yes
Electric seats: Yes
Head up display: Yes
LED lighting: Yes
Alloy rims: Yes
Fog lights: Yes

Multifunction steering wheel: Yes

Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensor

Rear parking sensors: Yes Front parking sensors: Yes

Radio: Yes Sport seats: Yes Seat heating: Yes

Other options: electric seats with memory

function DAB tuner

steering wheel heating

Registration certificate: Not present: the buyer will receive a certificate of loss of registration

certificate

Certificate of conformity: Yes, present Inspection certificate: Not present Maintenance booklet: Not present

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always

consult the photo report.

Condition: Used Quantity: 1





12 Brand: Audi

Model: A5 Version: TFSI

Year of construction (yyyy): 2021

First registration (dd/mm/yyyy): 05/05/2021

Fuel: Petrol

Odometer reading (km's): 73801

Chassis number: WAUZZZF5XMA033492

Number of keys: 1

Vehicle category: M1: passenger car

Vehicle type: Berline

Transmission: Automatic transmission

Cylinder capacity cc: 1984
Engine power kW: 150
Emission class: Euro 6
Exterior colour: Black
Metallic colour: No
Interior colour: Black
Upholstery: Fabric
Reversing camera: Yes

Air conditioning: Fully automatic air conditioning

On-board computer: Yes Central locking: Yes Cruise control: Yes

Electric folding mirrors: Yes

Electric tailgate: Yes Electric windows: Yes

Alloy rims: Yes Fog lights: Yes

Multifunctional steering wheel: Yes

Navigation: Yes

Rear parking sensors: Yes Front parking sensors: Yes

Radio: Yes

Shift paddles: Yes Seat heating: Yes

Other options: DAB tuner

Additional information: damage to gear lever

Registration certificate: Yes, present Certificate of conformity: Yes, present

CARPASS: Yes, present

Inspection certificate: Not present Maintenance booklet: Not present

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always

AUCTIM - MOYERSOEN NV

www.auctim.com info.moyersoen@auctim.be



consult the photo report.

Vehicle damage description: damage to gear lever

Condition: Used

Number: 1



13 Brand: Alfa Romeo

Model: Stelvio

Version: Veloce 2.0

Year of construction (yyyy): 2022

First registration (dd/mm/yyyy): 14/09/2022

Fuel: Petrol

Odometer reading (km's): 59142

Chassis number: ZARPAHDN0N7D46332

Number of keys: 2

Vehicle category: M1: passenger car

Vehicle type: SUV or 4x4

Transmission: Automatic transmission

Cylinder capacity cc: 1995
Engine power kW: 206
Emission class: Euro 6
Exterior colour: Grey
Metallic colour: Yes
Interior colour: Red
Upholstery: Full leather
Reversing camera: Yes

Air conditioning: Fully automatic air conditioning

On-board computer: Yes Central locking: Yes Cruise control: Yes

Electric folding mirrors: Yes

Electric tailgate: Yes Electric windows: Yes Electric seats: Yes LED lighting: Yes Alloy rims: Yes Fog lights: Yes

Multifunction steering wheel: Yes

Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes

AUCTIM - MOYERSOEN NV

www.auctim.com info.moyersoen@auctim.be



Front parking sensors: Yes

Radio: Yes

Shift paddles: Yes Sports package: Yes Sports seats: Yes Seat heating: Yes

Other options: electric seats with memory

function DAB tuner

painted brake calipers

Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Not present Maintenance booklet: Not present

Visible Vehicle damage: Yes, for a detailed overview of the visible damage you can always

consult the photo report.

Condition: Used Quantity: 1