



CATALOG
Transport & Logistics



DESCRIPTION

Auction of Transport and Logistics

START

8 february 2025 to 09:00 [UTC]

END DATE

18 february 2025 from 10:00 [UTC]

VIEWING

- ---
Wednesday February 12 2025 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622


ISSUE - COLLECTION

- ---
Tuesday February 25 2025 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47



Online bidding only!

Catalog created on 18 february 2025 to 04:00




	Item	Description	Start price
	1	<p>Make: MAN Model: TGM 18.290 Year of construction (yyyy): 2009 First registration (dd/mm/yyyy): 11/06/2009 Fuel: Diesel Odometer reading (km's): 952771 Chassis number: WMAN18ZZ79Y233572 Number of keys: 1 Category: N3: max. mass >12t. Type of truck: Tractor Number of axles: 2 Maximum Permissible Mass (kg): 18600 Transmission: Automatic transmission Cylinder capacity cc: 6871 Engine power kW: 213 Emission class: Euro 4 Exterior colour: White Interior colour: Grey Upholstery: Fabric Air conditioning: Manual air conditioning Cruise control: Yes Electric windows: Yes Air-sprung seat: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Bed: Yes Tachograph: Yes Additional information: 2+1 seats Registration certificate: Yes, present Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of conformity Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 07/06/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	100€




	2	<p>Brand: Kuiper Model: KPRO 0000 54 Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 13/12/2011 Semi-trailer category: O4: max. mass >10000kg Semi-trailer type: Market semi-trailer Chassis number: XL9PL545111090338 Number of axles: 1 Maximum Permissible Mass (kg): 11000 Exterior colour: White Trailer registration certificate: Yes, present Trailer certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of conformity Inspection certificate: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: brake line right rear defective, needs to be repaired before it can drive. Condition: Used Quantity: 1</p>	100€
	3	<p>Make: MAN Model: TGX Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 01/08/2012 Fuel: Diesel Odometer reading (km's): 582904 Chassis number: WMA45XZZ2DW175613 Number of keys: 2 Category: N3: max. mass >12t. Truck type: Swap system Number of axles: 3 Maximum Permissible Mass (kg): 25700 Transmission: Automatic transmission Cylinder capacity cc: 10518 Engine power kW: 324 Emission class: Euro 5</p>	1.000€





		<p>Exterior colour: White Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Cruise control: Yes Electric windows: Yes Air-sprung seat: Yes Multifunctional steering wheel: Yes Radio: Yes Bed: Yes Tachograph: Yes Additional information: equipped with Dhollandia tail lift vehicle not subject to the obligation to be in possession of COC Registration certificate: Yes, present Certificate of conformity: Not present, see additional information Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 11/02/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	4	<p>Brand: IVECO Model: 35-140 Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 28/06/2017 Fuel: Diesel Odometer reading (km's): 134726 Chassis number: ZCFCD35A60D586158 Number of keys: 1+1 Vehicle category: N1: max. mass <3.5t. Body: furniture van Number of seats: 2+1 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Automatic transmission</p>	1.000€




		<p>Cylinder capacity cc: 2287 Engine power kW: 100 Emission class: Euro 6b Exterior colour: White Interior colour: Black/blue Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Electric windows: Yes Multifunction steering wheel: Yes Radio: Yes Other options: Heated side mirror Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 08/01/2025 Visible vehicle damage: Yes, For a detailed overview of the visible damage, you can always consult the photo report. Vehicle damage description: Problem with injector</p> <p>Condition: Used Quantity: 1</p>	
	5	<p>Quantity: 1 Product category: Furniture box Brand: Baetens Dimensions mm (LxWxH): 7830x2550x2850 Accessories: Equipped with 4 metal legs Weight category: more than 1,000 kg Condition: Used Location: Lichtnast</p>	500€





	6	<p>Brand: De Breucker Model: KS F24 Year of construction (yyyy): 2004 First registration (dd/mm/yyyy): 15/12/2004 Trailer category: O4: max. mass >10000kg Trailer type: Closed trailer Chassis number: WAFKSF24X4K028084 Maximum Permissible Mass (kg): 38000 Internal dimensions (L x W x H) in mm: unknown Trailer registration certificate: Yes, present Trailer conformity certificate: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 17/12/2024 Number of axles: 3 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: chassis is bent, accident Condition: Used Quantity: 1</p>	250€
	7	<p>Brand: KRONE Model: Sd Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 20/07/2022 Trailer category: O4: max. mass >10000kg Trailer type: Closed trailer Chassis number: WKESD000001073468 Maximum permissible mass (kg): 41000 Internal dimensions (L x W x H) in mm: 13000x2460x2700 Trailer registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Trailer conformity certificate: Yes, available Identification report: Yes, available Inspection certificate: Not available Number of axles: 3 Visible vehicle damage: Yes, for a detailed</p>	100€




		<p>overview of the visible damage you can always consult the photo report. Vehicle damage description: Damage to right flank Condition: Used Quantity: 1</p>	
	8	<p>Make: Iveco Model: Eurocargo Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 30/11/2011 Fuel: Diesel Odometer reading (km's): 282829 Chassis number: ZCFA1EG1402587179 Number of keys: 2+2 Category: N2: max. mass >3.5t. - <12t. Number of axles: 2 Maximum Permissible Mass (kg): 11990 Transmission: Automatic transmission Cylinder capacity cc: 5880 Engine power kW: 160 Exterior colour: White Interior colour: Grey Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Air-sprung seat: Yes Radio: Yes Bed: Yes Tachograph: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 17/09/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Number: 1</p>	1.000€




	9	<p>Brand: Chereau Model: CSD2 Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 19/03/2018 Trailer category: O4: max. mass >10000kg Trailer type: Refrigerated trailer Chassis number: VM4CSD20000A114091 Maximum Permissible Mass (kg): 25000 Internal dimensions (L x W x H) in mm: 11225 Additional information: equipped with Dhollandia DH SM30 tail lift, max 2000Kg refrigeration unit: Carrier Vector 1350 Tridec equipped with steering axle Trailer registration certificate: Yes, available Trailer conformity certificate: Yes, available Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 28/01/2025 Number of axles: 2 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Number: 1</p>	1.000€
	10	<p>Make: Renault Year of construction (yyyy): 2006 First registration (dd/mm/yyyy): 04/07/2006 Fuel: Diesel Odometer reading (km's): 708636 Chassis number: VF644AEA000004846 Number of keys: 3 Category: N3: max. mass >12t. Number of axles: 2 Length (meters): 8500 Maximum Permissible Mass (kg): 16000 Transmission: Manual transmission Cylinder capacity cc: 4116 Engine power kW: 128 Emission class: Euro 3 Exterior color: Red</p>	1€




		<p>Interior color: Gray Upholstery: Fabric Air-sprung seat: Yes Radio: Yes Tachograph: Yes Additional information: Equipped with tailgate, does not open Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 11/07/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	31	<p>Make: MAN Model: TGL Version: 8.180 Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 19/09/2012 Fuel: Diesel Odometer reading (km's): 631634 Chassis number: WMAN13ZZ1DY289275 Number of keys: 1 Category: N2: max. mass >3.5t. - <12t. Truck type: Full combination Maximum Permissible Mass (kg): 8800kg Transmission: Manual transmission Cylinder capacity cc: 4580 Engine power kW: 162 Emission class: Euro 5 Exterior colour: White Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Radio: Yes Tachograph: No Registration certificate: Not present: the buyer</p>	100€




		<p>will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 29/06/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Number: 1</p>	
	34	<p>Brand: Mercedes-Benz Model: Atego Version: 1022 L/10.5 Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 08/06/2011 Fuel: Diesel Odometer reading (km's): 734521 Chassis number: WDB9702471L569856 Number of keys: 2 Category: N2: max. mass >3.5t. - <12t. Truck type: Box truck Number of axles: 2 Maximum Permissible Mass (kg): 10500 Transmission: Manual transmission Cylinder capacity cc: 4801 Engine power kW: 160 Emission class: Euro 5 Exterior colour: White Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Cruise control: Yes Electric windows: Yes Tachograph: No Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available</p>	100€




		<p>Inspection certificate valid until (dd/mm/yyyy):: 29/12/2024 Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Loading bridge does not open Condition: Used Quantity: 1</p>	
	37	<p>Brand: VOLVO Model: FLB3C Year of construction (yyyy): 2014 First registration (dd/mm/yyyy): 01-04-2014 Fuel: Diesel Odometer reading (km's): 526297 on 15-05-2024 Chassis number: YV2TN12A1EB679739 Number of keys: 2 Category: N3: max. mass >12t. Number of axles: 2 Maximum Permissible Mass (kg): 16000 Transmission: Manual transmission Cylinder capacity cc: 7146 Engine power kW: 181 Emission class: Euro 5 Exterior colour: White Interior colour: Grey Upholstery: Fabric Radio: Yes Tachograph: No Additional information: does not start! Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 15-05-2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used</p>	100€




		Number: 1	
	39	<p>Brand: Renault Model: Premium Version: 380 EEV Year of construction (yyyy): 2010 First registration (dd/mm/yyyy): 04/10/2010 Fuel: Diesel Odometer reading (km's): 982358 Chassis number: VF624GPD000002253 Number of keys: 1 Category: N3: max. mass >12t. Tractor type: Standard tractor Number of axles: 2 Maximum Permissible Mass (kg): 19000 Transmission: Automatic transmission Cylinder capacity cc: 10837 Engine power kW: 286 Emission class: Euro 5 Exterior colour: White Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Cruise control: Yes Electric windows: Yes Radio: Yes Other options: tachograph Spare wheel Additional information: Vehicle does not start or drive! Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 17/02/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Vehicle does not start or drive - parts missing!</p>	100€



		Condition: Used Quantity: 1	
	42	Brand: VOLVO Model: FLH42 18 Year of construction (yyyy): 2008 First registration (dd/mm/yyyy): 09-06-2008 Fuel: Diesel Odometer reading (km's): 1052190 Chassis number: YV2TBM0A68B520085 Number of keys: 1 Category: N3: max. mass >12t. Truck type: Truck Number of axles: 2 Maximum Permissible Mass (kg): 18000 Transmission: Manual transmission Cylinder capacity cc: 7146 Engine power kW: 177 Emission class: Euro 4 Exterior colour: Red Interior colour: Grey Upholstery: Fabric Electric windows: Yes Radio: Yes Tachograph: No Additional information: equipped with tachograph and loading bridge D'HOLLANDIA DHLSU11, year of manufacture: 2008, max cap: 2000kg Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 15-01-2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	1.000€



	43	<p>Make: RENAULT Model: 180 dci Year of construction (yyyy): 2006 First registration (dd/mm/yyyy): 04-07-2006 Fuel: Diesel Odometer reading (km's): 387101 Chassis number: VF644AEA000004922 Number of keys: 1 Category: N3: max. mass >12t. Truck type: Truck Number of axles: 2 Maximum Permissible Mass (kg): 16000 Transmission: Manual transmission Cylinder capacity cc: 4116 Engine power kW: 128 Emission class: Euro 3 Exterior colour: Red Interior colour: Grey Upholstery: Fabric Electric windows: Yes Radio: Yes Tachograph: Yes Additional information: 3-seater and loading bridge D'HOLLANDIA DHLSU11, max cap: 2000kg, year of manufacture: 2006 Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 27-06-2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Doors do not lock and loading bridge does not open start with booster Condition: Used Quantity: 1</p>	1.000€
---	----	---	--------