

## CATALOG

### Commercial vehicles



#### DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

#### START

10 april 2025 to 08:00 [UTC]

#### END DATE

17 april 2025 from 16:00 [UTC]

#### VIEWING

- Wednesday April 16 2025 from 15:00 until 17:00  
Helststraat 47, 2630 Aartselaar

#### AUCTIM PARTNER

##### MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium  
+32 3 827 21 31 - info.moyersoens@auctim.be  
BTW BE 0452 153 622

#### ISSUE - COLLECTION

- Wednesday April 23 2025 from 10:00 until 12:00  
Helststraat 47, 2630 Aartselaar


**Online bidding only!**

Catalog created on 17 april 2025 to 04:04

#### AUCTIM - MOYERSOEN NV

Helststraat 47  
2630 Aartselaar, Belgium  
VAT BE 0452 153 622

**www.auctim.com**  
info.moyersoens@auctim.be

	Item	Description	Start price
	161	<p>Make: Citroën  Model: Berlingo  Year of construction (yyyy): 2011  First registration (dd/mm/yyyy): 14/01/2011  Fuel: Diesel  Odometer reading (km's): 199177  Chassis number: VF7GB9HWCAN531950  Number of keys: 1  Vehicle category: N1: max. mass &lt;3.5t.  Body: Panel van  Number of seats: 3  Number of axles: 2  Maximum Permissible Mass (kg): 1730  Transmission: Manual transmission  Cylinder capacity cc: 1560  Engine power kW: 55  Emission class: Euro 4  Exterior colour: White  Metallic colour: No  Interior colour: Black  Upholstery: Fabric  Radio: Yes  Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate  Certificate of conformity: Yes, present  CARPASS: Yes, present  Identification report: Yes, present  Inspection certificate: Yes, present  Inspection certificate valid until (dd/mm/yyyy):: 08/02/2025  Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages  Condition: Used  Quantity: 1</p>	100€




165


Make: Ford  
Model: Transit  
Year of manufacture (yyyy): 2016  
First registration (dd/mm/yyyy): 07/10/2016  
Fuel: Diesel  
Odometer reading (km's): 197338  
Chassis number: WF0XXXTTGXGA35063  
Number of keys: 1  
Vehicle category: N1: max. mass <3.5t.  
Body: Panel van  
Number of seats: 3  
Number of axles: 2  
Maximum Permissible Mass (kg): 2900  
Transmission: Manual transmission  
Cylinder capacity cc: 2198  
Engine power kW: 92  
Emission class: Euro 5b  
Exterior colour: White  
Metallic colour: No  
Interior colour: Black  
Upholstery: Fabric  
Air conditioning: Manual air conditioning  
Central locking: Yes  
Cruise control: Yes  
Electric folding mirrors: Yes  
Electric windows: Yes  
Multifunction steering wheel: Yes  
Radio: Yes  
Other options: equipped loading space  
Additional information: including remaining contents  
Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate  
Certificate of conformity: Not available: the buyer will receive a certificate of loss of certificate of conformity  
Identification report: Yes, present  
Inspection certificate: Yes, present  
Inspection certificate valid until (dd/mm/yyyy):: 11/10/2024  
Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.  
Vehicle damage description: various damages

100€




		Condition: Used Quantity: 1	
	168	<p>Make: Opel Model: Vivaro Year of construction (yyyy): 2014 First registration (dd/mm/yyyy): 09/12/2014 Fuel: Diesel Odometer reading (km's): 133634 Chassis number: W0L4F7002FS010854 Number of keys: 1 Vehicle category: N1: max. mass &lt;3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 2740 Transmission: Manual transmission Cylinder capacity cc: 1598 Engine power kW: 66 Emission class: Euro 5b Exterior colour: Red Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Radio: Yes Other options: including remaining contents equipped loading space Additional information: battery defective - start and drive with booster! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 13/01/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always</p>	100€




		<p>consult the photo report. Vehicle damage description: battery defective - start and drive with booster! dashboard notifications Condition: Used Quantity: 1</p>	
	174	<p>Make: Opel Model: Vivaro Year of construction (yyyy): 2015 First registration (dd/mm/yyyy): 24/07/2015 Fuel: Diesel Odometer reading (km's): 157164 Chassis number: W0L4F7002FV645329 Number of keys: 1 Vehicle category: N1: max. mass &lt;3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 2740 Transmission: Manual transmission Cylinder capacity cc: 1598 Engine power kW: 66 Emission class: Euro 5b Exterior colour: Red Metallic colour: No Interior colour: Black Upholstery: Fabric Central locking: Yes Electric windows: Yes Radio: Yes Other options: Including remaining contents equipped loading space Additional information: Battery defective - vehicle only starts and drives with booster! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy)::</p>	100€




		23/10/2024 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Battery defect - vehicle only starts and drives with booster! dashboard notifications Condition: Used Quantity: 1	
	258	Brand: Maxus Model: EV 80 Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 24/12/2020 Fuel: Electric Odometer reading (km's): 45259 Chassis number: LSH14J4C3LA057181 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Automatic transmission Engine power kW: 92 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Electric windows: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Additional information: start with booster! Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present	100€



		<p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p> <p>Vehicle damage description: start with booster! various damages!</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	260	<p>Brand: Maxus</p> <p>Model: eDeliver3</p> <p>Year of manufacture (yyyy): 2020</p> <p>First registration (dd/mm/yyyy): 24/12/2020</p> <p>Fuel: Electric</p> <p>Odometer reading (km's): 46878</p> <p>Chassis number: LSH14C4CXLA079920</p> <p>Number of keys: 2</p> <p>Vehicle category: N1: max. mass &lt;3.5t.</p> <p>Body: Panel van</p> <p>Number of seats: 2</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 2460</p> <p>Transmission: Automatic transmission</p> <p>Engine power kW: 90</p> <p>Exterior colour: White</p> <p>Metallic colour: No</p> <p>Interior colour: Black</p> <p>Upholstery: Fabric</p> <p>Reversing camera: Yes</p> <p>Air conditioning: Manual air conditioning</p> <p>Trip computer: Yes</p> <p>Central locking: Yes</p> <p>Cruise control: Yes</p> <p>Electric windows: Yes</p> <p>Multifunction steering wheel: Yes</p> <p>Rear parking sensors: Yes</p> <p>Radio: Yes</p> <p>Other options: spare wheel</p> <p>Additional information: starting with booster!</p> <p>Registration certificate: Yes, present</p> <p>Certificate of conformity: Yes, present</p> <p>Identification report: Yes, present</p>	100€







		<p>Inspection certificate: Yes, present  Inspection certificate valid until (dd/mm/yyyy)::  17/03/2025  Maintenance booklet: Not present  Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.  Vehicle damage description: start with booster! various damages!  center console loose  Condition: Used  Quantity: 1</p>	
	261	<p>Brand: Maxus  Model: eDeliver3  Year of manufacture (yyyy): 2020  First registration (dd/mm/yyyy): 24/12/2020  Fuel: Electric  Odometer reading (km's): 24103  Chassis number: LSH14C4C7LA079969  Number of keys: 1  Vehicle category: N1: max. mass &lt;3.5t.  Body: Panel van  Number of seats: 2  Number of axles: 2  Maximum Permissible Mass (kg): 2630  Transmission: Automatic transmission  Engine power kW: 90  Exterior colour: White  Metallic colour: No  Interior colour: Black  Upholstery: Fabric  Reversing camera: Yes  Air conditioning: Manual air conditioning  Trip computer: Yes  Central locking: Yes  Cruise control: Yes  Electric windows: Yes  Multifunction steering wheel: Yes  Rear parking sensors: Yes  Radio: Yes  Additional information: start with booster!</p>	100€





		<p>Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 04/03/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! various damages Condition: Used Quantity: 1</p>	
	262	<p>Brand: Maxus Model: eDeliver3 Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 24/12/2020 Fuel: Electric Odometer reading (km's): 27004 Chassis number: LSH14C4C8LA080001 Number of keys: 1 Vehicle category: N1: max. mass &lt;3.5t. Body: Panel van Number of seats: 2 Number of axles: 2 Maximum Permissible Mass (kg): 2630 Transmission: Automatic transmission Engine power kW: 90 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes</p>	100€



		<p>Radio: Yes Additional information: start with booster!</p> <p>Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 16/03/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! various damages! Condition: Used Quantity: 1</p>	
	270	<p>Brand: Maxus Model: eDeliver3 Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 24/12/2020 Fuel: Electric Odometer reading (km's): 31788 Chassis number: LSH14C4CXLA079951 Number of keys: 2 Vehicle category: N1: max. mass &lt;3.5t. Body: Panel van Number of seats: 2 Number of axles: 2 Maximum Permissible Mass (kg): 2630 Transmission: Automatic transmission Engine power kW: 90 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes</p>	100€



		<p>Electric windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Other options: spare wheel Additional information: starting with booster! Registration certificate: Yes, present Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! various damages Condition: Used Quantity: 1</p>	
--	--	---	--