

## **CATALOG**Passenger cars







**DESCRIPTION** 

Auction of passenger cars from various bankruptcies, seizures, breaches of contract, end of leasing, etc.

**START** 

23 april 2025 to 08:00 [UTC]

**END DATE** 

30 april 2025 from 17:00 [UTC]

**VIEWING** 

• ---

Wednesday April 30 2025 from 15:00 until 17:00 Helststraat 47, 2630 Aartselaar

• --

Wednesday May 07 2025 from 10:00 until 12:00 Helststraat 47, 2630 Aartselaar

**AUCTIM PARTNER** 

## **MOYERSOEN NV**

Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622

**ISSUE - COLLECTION** 

## Online bidding only!

Catalog created on 30 april 2025 to 04:03

**AUCTIM** - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622  $\begin{tabular}{ll} www.auctim.com \\ info.moyersoen@auctim.be \\ \end{tabular}$ 



Ite	Description	Start price
	Brand: Ford Model: Focus Year of construction (yyyy): 2006 First registration (dd/mm/yyyy): 06/03/2006 Fuel: Petrol Odometer reading (km's): 83344 Chassis number: WF05XXGCD56Y21636 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 5-door Transmission: Automatic transmission Emission class: Euro 4 Exterior colour: Green Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Radio: Yes Additional information: start with booster! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! engine to be checked Condition: Used Quantity: 1	100€





67 Brand: Citroën

Model: C5 Aircross Hybrid

Version: Shine

Year of construction (yyyy): 2022

First registration (dd/mm/yyyy): 29/03/2022

Fuel: Hybrid - Electric/Petrol

Odometer reading (km's): 794487

Chassis number: VR7A4DGZSNL003585

Number of keys: 2

Vehicle category: M1: passenger car

Vehicle type: Berline Number of doors: 5-door

Transmission: Automatic transmission

Cylinder capacity cc: 1598 Engine power kW: 133

Emission class: Euro 6d-TEMP

Exterior colour: Grey Metallic colour: Yes Interior colour: Black Upholstery: Full leather Reversing camera: Yes

Air conditioning: Fully automatic air conditioning

On-board computer: Yes Central locking: Yes Cruise control: Yes

Electric folding mirrors: Yes

Electric tailgate: Yes Electric windows: Yes Electric seats: Yes LED lighting: Yes Alloy rims: Yes Massage seats: Yes Fog lights: Yes

Multifunction steering wheel: Yes

Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes

Radio: Yes

Seat heating: Yes

Equipped with electric charging cable: Present Other options: electric seats with memory

function DAB tuner

Registration certificate: Not present: the buyer

**AUCTIM** - MOYERSOEN NV

**www.auctim.com** info.moyersoen@auctim.be

100€



will receive a certificate of loss of registration

certificate

Certificate of conformity: Yes, present

CARPASS: Yes, present

Inspection certificate: Yes, present

Inspection certificate valid until (dd/mm/yyyy)::

29/03/2026

Maintenance booklet: Not present

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always

consult the photo report.

Condition: Used Quantity: 1



68 Brand: Fiat 100€

Model: 500 X

Version: 1.0 T3 Cross

Year of construction (yyyy): 2023

First registration (dd/mm/yyyy): 21/11/2023

Fuel: Petrol

Odometer reading (km's): 24462

Chassis number: ZFANF2D36NP989352

Number of keys: 2

Vehicle category: M1: passenger car

Vehicle type: Berline Number of doors: 5-door

Transmission: Manual transmission

Cylinder capacity cc: 999 Engine power kW: 88

Emission class: Euro 6d-TEMP

Exterior colour: Grey

Specific factory colour: Grigio Moda

Metallic colour: No Interior colour: Black Upholstery: Partial leather Reversing camera: Yes

Air conditioning: Fully automatic air conditioning

On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes LED lighting: Yes

**AUCTIM** - MOYERSOEN NV

www.auctim.com info.moyersoen@auctim.be



Alloy rims: Yes Fog lights: Yes

Multifunctional steering wheel: Yes

Rear parking sensors: Yes

Radio: Yes

Other options: DAB tuner

Registration certificate: Not available: the buyer will receive a certificate of loss of registration

certificate

Certificate of conformity: Yes, available Inspection certificate: Yes, available

Inspection certificate valid until (dd/mm/yyyy)::

21/11/2027

Maintenance booklet: Not available

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always

consult the photo report.

Condition: Used Quantity: 1



103 Brand: BMW

Model: X1

Version: sDrive 16D

Year of construction (yyyy): 2017

First registration (dd/mm/yyyy): 05/09/2017

Fuel: Diesel

Odometer reading (km's): 172084 Chassis number: WBAHT510205|70219

Number of keys: 2

Vehicle category: M1: passenger car

Vehicle type: SUV or 4x4 Number of doors: 5-door

Transmission: Manual transmission

Cylinder capacity cc: 1496
Engine power kW: 85
Emission class: Euro 6b
Exterior colour: Grey
Metallic colour: No
Interior colour: Black
Upholstery: Leatherette

Air conditioning: Fully automatic airco

On-board computer: Yes

**AUCTIM** - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622 **www.auctim.com** info.moyersoen@auctim.be

5/6

100€



Central locking: Yes Cruise control: Yes Electric tailgate: Yes Electric windows: Yes

Fog lights: Yes

Multifunction steering wheel: Yes

Navigation: Yes

Rear parking sensors: Yes Front parking sensors: Yes

Radio: Yes

Registration certificate: Yes, present Certificate of conformity: Yes, present

CARPASS: Yes, present

Inspection certificate: Yes, present

Inspection certificate valid until (dd/mm/yyyy)::

06/09/2025

Maintenance booklet: Not present

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always

consult the photo report.

Condition: Used Quantity: 1