

CATALOG

Commercial vehicles



DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

15 may 2025 to 08:00 [UTC]

END DATE

22 may 2025 from 16:00 [UTC]

VIEWING

- ---
Wednesday May 21 2025 from 15:00 until 17:00
Helststraat 47, 2630 Aartselaar

AUCTIM PARTNER

MOYERSOEN NV
Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoens@auctim.be
BTW BE 0452 153 622

ISSUE - COLLECTION

- ---
Wednesday May 28 2025 from 10:00 until 12:00
Helststraat 47, 2630 Aartselaar

Online bidding only!

Catalog created on 19 may 2025 to 04:06



	Item	Description	Start price
	29	Brand: IFOR WILLIAMS Model: 2SB Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 13-06-2018 Trailer category: O2: max. mass >750kg - <3500kg Trailer type: Closed trailer Chassis number: SCKD00000J0738082 Maximum Permissible Mass (kg): 3500 Internal dimensions (L x W x H) in mm: 3650 x 1770 Additional information: equipped with 1 door, ramp, wooden floor and support posts length of driving plates: 2100mm total dimensions: 2300 x 5500 x 2630mm Trailer registration certificate: Yes, present Trailer certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 21-06-2024 Number of axles: 2 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Number: 1	750€
	102	Brand: Nissan Model: NV 400 Version: F33.13 refrigerated truck Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 27/03/2012 Fuel: Diesel Odometer reading (km's): 69729 Chassis number: VNVM1FCDC46305660 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Refrigerated van Number of seats: 3	100€



		Number of axles: 2 Maximum Permissible Mass (kg): 3300 Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 92 Emission class: Euro 5 Co2 emissions gr/km: 221 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Radio: Yes Tow bar: Yes Other options: Equipped with Carrier cooling/freezing unit Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 03/04/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: side door handle missing, various damages! Condition: Used Quantity: 1	
	107	Brand: Mercedes-Benz Model: eVito Version: 112 L3 Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 10/11/2022 Fuel: Electric Odometer reading (km's): 83075 Chassis number: W1V44760514174405	100€



Number of keys: 2
Vehicle category: N1: max. mass <3.5t.
Body: Panel van
Number of seats: 3
Number of axles: 2
Maximum Permissible Mass (kg): 3200
Transmission: Automatic transmission
Engine power kW: 85
Exterior colour: Black
Metallic colour: No
Interior colour: Black
Upholstery: Full leather
Reversing camera: Yes
Air conditioning: Manual air conditioning
On-board computer: Yes
Central locking: Yes
Electric windows: Yes
Alloy rims: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Seat heating: Yes
Equipped with electric charging cable: Present
Other options: DAB tuner
Registration certificate: Yes, present
Certificate of conformity: Yes, present
Identification report: Yes, present
Inspection certificate: Yes, present
Inspection certificate valid until (dd/mm/yyyy)::
15/11/2024
Maintenance booklet: Not present
Visible vehicle damage: Yes, for a detailed
overview of the visible damage you can always
consult the photo report.
Invoice amount (€ incl. VAT): 63342.77
Invoice date (dd-mm-yyyy): 30/11/2022
Condition: Used
Quantity: 1



109

Brand: Renault
Model: Trafic
Year of construction (yyyy): 2022
First registration (dd/mm/yyyy): 20/01/2023
Fuel: Diesel
Odometer reading (km's): 43432
Chassis number: VF1FL000X70126974
Number of keys: 1
Vehicle category: N1: max. mass <3.5t.
Body: Panel van
Number of seats: 3
Number of axles: 2
Maximum Permissible Mass (kg): 3070
Transmission: Automatic transmission
Cylinder capacity cc: 1997
Engine power kW: 110
Emission class: Euro 6d-TEMP
Exterior colour: White
Metallic colour: No
Interior colour: Black
Upholstery: Fabric
Reversing camera: Yes
Air conditioning: Manual air conditioning
On-board computer: Yes
Central locking: Yes
Cruise control: Yes
Electric windows: Yes
Multifunction steering wheel: Yes
Rear parking sensors: Yes
Radio: Yes
Tow bar: Yes
Other options: DAB tuner
Registration certificate: Yes, present
Certificate of conformity: Yes, present
Inspection certificate: No present
Maintenance booklet: Not present
Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.
Vehicle damage description: side + star in the windshield
Condition: Used
Quantity: 1

100€



	416	Make: Citroën Model: Berlingo Version: refrigerated truck Year of construction (yyyy): 2007 First registration (dd/mm/yyyy): 12/06/2007 Fuel: Diesel Odometer reading (km's): 161224 Chassis number: VF7GCRHYB94300120 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Refrigerated van Number of seats: 2 Number of axles: 2 Maximum Permissible Mass (kg): 1990 Transmission: Manual transmission Cylinder capacity cc: 1997 Engine power kW: 66 Emission class: Euro 3 Exterior colour: White Metallic colour: No Interior colour: Grey Upholstery: Fabric Central locking: Yes Radio: Yes Tow bar: Yes Other options: equipped with Gradius cooling/freezing unit and insulating doors. Additional information: rear door does not open Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle Damage Description: Back Door Won't Open Driver's Seat Condition: Used Quantity: 1	100€
---	-----	---	------



	420	Brand: Opel Model: Combo Version: Cargo Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 28/02/2020 Fuel: Diesel Odometer reading (km's): 83903 Chassis number: W0VEFYHWCLJ583054 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 2000 Transmission: Manual transmission Cylinder capacity cc: 1499 Engine power kW: 56 Emission class: Euro 6 Exterior colour: Black Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Radio: Yes Tow bar: Yes Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 14/01/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: holes seat + side Condition: Used	100€
---	-----	---	------



		Quantity: 1	
	430	Brand: Opel Model: Movano Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 14/03/2022 Fuel: Diesel Odometer reading (km's): 52522 Chassis number: VXEYCAPFB12U52647 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2179 Engine power kW: 88 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Other options: DAB tuner Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 21/03/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always	100€



		consult the photo report. Vehicle damage description: message dashboard engine Condition: Used Quantity: 1	
	432	Brand: Opel Model: Vivaro Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 04/04/2022 Fuel: Diesel Odometer reading (km's): 83787 Chassis number: VXEVFEHZ7MZ122076 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: van with crew cab Number of seats: 5 Number of axles: 2 Maximum Permissible Mass (kg): 3100 Transmission: Automatic transmission Cylinder capacity cc: 1997 Engine power kW: 130 Emission class: Euro 6d-TEMP Exterior colour: Grey Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Semi-automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Shift paddles: Yes Tow bar: Yes Other options: double cabin Registration certificate: Yes, present	100€



		Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 11/04/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	
	434	Brand: Citroën Model: Jumper Year of construction (yyyy): 2007 First registration (dd/mm/yyyy): 19/12/2007 Fuel: Diesel Odometer reading (km's): 251975 Chassis number: VF7YBBMFB11299247 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3300 Transmission: Manual transmission Cylinder capacity cc: 2198 Engine power kW: 88 Emission class: Euro 4 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Other options: Equipped with cooling compartment with Thermoking cooling unit Additional information: start with booster! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate	100€



		Certificate of conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 30/01/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! Various damages + engine problem! Condition: Used Quantity: 1	
--	--	--	--