

CATALOG

Commercial vehicles



DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

12 june 2025 to 08:00 [UTC]

END DATE

19 june 2025 from 16:00 [UTC]

VIEWING

- Wednesday June 11 2025 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoens@auctim.be
BTW BE 0452 153 622

ISSUE - COLLECTION

- Wednesday June 25 2025 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47

Online bidding only!

Catalog created on 19 june 2025 to 04:02

AUCTIM - MOYERSOEN NV


Helststraat 47
2630 Aartselaar, Belgium
VAT BE 0452 153 622

www.auctim.com
info.moyersoens@auctim.be





	Item	Description	Start price
	118	<p>Brand: Renault Model: Master Version: L3H2 Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 17/10/2022 Fuel: Diesel Odometer reading (km's): 50883 Chassis number: VF6MF000669411285 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 132 Emission class: Euro 6d-TEMP Exterior colour: White Metallic colour: No Interior colour: Grey Upholstery: Leatherette Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: Equipped with roof rack, ladder and fitted loading space BOA constructor.</p> <p>Tails with booster! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 31/08/2022</p>	100€




		<p>Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Tails with booster! star windshield Condition: Used Quantity: 1</p>	
	119	<p>Brand: Renault Model: Master Version: L3H2 Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 05/05/2023 Fuel: Diesel Odometer reading (km's): 43327 Chassis number: VF6MF000670227339 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 120 Emission class: Euro 6 Co2 emissions gr/km: 368 Exterior colour: White Metallic colour: No Interior colour: Grey Upholstery: Leatherette Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: equipped loading space</p>	100€




		<p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate</p> <p>Certificate of conformity: Yes, present</p> <p>Inspection certificate: Not present</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p> <p>Vehicle damage description: perform maintenance various damages</p> <p>Condition: Used</p> <p>Number: 1</p>	
	120	<p>Brand: Renault</p> <p>Model: Master</p> <p>Version: L3H2</p> <p>Year of construction (yyyy): 2022</p> <p>First registration (dd/mm/yyyy): 15/09/2022</p> <p>Fuel: Diesel</p> <p>Odometer reading (km's): 40103</p> <p>Chassis number: VF6M000569400407</p> <p>Number of keys: 3</p> <p>Vehicle category: N1: max. mass <3.5t.</p> <p>Body: Panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 3500</p> <p>Transmission: Manual transmission</p> <p>Cylinder capacity cc: 2299</p> <p>Engine power kW: 132</p> <p>Emission class: Euro 6d-TEMP</p> <p>Exterior colour: White</p> <p>Metallic colour: No</p> <p>Interior colour: Grey</p> <p>Upholstery: Artificial leather</p> <p>Reversing camera: Yes</p> <p>Air conditioning: Fully automatic air conditioning</p> <p>On-board computer: Yes</p> <p>Central locking: Yes</p> <p>Cruise control: Yes</p> <p>Electric windows: Yes</p>	100€

		<p>Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Other options: equipped with roof rack, ladder, side door lock and fitted loading space BOA constructor.</p> <p>Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate</p> <p>Certificate of conformity: Yes, present</p> <p>Inspection certificate: Not present</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p> <p>Condition: Used</p> <p>Number: 1</p>	
	122	<p>Brand: Mercedes-Benz Model: Sprinter Version: 311 CDI Year of construction (yyyy): 2009 First registration (dd/mm/yyyy): 25/09/2009 Fuel: Diesel Odometer reading (km's): 241518 Chassis number: WDB9066331S401069 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2148</p>	100€




		<p>Engine power kW: 80 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 17/04/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages Condition: Used Quantity: 1</p>	
	123	<p>Brand: BW Trailers Model: 02T Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 01/06/2022 Trailer category: O2: max. weight >750kg - <3500kg Trailer type: Tipper Chassis number: YB83500KBT2285456 Maximum Permissible Mass (kg): 3500 Internal dimensions (L x W x H) in mm: 3350x1840 Additional information: Equipped with electric tipping function and front rack. Trailer registration certificate: Yes, available Trailer conformity certificate: Yes, available Identification report: Yes, available Inspection certificate: Yes, available</p>	100€




		<p>Inspection certificate valid until (dd/mm/yyyy):: 20/06/2024 Number of axles: 2 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Number: 1</p>	
	200	<p>Brand: Volkswagen Model: Crafter Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 25/10/2022 Fuel: Diesel Odometer reading (km's): 92175 Chassis number: WV1ZZZSYZN9049249 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 1968 Engine power kW: 130 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Electric windows: Yes Rear parking sensors: Yes Radio: Yes Other options: DAB tuner Additional information: start with booster! Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present</p>	100€




		<p>Inspection certificate valid until (dd/mm/yyyy):: 28/10/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Oil service and inspection required driver and passenger seat side mirror Condition: Used Quantity: 1</p>	
	201	<p>Brand: Mercedes-Benz Model: Sprinter Version: 315 CDI L3 Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 03/01/2023 Fuel: Diesel Odometer reading (km's): 88572 Chassis number: W1V9076351P532087 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 1950 Engine power kW: 110 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Electric windows: Yes Fog lights: Yes Multifunction steering wheel: Yes</p>	100€




		<p>Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: DAB tuner Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 05/01/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages driver's seat Condition: Used Number: 1</p>	
	202	<p>Brand: Volkswagen Model: Crafter Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 24/10/2022 Fuel: Diesel Odometer reading (km's): 113600 Chassis number: WV1ZZZSY8N9049735 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 1968 Engine power kW: 130 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning</p>	100€




		<p>On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 28/10/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: driver's seat Condition: Used Quantity: 1</p>	
	214	<p>Brand: Peugeot Model: Expert Version: BlueHDI L3 Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 04/10/2021 Fuel: Diesel Odometer reading (km's): 97680 Chassis number: VF3VFAHKKM7842295 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3100 Transmission: Manual transmission Cylinder capacity cc: 1997 Engine power kW: 90 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black</p>	100€




		<p>Upholstery: Partial leather Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Other options: equipped loading space Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 04/08/2024 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	216	<p>Brand: Fiat Model: Ducato Version: 150 Multijet Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 04/01/2012 Fuel: Diesel Odometer reading (km's): 254884 Chassis number: ZFA25000002123037 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3300</p>	100€




		<p>Transmission: Manual transmission Cylinder capacity cc: 2287 Engine power kW: 109 Emission class: Euro 5 Co2 emissions gr/km: 189 Exterior colour: White Metallic colour: No Interior colour: black/red Upholstery: Fabric Central locking: Yes Electric windows: Yes Radio: Yes Tow bar: Yes Other options: equipped with locks, ladder, roof rack Alurack and equipped loading space. Additional information: Clutch/gearbox defective! Vehicle starts but does not drive! Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 11/01/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Clutch/gearbox defective! Vehicle starts but does not drive! Condition: Used Quantity: 1</p>	
	217	<p>Make: Renault Model: Master Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 18/04/2016 Fuel: Diesel Odometer reading (km's): 210393 Chassis number: VF1MAFCRC55259104 Number of keys: 0 Vehicle category: N1: max. mass <3.5t. Body: Panel van</p>	100€




		<p>Number of seats: 3 Number of axles: 2 Transmission: Manual transmission Cylinder capacity cc: 2300 Emission class: Euro 5 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Electric windows: Yes Radio: Yes Tow bar: Yes Additional information: no key present!! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of conformity CARPASS: Yes, present Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: no key present!! various damages! Condition: Used Quantity: 1</p>	
	220	<p>Brand: Fuso Model: Canter Version: 3S13 Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 06/04/2022 Fuel: Diesel Odometer reading (km's): unknown Chassis number: TYBFEA01CLDC15366 Number of keys: 0 Category: N1: max. mass <3.5t. Truck type: Moving lift on truck Number of axles: 2</p>	100€




		<p>Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2998 Engine power kW: 96 Emission class: Euro 6 Exterior colour: White Interior colour: Black Upholstery: Fabric Tachograph: No Other options: equipped with ladder lift Böcker 30/1-7LH, year of construction 2022, serial number: 43984, capacity: 400kg, maximum height: 30m, odometer reading: 1507h. equipped with support legs and yellow PVC material case. Additional information: no key present! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 15/08/2023 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: no key present! Condition: Used Quantity: 1</p>	
	221	<p>Brand: Klaas Model: Toplight 21 Year of construction (yyyy): 2021 Trailer category: O1: max. mass <750kg Trailer type: Ladder lift Chassis number: W09A21175M1KC8012 Maximum Permissible Mass (kg): 750 Internal dimensions (L x W x H) in mm: N/A Additional information: Capacity: 200kg Maximum height: 21m S/N: 2100882</p>	100€





		<p>Inspection certificate: Not applicable Number of axles: 1 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	222	<p>Brand: Citroën Model: Jumpy Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 14/02/2022 Fuel: Diesel Odometer reading (km's): 37145 Chassis number: VF7VBHVM7867041 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 2695 Transmission: Manual transmission Cylinder capacity cc: 1499 Engine power kW: 88 Emission class: Euro 6 Exterior colour: Grey Metallic colour: No Interior colour: Black Upholstery: Partial leather Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Rear parking sensors: Yes Radio: Yes Other options: equipped loading space Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present</p>	100€




		<p>Inspection certificate valid until (dd/mm/yyyy):: 14/03/2025</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: No, except general wear and tear. (General wear and tear includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	223	<p>Brand: Citroën</p> <p>Model: Berlingo</p> <p>Year of construction (yyyy): 2022</p> <p>First registration (dd/mm/yyyy): 19/09/2022</p> <p>Fuel: Petrol</p> <p>Odometer reading (km's): 12353</p> <p>Chassis number: VR7EUHNP2NJ614664</p> <p>Number of keys: 2</p> <p>Vehicle category: N1: max. mass <3.5t.</p> <p>Body: Panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 1960</p> <p>Transmission: Manual transmission</p> <p>Cylinder capacity cc: 1199</p> <p>Engine power kW: 81</p> <p>Emission class: Euro 6</p> <p>Exterior colour: Grey</p> <p>Metallic colour: No</p> <p>Interior colour: Black</p> <p>Upholstery: Fabric</p> <p>Air conditioning: Manual air conditioning</p> <p>On-board computer: Yes</p> <p>Central locking: Yes</p> <p>Cruise control: Yes</p> <p>Electric folding mirrors: Yes</p> <p>Electric windows: Yes</p> <p>Rear parking sensors: Yes</p> <p>Radio: Yes</p> <p>Other options: equipped loading space</p> <p>Registration certificate: Yes, present</p>	100€




		<p>Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid to (dd/mm/yyyy):: 29/11/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	225	<p>Brand: Renault Model: Master Version: Grand Confort L2H2 - 121FT Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 17/02/2021 Fuel: Diesel Odometer reading (km's): 142924 Chassis number: VF1VA000866311327 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 107 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Other options: equipped with France Elévateur 121FT aerial platform, max. working height: 12m. equipped with locks. Additional information: Vehicle does not start!</p> <p>Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present</p>	100€

		<p>Inspection certificate valid until (dd/mm/yyyy):: 22/02/2025</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p> <p>Vehicle damage description: Vehicle does not start!</p> <p>Various damages: parts in the cabin.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	226	<p>Brand: Renault</p> <p>Model: Master</p> <p>Version: L3</p> <p>Year of construction (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 07/10/2021</p> <p>Fuel: Diesel</p> <p>Odometer reading (km's): 94988</p> <p>Chassis number: VF6VG000167297631</p> <p>Number of keys: 0</p> <p>Vehicle category: N1: max. mass <3.5t.</p> <p>Body: Box truck</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Transmission: Manual transmission</p> <p>Exterior colour: White</p> <p>Metallic colour: No</p> <p>Interior colour: Black</p> <p>Upholstery: Fabric</p> <p>Air conditioning: Manual air conditioning</p> <p>Central locking: Yes</p> <p>Cruise control: Yes</p> <p>Electric windows: Yes</p> <p>Multifunctional steering wheel: Yes</p> <p>Radio: Yes</p> <p>Other options: equipped with D'Hollandia tailgate</p> <p>Additional information: no key available! no on-board documents available!</p> <p>Vehicle is sold as a wreck, without certificates of</p>	100€

		<p>loss!</p> <p>Registration certificate: Not available, see additional information</p> <p>Certificate of conformity: Not available, see additional information</p> <p>Inspection certificate: Not available</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: no key present!</p> <p>no on-board documents present!</p> <p>various damages - engine operation unknown!</p> <p>Vehicle is sold as wreck, without certificates of loss!</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	227	<p>Brand: Mercedes-Benz</p> <p>Model: Citan</p> <p>Version: 110 CDI</p> <p>Year of construction (yyyy): 2023</p> <p>First registration (dd/mm/yyyy): 11/04/2023</p> <p>Fuel: Diesel</p> <p>Odometer reading (km's): 104951</p> <p>Chassis number: W1V4206231U328008</p> <p>Number of keys: 2</p> <p>Vehicle category: N1: max. mass <3.5t.</p> <p>Body: Panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 2021</p> <p>Transmission: Manual transmission</p> <p>Cylinder capacity cc: 1461</p> <p>Engine power kW: 70</p> <p>Emission class: Euro 6</p> <p>Exterior colour: White</p> <p>Metallic colour: No</p> <p>Interior colour: Black</p> <p>Upholstery: Fabric</p> <p>Air conditioning: Manual air conditioning</p>	100€



		<p>On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Other options: DAB tuner Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid to (dd/mm/yyyy):: 13/04/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	228	<p>Brand: Mercedes-Benz Model: Citan Version: 110 CDI Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 11/04/2023 Fuel: Diesel Odometer reading (km's): 76680 Chassis number: W1V4206231U320201 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 2021 Transmission: Manual transmission Cylinder capacity cc: 1461 Engine power kW: 70 Emission class: Euro 6 Exterior colour: White Metallic colour: No</p>	100€



		<p>Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Other options: DAB tuner Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 13/04/2025 Maintenance booklet: Not present Visible vehicle damage: No, except general wear and tear. (General wear and tear includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. Condition: Used Quantity: 1</p>	
--	--	---	--