

CATALOGCommercial vehicles







DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

26 june 2025 to 08:00 [UTC]

END DATE

3 july 2025 from 16:00 [UTC]

VIEWING

• ---

Wednesday July 02 2025 from 15:00 until 17:00 BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622

ISSUE - COLLECTION

• ---

Wednesday July 09 2025 from 10:00 until 12:00 BE-2630 Aartselaar, Helststraat 47

Online bidding only!

Catalog created on 3 july 2025 to 04:00



Item	Description	Start price
234	Brand: Chevrolet Model: Silverado Version: Cheyenne High Country Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 20/02/2022 Fuel: LPG + petrol Odometer reading (km's): 2134 engine hours Chassis number: 3GCUY9ELNG117594 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Pick-Up Truck Number of axles: 2 Maximum Permissible Mass (kg): 3221 Transmission: Automatic transmission Cylinder capacity cc: 6200 Engine power kW: 313 Number of doors: 4-door Exterior colour: White Metallic colour: No Interior colour: Brown Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Electric windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Rear parking sensors: Yes Rear parking sensors: Yes Seat ventilation: Yes Tow bar: Yes Other options: steering wheel heating electric seats with memory function BOSE sound system	100€



Additional information: Mileage not visible: 2134

engine hours.

Registration certificate: Yes, present Certificate of conformity: Yes, present

CARPASS: Yes, present

Identification report: Yes, present Inspection certificate: Yes, present

Inspection certificate valid until (dd/mm/yyyy)::

10/05/2023

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always

consult the photo report.

Vehicle damage description: rear window missing

Condition: Used Quantity: 1



254 Brand: Volkswagen

Model: Crafter Version: TDI

Year of construction (yyyy): 2016

First registration (dd/mm/yyyy): 12/05/2016

Fuel: Diesel

Odometer reading (km's): 308194

Chassis number: WV1ZZZ2EZG6034459

Number of keys: 2

Vehicle category: N1: max. mass <3.5t.

Body: Panel van Number of seats: 3 Number of axles: 2

Maximum Permissible Mass (kg): 3500 Transmission: Manual transmission

Cylinder capacity cc: 1968
Engine power kW: 120
Emission class: Euro 5b
Exterior colour: Grey
Metallic colour: No
Interior colour: Black
Upholstery: Fabric
Reversing camera: Yes

Air conditioning: Fully automatic air conditioning

Central locking: Yes Cruise control: Yes

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622 **www.auctim.com** info.moyersoen@auctim.be

3/8

100€



Electric windows: Yes

Multifunction steering wheel: Yes

Radio: Yes Tow bar: Yes

Other options: equipped loading space

Registration certificate: Not present: the buyer will receive a certificate of loss of registration

certificate

Certificate of conformity: Yes, present

CARPASS: Yes, present

Identification report: Yes, present Inspection certificate: Yes, present

Inspection certificate valid until (dd/mm/yyyy)::

25/04/2025

Maintenance booklet: Not present

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always

consult the photo report.

Vehicle damage description: star in the windshield

Condition: Used Quantity: 1



258 Brand: Fiat

Model: New E-Doblo Version: L1 Heavy 50Kwh

Year of construction (yyyy): 2022

First registration (dd/mm/yyyy): 18/12/2022

Fuel: Electric

Read odometer reading (km's): unknown Chassis number: VYFEAZKXZNJ741226

Number of keys: 0

Vehicle category: N1: max. mass <3.5t.

Construction: Panel van Number of seats: 3 Number of axles: 2

Transmission: Automatic transmission

Exterior colour: Grey Metallic colour: No Interior colour: Black Upholstery: Fabric

Additional information: no key present!

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622 **www.auctim.com** info.moyersoen@auctim.be

100€



vehicle is locked

Registration certificate: Not present: the buyer will receive a certificate of loss of registration

certificate

Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of

conformity

Inspection certificate: Not present Maintenance booklet: Not present

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always

consult the photo report.

Vehicle damage description: No key present! Vehicle has been standing still for a long time, battery has not been charged for a long time.

Condition: Used Quantity: 1



260 Brand: Meclean

Model: Traileriet-L 350/18

Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): N/A Trailer type: High-pressure trailer

Chassis number: TI0577-20

Internal dimensions (L x W x H) in mm:

2050x1360x1700

Additional information: Power: 19kW

Pressure: 350 bar

No key available! Operation unknown.

Inspection certificate: Not available

Number of axles: 1

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage

description: various damages

Invoice amount (€ incl. VAT): 13208.40 Invoice date (dd-mm-yyyy): 06-04-2020

Condition: Used Quantity: 1

AUCTIM - MOYERSOEN NV

Helststraat 47 2630 Aartselaar, Belgium VAT BE 0452 153 622 **www.auctim.com** info.moyersoen@auctim.be

100€





277 Brand: Mercedes-Benz 100€

Model: Citan

Version: 110 CDI Fourgon L1 PRO Year of construction (yyyy): 2023

First registration (dd/mm/yyyy): 11/04/2023

Fuel: Diesel

Odometer reading (km's): 87659

Chassis number: W1VTBACZ6PU337257

Number of keys: 2

Vehicle category: N1: max. mass <3.5t.

Body: Panel van Number of seats: 3 Number of axles: 2

Maximum Permissible Mass (kg): 2021 Transmission: Manual transmission

Cylinder capacity cc: 1461
Engine power kW: 70
Emission class: Euro 6
Exterior colour: White
Metallic colour: No
Interior colour: Black
Upholstery: Fabric

Air conditioning: Manual air conditioning

On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes

Fog lights: Yes

Multifunction steering wheel: Yes

Navigation: Yes Radio: Yes

Other options: DAB tuner

Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present

Inspection certificate valid to (dd/mm/yyyy)::

13/04/2025

Maintenance booklet: Not present

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always

consult the photo report.

AUCTIM - MOYERSOEN NV

www.auctim.com info.moyersoen@auctim.be



Vehicle damage description: cracked windshield

Condition: Used Quantity: 1



297 Brand: Renault 100€

Model: Master Version: dci 100

Year of construction (yyyy): 2006

First registration (dd/mm/yyyy): 07/06/2006

Fuel: Diesel

Odometer reading (km's): unknown Chassis number: VF1FDBVH535836019

Number of kevs: 0

Vehicle category: N1: max. mass <3.5t.

Construction: Panel van Number of seats: 3 Number of axles: 2

Transmission: Manual transmission

Exterior colour: White Metallic colour: No Interior colour: Grey Upholstery: Fabric Electric windows: Yes

Radio: Yes Tow bar: Yes

Other options: equipped with cooling

compartment with Carrier cooling - operation

unprecedented!

Additional information: no key present!

Registration certificate: Not present: the buyer will receive a certificate of loss of registration

certificate

Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of

conformity

Inspection certificate: Not present Maintenance booklet: Not present

Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always

consult the photo report.

Description of vehicle damage: no key present!

Condition: Used



	Quantity: 1	