

CATALOG

Passenger cars



DESCRIPTION

Auction of passenger cars from various bankruptcies, seizures, breaches of contract, end of leasing, etc.

START

3 july 2025 to 08:00 [UTC]

END DATE

10 july 2025 from 17:00 [UTC]

VIEWING

- Wednesday July 09 2025 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
 +32 3 827 21 31 - info.moyersoens@auctim.be
 BTW BE 0452 153 622


ISSUE - COLLECTION

- Wednesday July 16 2025 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47


Online bidding only!

Catalog created on 10 july 2025 to 04:02




	Item	Description	Start price
	116	<p>Brand: Opel Model: Corsa-e Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 16/06/2022 Fuel: Electric Odometer reading (km): 54454 Chassis number: VXKUHZKXZM4323903 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 5-door Transmission: Automatic transmission Engine power kW: 100 Emission class: Euro 6 Exterior colour: Grey Metallic colour: Yes Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Alloy rims: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Equipped with electric charging cable: Present Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	100€




	163	<p>Brand: Hyundai Model: Kona Version: Hybrid Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 17/06/2021 Fuel: Hybrid - Electric/Petrol Odometer reading (km's): 63116 Chassis number: KMHK581EGLU049576 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1580 Engine power kW: 77 Emission class: Euro 6d-TEMP Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Electric seats: Yes Head up display: Yes Alloy rims: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Open roof: Yes Rear parking sensors: Yes Radio: Yes Shift paddles: Yes Seat ventilation: Yes Seat heating: Yes Other options: steering wheel heating Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Not available</p>	100€
-----------------------------------------------------------------------------------	-----	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------




		<p>Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used</p> <p>Quantity: 1</p>	
	249	<p>Brand: Opel Model: Insignia Version: Sports Tourer SW Year of construction (yyyy): 2013 First registration (dd/mm/yyyy): 23/01/2013 Fuel: Diesel Odometer reading (km's): 182256 Chassis number: W0LGM8EL5D1056826 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Estate / station wagon Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1956 Engine power kW: 96 Emission class: Euro 5 Exterior colour: Black Metallic colour: No Interior colour: Grey Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Fog lights: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes</p>	100€




		<p>Tow bar: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 13/01/2016 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	250	<p>Brand: Peugeot Model: 208 Version: Style Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 06/06/2016 Fuel: Diesel Odometer reading (km's): 169455 Chassis number: VF3CCBHW6GT127105 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 5-door Transmission: Manual transmission Cylinder capacity cc: 1560 Engine power kW: 55 Emission class: Euro 6b Exterior colour: Blue Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Multifunctional steering wheel: Yes</p>	100€




		<p>Navigation: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 10/05/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: maintenance report Condition: Used Number: 1</p>	
	253	<p>Brand: Jeep Model: Compass Version: MX Year of construction (yyyy): 2018 First registration (dd/mm/yyyy): 04/03/2019 Fuel: Petrol Odometer reading (km's): 92481 Chassis number: 3C4NJDCH4KT589023 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1368 Engine power kW: 125 Emission class: Euro 6d-TEMP Exterior colour: Grey Metallic colour: Yes Interior colour: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes</p>	100€




		<p>Electric windows: Yes Electric seats: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: Beats sound system Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 05/04/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	255	<p>Brand: BMW Model: 418d Version: Grancoupé Year of construction (yyyy): 2016 First registration (dd/mm/yyyy): 30/11/2016 Fuel: Diesel Odometer reading (km's): 163475 Chassis number: WBA4E71090G746946 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Berline Number of doors: 5-door Transmission: Automatic transmission Emission class: Euro 6b Exterior colour: Black Metallic colour: No Interior colour: Black Upholstery: Full leather Air conditioning: Fully automatic air conditioning</p>	100€



		<p> Trip computer: Yes Central locking: Yes Cruise control: Yes Electric tailgate: Yes Electric windows: Yes Alloy rims: Yes Multifunctional steering wheel: Yes Radio: Yes Seat heating: Yes Additional information: start with booster! Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Conformity certificate: Not available: the buyer will receive a certificate of loss of conformity certificate Inspection certificate: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! vehicle to be checked various damages Condition: Used Number: 1 </p>	
	261	<p> Brand: Peugeot Model: 3008 Version: GT Pack Hybrid Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 27/10/2022 Fuel: Hybrid - Electric/Petrol Odometer reading (km's): 47136 Chassis number: VF3M4DGZUNS133150 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1598 Engine power kW: 133 Emission class: Euro 6d-TEMP </p>	100€




		<p>Exterior colour: Black Specific factory colour: Perla Nera Metallic colour: Yes Colour interior: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sport seats: Yes Seat heating: Yes Other options: GT Pack Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Invoice amount (€ incl. VAT): 50348.71 Invoice date (dd-mm-yyyy): 03/10/2022 Condition: Used Quantity: 1</p>	
	262	<p>Brand: Tesla Model: Model Y Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 23/11/2023 Fuel: Electric</p>	100€




Odometer reading (km's): 77041
Chassis number: XP7YGCE51RB273083
Number of keys: 2
Vehicle category: M1: passenger car
Vehicle type: Berline
Number of doors: 5-door
Transmission: Automatic transmission
Engine power kW: 220
Exterior colour: White
Metallic colour: No
Interior colour: Black
Upholstery: Full leather
Reversing camera: Yes
Air conditioning: Fully automatic air conditioning
On-board computer: Yes
Central locking: Yes
Cruise control: Yes
Electric folding mirrors: Yes
Electric windows: Yes
Electric seats: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Seat heating: Yes
Equipped with electric charging cable: Present
Other options: Autopilot
Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate
Certificate of conformity: Yes, present
Identification report: Yes, present
Inspection certificate: Yes, present
Inspection certificate valid until (dd/mm/yyyy):: 23/11/2027
Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.
Vehicle damage description: various damages: side mirror, rim and front.
Condition: Used
Quantity: 1




	266	<p>Brand: Mercedes-Benz Model: C 180 Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 10/07/2022 Fuel: Petrol Odometer reading (km's): 53533 Chassis number: W1K2060411R004251 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Berline Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1496 Engine power kW: 125 Emission class: Euro 6d-TEMP Exterior colour: Grey Metallic colour: Yes Interior colour: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes LED lighting: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sport seats: Yes Seat heating: Yes Other options: sound system DAB tuner</p>	100€
-----------------------------------------------------------------------------------	-----	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	------




		<p>Registration certificate: Yes, present Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of conformity Inspection certificate: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult photo report. Condition: Used Quantity: 1</p>	
	267	<p>Brand: Toyota Model: Rav 4 Version: 2.5 Hybrid Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 13/03/2023 Fuel: Hybrid - Electric/Petrol Odometer reading (km's): 37057 Chassis number: JTMW53F80J022760 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 2487 Engine power kW: 131 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Grey Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes</p>	100€



		<p>Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 13/03/2027 Visible vehicle damage: No, except general usage damage. (General usage damage includes all damage that may be expected given the age and mileage or hours.) For a detailed overview, you can always consult the photo report. Condition: Used Quantity: 1</p>	
	280	<p>Brand: Volkswagen Model: T-Roc Version: Active 1.5 TSI DSG Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 21/12/2021 Fuel: Petrol Odometer reading (km's): 37684 Chassis number: WVGZZZA1ZNV056491 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1498 Engine power kW: 110 Emission class: Euro 6 Exterior colour: Blue Metallic colour: Yes Interior colour: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes</p>	100€



		<p>Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat heating: Yes Other options: DAB tuner Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 09/04/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: side wall damage Condition: Used Quantity: 1</p>	
	440	<p>Brand: Fiat Model: Stilo Year of construction (yyyy): 2003 First registration (dd/mm/yyyy): 23/06/2003 Fuel: Petrol Odometer reading (km's): 159308 Chassis number: ZFA19200000319067 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 3-door Transmission: Manual transmission Cylinder capacity cc: 1596 Engine power kW: 76 Emission class: Euro 4 Exterior colour: Green Metallic colour: No</p>	100€



		<p>Central locking: Yes Electric windows: Yes Radio: Yes Additional information: Battery empty, starting with booster Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
--	--	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--