

CATALOG

Commercial vehicles



DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

10 july 2025 to 08:00 [UTC]

END DATE

17 july 2025 from 16:00 [UTC]

VIEWING

- (no data)

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoens@auctim.be
BTW BE 0452 153 622

ISSUE - COLLECTION

- (no data)

Online bidding only!

Catalog created on 10 july 2025 to 04:08

AUCTIM - MOYERSOEN NV

Helststraat 47
2630 Aartselaar, Belgium
VAT BE 0452 153 622

www.auctim.com
info.moyersoens@auctim.be



	Item	Description	Start price
	268	Brand: Mercedes-Benz Model: Vito Version: 114CDI Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 24/03/2023 Fuel: Diesel Odometer reading (km's): 83883 Chassis number: W1VVKBEZ0P4195581 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 2800 Transmission: Manual transmission Cylinder capacity cc: 1950 Engine power kW: 100 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 30/03/2026 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.	100€



		Vehicle damage description: star in the windshield Condition: Used Quantity: 1	
	269	Brand: Mercedes-Benz Model: Citan Version: 110 CDI Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 11/04/2023 Fuel: Diesel Odometer reading (km's): 63350 Chassis number: W1VTBACZ4PU337256 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 2 Number of axles: 2 Maximum Permissible Mass (kg): 2021 Transmission: Manual transmission Cylinder capacity cc: 1461 Engine power kW: 70 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 13/04/2026 Visible vehicle damage: Yes, for a detailed	100€



		overview of the visible damage you can always consult the photo report. Vehicle damage description: windshield cracked Condition: Used Quantity: 1	
	270	Brand: Mercedes-Benz Model: Vito Version: 114 CDI Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 24/03/2023 Fuel: Diesel Odometer reading (km's): 67617 Chassis number: W1VVKBEZ0P4195290 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 2800 Transmission: Manual transmission Cylinder capacity cc: 1950 Engine power kW: 100 Emission class: Euro 6d-TEMP Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Additional information: Infotainment system screen defective! Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present	100€



		Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 29/03/2026 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: Infotainment system screen defective! various damages Condition: Used Quantity: 1	
	272	Brand: Iveco Model: Daily Version: 35-180 Hi-Matic Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 31/10/2022 Fuel: Diesel Odometer reading (km's): 21864 Chassis number: ZCFC535C1P5513704 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Automatic transmission Cylinder capacity cc: 2998 Engine power kW: 129 Exterior colour: Silver Metallic colour: Yes Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes	100€



		Tow bar: Yes Other options: DAB tuner Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid to (dd/mm/yyyy):: 07/03/22025 Maintenance booklet: Not present Visible vehicle damage: No, except general wear and tear. (General wear and tear includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report. Condition: Used Quantity: 1	
	274	Brand: Peugeot Model: Partner Version: 1.5 BlueHDI L2 Premium Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 29/04/2021 Fuel: Diesel Odometer reading (km's): 67076 Chassis number: VR3EFYHYCLN544043 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Transmission: Manual transmission Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Semi-automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunction steering wheel: Yes	100€



		Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Not available: the buyer will receive a certificate of loss of certificate of conformity Inspection certificate: Not available Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	
	281	Brand: Mercedes-Benz Model: Sprinter Version: 317 CDI L3 Year of construction (yyyy): 2021 First registration (dd/mm/yyyy): 09/12/2021 Fuel: Diesel Odometer reading (km's): 62210 Chassis number: W1V9076351P421131 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Automatic transmission Cylinder capacity cc: 1950 Engine power kW: 125 Emission class: Euro 6 Exterior colour: Black Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Fully automatic air conditioning	100€



		Trip computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Tow bar: Yes Seat heating: Yes Other options: DAB Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 14/12/2023 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	
	285	Brand: Renault Model: Trafic Version: Confort L2H1 Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 21/11/2023 Fuel: Diesel Odometer reading (km's): 58639 Chassis number: VF1FL000371757124 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: van with double cabin Number of seats: 6 Number of axles: 2 Maximum Permissible Mass (kg): 3070	100€



		Transmission: Manual transmission Cylinder capacity cc: 1997 Engine power kW: 110 Emission class: Euro 6 Co2 emissions gr/km: 189 Exterior colour: Grey Metallic colour: Yes Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 31/03/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	
	288	Make: Volkswagen Model: Transporter Year of construction (yyyy): 2010 First registration (dd/mm/yyyy): 12/03/2010 Fuel: Diesel	100€



		Odometer reading (km's): 356418 Chassis number: WV1ZZZ7HZA228171 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3200 Transmission: Manual transmission Cylinder capacity cc: 1968 Engine power kW: 103 Emission class: Euro 5 Exterior colour: Black Metallic colour: No Interior colour: Grey Upholstery: Partial leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Electric windows: Yes Navigation: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 12/08/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	
	297	Brand: Renault Model: Master Version: dci 100 Year of construction (yyyy): 2006 First registration (dd/mm/yyyy): 07/06/2006 Fuel: Diesel Odometer reading (km's): unknown	100€



		Chassis number: VF1FDBVH535836019 Number of keys: 0 Vehicle category: N1: max. mass <3.5t. Construction: Panel van Number of seats: 3 Number of axles: 2 Transmission: Manual transmission Exterior colour: White Metallic colour: No Interior colour: Grey Upholstery: Fabric Electric windows: Yes Radio: Yes Tow bar: Yes Other options: equipped with cooling compartment with Carrier cooling - operation unprecedented! Additional information: no key present! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Description of vehicle damage: no key present! Condition: Used Quantity: 1	
	300	Brand: Iveco Model: Daily Version: 3.0 EEV Year of construction (yyyy): 2011 First registration (dd/mm/yyyy): 18/03/2011 Fuel: Diesel Odometer reading (km's): unknown Chassis number: ZCFC35A3105858710 Number of keys: 0	100€



		Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Transmission: Automatic transmission Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Cruise control: Yes Electric windows: Yes Radio: Yes Other options: equipped with Carrier cooling unit (operation unknown) Additional information: no key present! Mileage unknown Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: no key present! mileage unknown function unknown Condition: Used Quantity: 1	
	304	Brand: Maxus Model: eDeliver3 Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 24/12/2020 Fuel: Electric Odometer reading (km's): 59741 Chassis number: LSH14C4C8LA080015 Number of keys: 2 Vehicle category: N1: max. mass <3.5t.	100€



		Body: Panel van Number of seats: 2 Number of axles: 2 Maximum Permissible Mass (kg): 2630 Transmission: Automatic transmission Engine power kW: 90 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Additional information: start with booster! Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 02/03/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! various damages Condition: Used Quantity: 1	
	308	Brand: Maxus Model: EV 80 Year of construction (yyyy): 2020 First registration (dd/mm/yyyy): 24/12/2020 Fuel: Electric Odometer reading (km's): 52594 Chassis number: LSH14J4C5LA057182 Number of keys: 2	100€



		Vehicle category: N1: max. mass <3.5t. Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Mass (kg): 3500 Transmission: Automatic transmission Engine power kW: 92 Exterior colour: White Metallic colour: No Interior colour: Grey Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Electric windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 10/03/2025 Maintenance booklet: No present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: various damages + rust formation! Condition: Used Quantity: 1	
	312	Brand: Opel Model: Movano Version: open loading platform Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 05/06/2023 Fuel: Diesel Odometer reading (km's): 55634 Chassis number: VXEYDCPGC12W43555	100€



Number of keys: 1
Vehicle category: N1: max. mass <3.5t.
Body: van with open loading platform
Number of seats: 7
Number of axles: 2
Maximum Permissible Mass (kg): 3500
Transmission: Manual transmission
Cylinder capacity cc: 2179
Engine power kW: 121
Emission class: Euro 6
Exterior colour: White
Metallic colour: No
Interior colour: Black
Upholstery: Fabric
Air conditioning: Manual air conditioning
Central locking: Yes
Cruise control: Yes
Electric windows: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Radio: Yes
Tow bar: Yes
Other options: double cabin

Registration certificate: Yes, present
Certificate of conformity: Yes, present
CARPASS: Yes, present
Identification report: Yes, present
Inspection certificate: Yes, present
Inspection certificate valid until (dd/mm/yyyy)::
22/04/2026
Maintenance booklet: Not present
Visible vehicle damage: Yes, for a detailed
overview of the visible damage you can always
consult the photo report.
Vehicle damage description: broken glass lights
Condition: Used
Quantity: 1