



CATALOG
Passenger cars



DESCRIPTION

Auction of passenger cars from various bankruptcies, seizures, breaches of contract, end of leasing, etc.

START

10 July 2025 to 08:00 [UTC]

END DATE

17 July 2025 from 17:00 [UTC]

VIEWING

- ---
Wednesday July 16 2025 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622


ISSUE - COLLECTION

- ---
Wednesday July 23 2025 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47


Online bidding only!

Catalog created on 10 July 2025 to 04:08




	Item	Description	Start price
	235	Brand: Citroën Model: C4 Version: 1.5 BlueHDI 130 S Year of construction (yyyy): 2024 First registration (dd/mm/yyyy): 12/06/2024 Fuel: Diesel Odometer reading (km's): 25401 Chassis number: VR7BBYHZ5RE032640 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Berline Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1499 Engine power kW: 96 Emission class: Euro 6 Exterior colour: White Specific factory colour: Okenite White Metallic colour: No Interior colour: Grey Upholstery: Partial leather Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 12/06/2028 Visible vehicle damage: No, except general usage damage. (General usage damage includes all damage that may be expected given the age and	100€




		<p>the mileage or hours.) For a detailed overview, you can always consult the photo report. Condition: Used Quantity: 1</p>	
	236	<p>Brand: Citroën Model: C4 Version: 1.5 BlueHDi 130 S Year of construction (yyyy): 2024 First registration (dd/mm/yyyy): 17/06/2024 Fuel: Diesel Odometer reading (km's): 52932 Chassis number: VR7BBYHZ7RE032641 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Berline Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1499 Engine power kW: 96 Emission class: Euro 6 Exterior colour: White Specific factory colour: Okenite White Metallic colour: No Interior colour: Grey Upholstery: Partial leather Reversing camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Shift paddles: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate</p>	100€




		<p>Certificate of conformity: Yes, available CARPASS: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 17/06/2028 Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	242	<p>Brand: Nissan Model: Qashqai Year of construction (yyyy): 2015 First registration (dd/mm/yyyy): 25/03/2015 Fuel: Diesel Odometer reading (km's): 104416 Chassis number: SJNFDAJ11U1333727 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1598 Engine power kW: 96 Emission class: Euro 5b Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Sun roof: Yes</p>	100€




		<p>Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Seat heating: Yes Additional information: starting with booster! Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 11/10/2022 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: start with booster! Condition: Used Quantity: 1</p>	
	284	<p>Brand: Mini Model: Countryman Cooper Version: D Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 18/08/2017 Fuel: Diesel Odometer reading (km's): 105467 Chassis number: WMWYT910503D93022 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Berline Number of doors: 5-door Transmission: Manual transmission Cylinder capacity cc: 1995 Engine power kW: 110 Emission class: Euro 6b Exterior colour: Black Metallic colour: No Interior colour: Brown Upholstery: Full leather</p>	100€



		<p>Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Head up display: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 18/08/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	291	<p>Brand: Volkswagen Model: Jetta Year of construction (yyyy): 2012 First registration (dd/mm/yyyy): 27/09/2012 Fuel: Diesel Odometer reading (km's): 247835 Chassis number: WVVZZZ16ZDM007884 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Berline Number of doors: 5-door Transmission: Manual transmission Cylinder capacity cc: 1968 Engine power kW: 103</p>	100€




		<p>Emission class: Euro 5 Co2 emissions gr/km: 126 Exterior colour: Black Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 13/06/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
	293	<p>Brand: BMW Model: X5 Version: xDrive 45e Year of construction (yyyy): 2022 First registration (dd/mm/yyyy): 28/10/2022 Fuel: Hybrid - Electric/Petrol Odometer reading (km's): 64553 Chassis number: WBATA610X09N02910 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 2998 Engine power kW: 210 Emission class: Euro 6</p>	100€




		<p>Exterior colour: Grey Specific factory colour: Arktikgrau Brillanteffekt Metallic colour: Yes Colour interior: Black Upholstery: Full leather Reversing camera: Yes Trip computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Head up display: Yes LED lighting: Yes Alloy rims: Yes Massage seats: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports package: Yes Seat ventilation: Yes Tow bar: Yes Seat heating: Yes Equipped with electric charging cable: Present Other options: electrically folding tow bar electric seats with memory function M-package 22" black alloy wheels rear sun blinds Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that may be expected given the age and the mileage or hours.) For a detailed overview, you can always consult the photo report.</p>	
--	--	---	--




		Vehicle damage description: reversing camera defective Condition: Used Number: 1	
	301	Brand: Peugeot Model: Partner Version: Tepee Year of construction (yyyy): 2009 First registration (dd/mm/yyyy): 22/12/2009 Fuel: Diesel Odometer reading (km's): 101732 Chassis number: VF37J9HTC9J302483 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Estate / station wagon Number of doors: 5-door Transmission: Manual transmission Cylinder capacity cc: 1560 Engine power kW: 55 Emission class: Euro 4 Co2 emissions gr/km: 149 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Fabric Air conditioning: Manual airco Central locking: Yes Electric windows: Yes Radio: Yes Other options: Double cabin: 5 seats Additional information: Passenger car M1! Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 01/04/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1	100€




	302	<p>Brand: Volkswagen Model: Kombi Version: TDI Bluemotion Year of construction (yyyy): 2015 First registration (dd/mm/yyyy): 26/06/2015 Fuel: Diesel Odometer reading (km's): 222964 Chassis number: WV2ZZZ7HZFH102664 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1968 Engine power kW: 132 Emission class: Euro 5 Exterior colour: White Metallic colour: No Interior colour: Grey Upholstery: Full leather Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Additional information: Passenger car M1! Registration certificate: Yes, present Certificate of conformity: Yes, present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Vehicle damage description: rust formation Condition: Used Number: 1</p>	100€
---	-----	---	------



	303	<p>Brand: Volkswagen Model: Kombi Version: 4 Motion Year of construction (yyyy): 2019 First registration (dd/mm/yyyy): 07/04/2020 Fuel: Diesel Odometer reading (km's): 255951 Chassis number: WV2ZZZ7HZKH171407 Number of keys: 4 Vehicle category: M1: passenger car Vehicle type: Monovolume Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 1968 Engine power kW: 146 Emission class: Euro 6 Exterior colour: White Metallic colour: No Interior colour: Black Upholstery: Full leather Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunctional steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Number: 1</p>	100€
---	-----	--	------



	307	<p>Brand: Land Rover Model: Range Rover Sport Version: Autobiography Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 16/06/2023 Fuel: Hybrid - Electric/Petrol Odometer reading (km's): 96446 Chassis number: SAL1A2B47PA131906 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic transmission Cylinder capacity cc: 2996 Engine power kW: 375 Emission class: Euro 6 Exterior colour: Black Specific factory colour: Santorini Black Metallic colour: Yes Interior colour: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Head up display: Yes LED lighting: Yes Alloy rims: Yes Massage seats: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports package: Yes Seat ventilation: Yes</p>	100€
---	-----	--	------



		<p>Tow bar: Yes Seat heating: Yes Equipped with electric charging cable: Present Other options: Electric folding tow bar Electric seats with memory function Meridian Soundsystem 23" black alloy rims rear sun blinds Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 13/12/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report. Condition: Used Quantity: 1</p>	
--	--	--	--