

CATALOG

Commercial vehicles



DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

4 september 2025 to 08:00 [UTC]

END DATE

11 september 2025 from 16:00 [UTC]

VIEWING

- Wednesday September 10 2025 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
 +32 3 827 21 31 - info.moyersoens@auctim.be
 BTW BE 0452 153 622

ISSUE - COLLECTION

- Wednesday September 17 2025 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47

Online bidding only!


Catalog created on 9 september 2025 to 04:11

AUCTIM - MOYERSOEN NV


Helststraat 47
 2630 Aartselaar, Belgium
 VAT BE 0452 153 622

www.auctim.com
 info.moyersoens@auctim.be



	Item	Description	Start price
	5	<p>Make: Mercedes-Benz Model: Sprinter Version: 315 CDI L2 with aerial platform</p> <p>Year of manufacture (yyyy): 2024</p> <p>First registration (dd/mm/yyyy): 31/10/2024</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 4091 Chassis number: W1V3HBFZ7PP543315 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Aerial work platform Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 1950 Engine power (kW): 110 Emission class: Euro 6 Exterior color: White</p> <p>Metallic paint: No Interior color: Black Upholstery: Leatherette Reversing camera: Yes Trip computer: Yes Central locking: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: Equipped with a mounted Versalift VTL-140-F aerial work platform with serial number VTL39G-22402, manufactured in 2023, mileage: 36 hours.</p>	100€



		<p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 07/01/2025</p> <p>Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that may be expected given the vehicle's age and mileage or hours.) For a detailed overview, please consult the photo report.</p> <p>Invoice amount (€ incl. VAT): 116039 Invoice date (dd/mm/yyyy): 31/10/2024</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	7	<p>Make: Ford Model: Ranger</p> <p>Version: Double Cab Wildtrak 2.0 Ecoblue 4WD Year of manufacture (yyyy): 2023</p> <p>First registration (dd/mm/yyyy): 12/01/2024</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 44,553 Chassis number: 6FPPXXMJ2PPJ00990 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Pick-up truck Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3230 Transmission: Automatic Engine capacity (cc): 1996 Engine power (kW): 150</p>	100€




Emission class: Euro 6
CO2 emissions (g/km): 234
Number of doors: 5-door
Exterior color: Gray

Metallic body: Yes


Interior color: Black

Upholstery: Partial leather
Reversing camera: Yes
Air conditioning: Fully automatic climate control
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power folding mirrors: Yes
Power windows: Yes
Power seats: Yes
LED lighting: Yes
Alloy wheels: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Tow bar: Yes
Seat heating: Yes
Other options: Equipped with LED bars
Dometic Front Runner roof rack
Electric roller shutter
Double cab
Heated steering wheel
DAB tuner
B&O sound system
Additional information: Equipped with ceramic coating
Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate
Certificate of Conformity: Yes, available
CARPASS: Yes, available
Identification report: Yes, available
Inspection certificate: Yes, available
Inspection certificate valid until (dd/mm/yyyy):



		<p>23/06/2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that might be expected given the age and mileage or hours of use.) For a detailed overview, please consult the photo report.</p> <p>Invoice amount (€ incl. VAT): €63,659.39</p> <p>Invoice date (dd/mm/yyyy): 17/01/2024</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	20	<p>Make: Opel</p> <p>Model: Combo</p> <p>Year of manufacture (yyyy): 2019</p> <p>First registration (dd/mm/yyyy): 22/02/2019</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 274316</p> <p>Chassis number: W0VEFBHWBKJ531095</p> <p>Number of keys: 2</p> <p>Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Permitted Gross Vehicle Weight (kg): 1970</p> <p>Transmission: Manual transmission</p> <p>Engine capacity (cc): 1560</p> <p>Engine power (kW): 55</p> <p>Emission class: Euro 6b</p> <p>Exterior color: White</p> <p>Metallic body: No</p> <p>Interior color: Black</p>	100€



		<p>Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy):: 07/05/2026</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: chip in the windshield</p> <p>Maintenance notification</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	21	<p>Make: Ford Model: Transit Version: Custom Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 29/04/2020 Fuel: Diesel Odometer reading (km): 195,446 Chassis number: WF0ZXXTTGZLR18298 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p>	100€



Body: Crew-cab van
Number of seats: 3
Number of axles: 2
Permitted Gross Vehicle Weight (kg): 3200
Transmission: Automatic
Engine capacity (cc): 1995
Engine power (kW): 95
Emission class: Euro 6
Exterior color: Gray

Metallic body: Yes
Interior color: Black

Upholstery: Fabric
Reversing camera: Yes
Air conditioning: Fully automatic climate control
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power-folding mirrors: Yes
Power windows: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Tow bar: Yes
Seat heating: Yes
Other Options: DAB tuner


Registration certificate: Yes, present

Certificate of Conformity: Yes, present
Identification report: Yes, present


Inspection certificate: Yes, present
Inspection certificate valid until (dd/mm/yyyy):
17/08/2025
Maintenance booklet: Not present
Visible vehicle damage: Yes. For a detailed
overview of the visible damage, please consult
the photo report.


Vehicle damage description: Broken windshield +



		various other damage Condition: Used Quantity: 1	
	52	<p>Make: Fiat Model: Talento Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 24/03/2021 Fuel: Diesel Odometer reading (km): 105954 Chassis number: ZFAFFL002L5131214 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3050 Transmission: Manual transmission Engine capacity (cc): 1997 Engine power (kW): 88 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration Certificate of conformity: Yes, available CARPASS: Yes, available Identification report: Yes, available</p>	100€



		<p>Inspection certificate: Yes Available Inspection certificate valid until (dd/mm/yyyy): May 23, 2024</p> <p>Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Dashboard message Star in the windshield Paint on the rear bumper</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	60	<p>Make: Renault Model: Express Version: Blue DCI 75 Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 26/08/2022 Fuel: Diesel Odometer reading (km): 50,287 Chassis number: VF1RJK00969222183 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2002 Transmission: Manual Cylinder capacity (cc): 1461 Engine power (kW): 55 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black</p>	100€

		Upholstery: Partial leather Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Multifunction steering wheel: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): August 30, 2025 Maintenance booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that would be expected given the car's age and mileage or hours.) For a detailed overview, please consult the photo report. Condition: Used Quantity: 1	
	67	Make: Ford Model: Transit Version: 2T 350L L3 Trend 2.0TD Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 17/03/2025 Fuel: Diesel Odometer reading (km): 7957 Chassis number: WF0EXXTTRERR78613 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 1995 Engine power (kW): 95 Emission class: Euro 6	100€



		<p>Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: Fitted cargo area Roof rack King Alu PDE ladder DAB Tuner Additional information: Mint condition.</p> <p>Registration certificate: Yes, available</p> <p>Certificate of Conformity: Yes, available</p> <p>Inspection certificate: Not available</p> <p>Maintenance booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that would be expected given the car's age and mileage or hours.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
--	--	---	--



73

Make: Fuso
Model: Canter
Version: 7C15
Year of manufacture (yyyy): 2023
First registration (dd/mm/yyyy): 30/08/2023
Fuel: Diesel
Odometer reading (km): 13754
Chassis number: TYBFEB71ELDD10805
Number of keys: 2
Vehicle category: N2: max. weight >3.5t - <12t

Body: Rigid truck
Number of axles: 2
Permitted Gross Vehicle Weight (kg): 7490
Transmission: Automatic
Cylinder capacity (cc): 2998
Engine power (kW): 110
Emission class: Euro 6
Number of doors: 2-door
Exterior color: Black

Metallic paint: No
Interior color: Black
Upholstery: Fabric
Reversing camera: Yes
Air conditioning: Manual air conditioning
Trip computer: Yes
Central locking: Yes
Power windows: Yes
Radio: Yes
Other options: Tachograph

Equipped with a D'Hollandia tailgate with key.
Additional information: Aluminum chassis.


Registration certificate: Yes, present

Certificate of Conformity: Yes, present
Identification report: Yes, present


Inspection certificate: Yes, present
Inspection certificate valid until (dd/mm/yyyy):
14/09/2025
Maintenance booklet: Not present
Visible vehicle damage: No, except for general

100€




		<p>wear and tear. (General wear and tear includes all damage that may be expected given the vehicle's age and mileage or hours.) For a detailed overview, please consult the photo report.</p> <p>Vehicle damage description: side mirror</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	75	<p>Make: Opel</p> <p>Model: Vivaro</p> <p>Year of manufacture (yyyy): 2014</p> <p>First registration (dd/mm/yyyy): 09/12/2014</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 216,463</p> <p>Chassis number: W0L4F7002FS010922</p> <p>Number of keys: 1</p> <p>Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Permitted Gross Vehicle Weight (kg): 2740</p> <p>Transmission: Manual transmission</p> <p>Engine capacity (cc): 1598</p> <p>Engine power (kW): 66</p> <p>Emission class: Euro 5b</p> <p>CO2 emissions (g/km): 170</p> <p>Exterior color: Red</p> <p>Metallic body: No</p> <p>Interior color: Black</p> <p>Upholstery: Fabric</p> <p>Power windows: Yes</p> <p>Radio: Yes</p> <p>Other options: Fitted cargo area</p> <p>Additional information: Includes remaining contents</p> <p>Registration certificate: Yes, available</p> <p>Certificate of Conformity: Yes, available</p> <p>Identification report: Yes, available</p>	100€




		<p>Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 25/07/2025 Maintenance booklet: None Present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Various damage, see photos.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	79	<p>Make: Opel</p> <p>Model: Vivaro</p> <p>Year of manufacture (yyyy): 2015</p> <p>First registration (dd/mm/yyyy): 24/07/2015</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 188,210</p> <p>Chassis number: W0L4F7002FV645283</p> <p>Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Weight (kg): 2740 Transmission: Manual transmission Engine capacity (cc): 1598 Engine power (kW): 66 Emission class: Euro 5b CO2 emissions (g/km): 170 Exterior color: Red</p>	100€



		<p>Metallic body: No</p> <p>Interior color: Black</p> <p>Upholstery: Fabric</p> <p>Central locking: Yes</p> <p>Power windows: Yes</p> <p>Radio: Yes</p> <p>Other options: Fitted cargo area</p> <p>Registration certificate: Yes, available</p> <p>Certificate of Conformity: Yes, available</p> <p>Identification report: Yes, available</p> <p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 14/06/2025</p> <p>Maintenance booklet: None Present</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: side mirror, seats</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	82	<p>Make: Fiat</p> <p>Model: Ducato</p> <p>Year of manufacture (yyyy): 2015</p> <p>First registration (dd/mm/yyyy): 24/09/2015</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 48611</p> <p>Chassis number: ZFA25000002886015</p> <p>Number of keys: 1</p> <p>Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Permitted Gross Vehicle Weight (kg): 3490</p>	100€



		<p>Transmission: Manual transmission Engine capacity (cc): 1956 Engine power (kW): 85 Emission class: Euro 5b Exterior color: Not used Interior color: Gray Upholstery: Fabric Trip computer: Yes Central locking: Yes Power windows: Yes Radio: Yes Additional information: Vehicle color: white, with advertising wrap.</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>CARPASS: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 15/12/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	85	<p>Make: Toyota Model: Proace Version: Long 2.0L Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 12/09/2024 Fuel: Diesel Odometer reading (km): 55,765 Chassis number: YARVLEHTMRZ049782</p>	100€




Number of keys: 1
Vehicle category: N1: max. weight <3.5 t

Body: Panel van
Number of seats: 3
Number of axles: 2
Maximum Permissible Weight (kg): 3100
Transmission: Manual transmission
Engine capacity (cc): 1997
Engine power (kW): 106
Emission class: Euro 6e
CO2 emissions (g/km): 202
Exterior color: White


Metallic paint: No
Interior color: Black

Upholstery: Fabric
Reversing camera: Yes
Air conditioning: Semi-automatic air conditioning
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power windows: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Tow bar: Yes
Registration certificate: Not available: the buyer will receive one Certificate of loss of registration certificate
Certificate of Conformity: Yes, present
Identification report: Yes, present
Inspection certificate: Yes, present
Inspection certificate valid until (dd/mm/yyyy): 03/01/2026
Maintenance booklet: Not present
Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.
Vehicle damage description: damage to the upper side
Condition: Used




		Quantity: 1	
	118	<p>Make: Fiat Model: Scudo Version: L3 Van Base 2.0</p> <p>Year of manufacture (yyyy): 2022</p> <p>First registration (dd/mm/yyyy): 02/05/2022</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 40537 Chassis number: VXFVFEHTMNZ030986 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3100 Transmission: Manual Engine capacity (cc): 1997 Engine power (kW): 106 Emission class: Euro 6 Exterior color: Beige</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Rear parking sensors: Yes Radio: Yes Additional information: Vehicle color: black, with advertising wrap.</p>	100€



		<p>Registration certificate: Yes, available</p> <p>Certificate of Conformity: Yes, available</p> <p>CARPASS: Yes, available</p> <p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 08/05/2026</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: dashboard notifications</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	172	<p>Make: Nissan</p> <p>Model: NV300</p> <p>Version: L2H1 2.0 dCi</p> <p>Year of manufacture (yyyy): 2020</p> <p>First registration (dd/mm/yyyy): 19/02/2020</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 85,233</p> <p>Chassis number: VNVF4000864631637</p> <p>Number of keys: 2</p> <p>Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Permitted Gross Vehicle Weight (kg): 3050</p> <p>Transmission: Manual</p> <p>Engine capacity (cc): 1997</p> <p>Engine power (kW): 88</p> <p>Emission class: Euro 6</p> <p>Exterior color: White</p> <p>Metallic body: No</p> <p>Interior color: Black</p>	100€



		<p>Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Additional information: Vehicle color: white, with advertising wrap.</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>CARPASS: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 14/09/2025</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	220	<p>Make: Opel Model: Vivaro Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 17/02/2023 Fuel: Diesel Odometer reading (miles): 5686 Chassis number: VXEVFEHTMN7076682</p>	100€



Number of keys: 2
Vehicle category: N1: max. weight <3.5 t

Body: Panel van
Number of seats: 3
Number of axles: 2
Permitted Gross Vehicle Weight (kg): 3100
Transmission: Manual
Engine capacity (cc): 1997
Engine power (kW): 106
Emission class: Euro 6
Exterior color: Orange

Metallic body: No
Interior color: Gray

Upholstery: Fabric
Air conditioning: Manual air conditioning
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power windows: Yes
Radio: Yes
Additional information: Vehicle color: white, with advertising wrap.

Registration certificate: Yes, present

Certificate of Conformity: Yes, present

CARPASS: Yes, present


Identification report: Yes, present

Inspection certificate: Not present


Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.

Condition: Used


Quantity: 1

	269	<p> Make: Opel Model: Vivaro Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 28/07/2023 Fuel: Diesel Odometer reading (km): 2924 Chassis number: VXEVFEHTMPZ049218 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t </p> <p> Body: Panel van Number of seats: 3 Number of axles: 2 Transmission: Manual Engine capacity (cc): 1997 Engine power (kW): 106 Emission class: Euro 6 Exterior color: Orange </p> <p> Metallic paint: No Interior color: Black </p> <p> Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: Vehicle color: white, with advertising wrap. </p> <p> Registration Certificate: Not present: the buyer will receive a certificate of loss of registration certificate. Certificate of Conformity: Not present: the buyer will receive a certificate of loss of conformity </p>	100€
---	-----	---	------




		<p>certificate. Inspection Certificate: Not present Maintenance Booklet: Not present Visible Vehicle Damage: No, except for general wear and tear. (General wear and tear includes all damage that may be expected given the vehicle's age and mileage or hours.) For a detailed overview, please consult the photo report. Condition: Used Quantity: 1</p>	
	325	<p>Make: Fiat Model: Ducato</p> <p>Year of manufacture (yyyy): 2014</p> <p>First registration (dd/mm/yyyy): 19/03/2014</p> <p>Fuel: Diesel Odometer reading (km): 68,176 Chassis number: ZFA25000002541954 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 1956 Engine power (kW): 85 Emission class: Euro 5b Exterior color: White</p> <p>Metallic paint: No Interior color: Red/black Upholstery: Fabric Central locking: Yes Power windows: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available</p>	100€



		<p>Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 23/08/2025 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please contact us. Always consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	371	<p>Make: Renault Model: Trafic Year of manufacture (yyyy): 2018 First registration (dd/mm/yyyy): 21/09/2018 Fuel: Diesel Odometer reading (km): 70922 Chassis number: VF1FL000X61273210 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2800 Transmission: Manual Cylinder capacity (cc): 1598 Engine power (kW): 70 Emission class: Euro 6b Exterior color: Not used Metallic body: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Radio: Yes Additional information: Vehicle color: white, with advertising wrap.</p>	100€



		<p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>CARPASS: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 11/09/2025</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	423	<p>Make: Renault</p> <p>Model: Trafic</p> <p>Year of manufacture (yyyy): 2019</p> <p>First registration (dd/mm/yyyy): 02/08/2019</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 34386</p> <p>Chassis number: VF1FL000X63675300</p> <p>Number of keys: 2</p> <p>Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Permitted Gross Vehicle Weight (kg): 2800</p> <p>Transmission: Manual</p> <p>Cylinder capacity (cc): 1598</p> <p>Engine power (kW): 70</p> <p>Emission class: Euro 6b</p> <p>Exterior color: Not used</p> <p>Metallic body: No</p> <p>Interior color: Black</p>	100€



		<p>Upholstery: Fabric Air conditioning: Manual air conditioning Power windows: Yes Radio: Yes Additional information: Vehicle color: White, with advertising wrap.</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>CARPASS: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 08/12/2025</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	--	--