

CATALOG

Passenger cars



DESCRIPTION

Auction of passenger cars from various bankruptcies, seizures, breaches of contract, end of leasing, etc.

START

4 september 2025 to 08:00 [UTC]

END DATE

11 september 2025 from 17:00 [UTC]

VIEWING

- Wednesday September 10 2025 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622

ISSUE - COLLECTION

- Wednesday September 17 2025 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47

Online bidding only!


Catalog created on 10 september 2025 to 04:12

AUCTIM - MOYERSOEN NV


Helststraat 47
2630 Aartselaar, Belgium
VAT BE 0452 153 622

www.auctim.com
info.moyersoen@auctim.be




	Item	Description	Start price
	18	<p>Brand: Volkswagen Model: Golf Version: TDI</p> <p>Year of manufacture (yyyy): 2016</p> <p>First registration (dd/mm/yyyy): 19/09/2016 Fuel: Diesel Odometer reading (km): 170122 Chassis number: WVVZZZAUZHP026808 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1598 Engine power (kW): 81 Emission class: Euro 6b CO2 emissions (g/km): 102 Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic Air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Heated seats: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available</p>	100€




		<p>CARPASS: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 19/09/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: various damage</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	23	<p>Brand: BMW Model: 216D Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 24/07/2020 Fuel: Diesel Odometer reading (km): 90619 Chassis number: WBA11AM0507G34364 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Sedan Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1496 Engine power (kW): 85 Emission class: Euro 6 Exterior color: White</p> <p>Metallic paint: No Interior color: Black Upholstery: Partial leather Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes</p>	100€




		<p>Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Sport seats: Yes Heated seats: Yes Other options: M package</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 24/07/2026 Maintenance booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that would be expected given the age and mileage or hours of use.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	49	<p>Make: Mercedes-Benz Model: A 160 Version: D Year of manufacture (yyyy): 2017 First registration (dd/mm/yyyy): 02/05/2017 Fuel: Diesel Odometer reading (km): 148889 Chassis number: WDD1760111J619796 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 5-door Transmission: Manual Engine capacity (cc): 1461 Engine power (kW): 66</p>	100€



		<p>Emission class: Euro 6b Exterior color: Black</p> <p>Metallic paint: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic Air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 26/04/2026 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: various damage Condition: Used Quantity: 1</p>	
	51	<p>Make: Opel Model: Zafira Year of manufacture (yyyy): 2008 First registration (dd/mm/yyyy): 01/02/2008 Fuel: Diesel Odometer reading (km): 172255 Chassis number: W0L0AHM758G077395 Number of keys: 1 Vehicle category: M1: passenger car</p>	100€



		<p>Vehicle type: Estate Number of doors: 5-door Transmission: Manual Engine capacity (cc): 1910 Engine power (kW): 74 Emission class: Euro 4 Exterior color: Black</p> <p>Metallic paint: No Interior color: Black Upholstery: Cloth Central locking: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, present Certificate of Conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 22/03/2025 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: cracked windshield various damage Condition: Used Quantity: 1</p>	
	54	<p>Make: Audi Model: A1 Version: Allstreet Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 18/04/2024 Fuel: Petrol Odometer reading (km): 80,009 Chassis number: WAUZZZGB8RR001377 Number of keys: 1</p>	100€



Vehicle category: M1: passenger car
Vehicle type: City car
Number of doors: 5-door
Transmission: Automatic
Engine capacity (cc): 999
Engine power (kW): 81
Emission class: Euro 6
Exterior color: Gray

Metallic paint: Yes
Interior color: Black
Upholstery: Cloth
Air conditioning: Fully automatic climate control
Trip computer: Yes
Central locking: Yes
Cruise Control: Yes

Power-folding mirrors: Yes

Power windows: Yes

Alloy wheels: Yes

Fog lights: Yes

Multifunction steering wheel: Yes

Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes

Radio: Yes

Registration certificate: Yes, present


Certificate of Conformity: Yes, present

Inspection certificate: Not present


Maintenance booklet: Not present

Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.




		Condition: Used Quantity: 1	
	55	<p>Make: Audi Model: A1 Version: Sportback 25 TFSI Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 18/04/2024 Fuel: Petrol Odometer reading (km): 74,424 Chassis number: WAUZZZGB8RR015943 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 999 Engine power (kW): 70 Emission class: Euro 6 Exterior color: Gray</p> <p>Metallic paint: Yes Interior color: Gray Upholstery: Fabric Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Not present Maintenance booklet: Not present</p>	100€



		Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: sidewall damage Condition: Used Quantity: 1	
	65	Brand: Volvo Model: V60 Version: Recharge R-Design T6 AWD plug-in hybrid Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 30/06/2021 Fuel: Hybrid - Electric/Gasoline Odometer reading (km): 130,424 Chassis number: YV1ZWBFVDN1468926 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Estate Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1969 Engine power (kW): 186 Emission class: Euro 6 Exterior color: Black Specific factory paint: Onyx Black Metallic paint: Yes Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power tailgate: Yes Power windows: Yes Power seats: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes	100€



		<p>Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Sport seats: Yes Seat heating: Yes Equipped with electric charging cable: Available Other options: Power seats with memory function Heated steering wheel Dark tinted rear windows DAB+ Registration certificate: Yes Available Certificate of Conformity: Yes, available Inspection Certificate: Not available Maintenance Booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that would be expected given the age and mileage or hours of use.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	66	<p>Make: Audi Model: Q3</p> <p>Version: S-Line 45 TFSI S Tronic Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 16/12/2021</p> <p>Fuel: Hybrid - Electric/Gasoline Odometer reading (km): 83653 Chassis number: WAUZZZF37N1029433 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic</p>	100€




Engine capacity (cc): 1395
Engine power (kW): 110
Emission class: Euro 6
Exterior color: Blue
Metallic paint: Yes
Interior color: Black

Upholstery: Fabric
Reversing camera: Yes
Air conditioning: Fully automatic climate control
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power-folding mirrors: Yes
Power windows: Yes
Alloy wheels: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Sports package: Yes
Tow bar: Yes
Seat heating: Yes
Equipped with electric charging cable: Available
Registration certificate: Yes, available
Certificate of Conformity: Yes, available
Inspection certificate: Yes, available
Inspection certificate valid until (dd/mm/yyyy):
16/12/2025
Visible vehicle damage: No, except general wear and tear. (General wear and tear includes all damage that would be expected given the age and mileage or hours of use.) For a detailed overview, please consult the photo report.


Condition: Used

Quantity: 1




	70	<p>Brand: KG Mobility Model: Torres EVX Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 25/10/2024 Fuel: Electric Odometer reading (km): 41,000 Chassis number: KPT00A123RP014737 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Estate Number of doors: 5-door Transmission: Automatic Engine power kW: 152 Exterior color: Green</p> <p>Metallic body: No Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power tailgate: Yes Power windows: Yes Power seats: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat ventilation: Yes Tow bar: Yes Seat heating: Yes Equipped with an electric charging cable: Present Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Yes, present</p>	100€
---	----	--	------




		<p>Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Condition: Used</p> <p>Quantity: 1</p>	
	72	<p>Make: Mercedes-Benz Model: C 160 Year of manufacture (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 21/01/2019 Fuel: Petrol Odometer reading (km): 113722 Chassis number: WDD2052441F860161 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Estate Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1595 Engine power (kW): 95 Emission class: Euro 6 Exterior color: Gray</p> <p>Metallic paint: Yes Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power tailgate: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes</p>	100€




		<p>Front parking sensors: Yes Radio: Yes Shift paddles: Yes Heated seats: Yes Other options: DAB tuner Registration certificate: Yes, available Certificate of Conformity: Yes, available CARPASS: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 23/08/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used</p> <p>Quantity: 1</p>	
	76	<p>Make: Fiat Model: 500 Version: Dolcevit Hybrid Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 16/08/2021</p> <p>Fuel: Hybrid - Electric/Gasoline Odometer reading (km): 76,435 Chassis number: ZFACF1CJXNJF47228 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 3-door Transmission: Manual Engine capacity (cc): 999 Engine power (kW): 51 Emission class: Euro 6 Exterior color: White Metallic paint: No Interior color: White/Black Upholstery: Full leather Air conditioning: Manual Air conditioning Trip computer: Yes Central locking: Yes</p>	100€



		<p>Cruise control: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Panoramic roof: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	77	<p>Make: Fiat Model: 500 Version: Dolcevit Hybrid Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 16/08/2021 Fuel: Petrol Odometer reading (km): 78,558 Chassis number: ZFACF1CJ8NJF47521 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 3-door Transmission: Manual Engine capacity (cc): 999 Engine power (kW): 51 Emission class: Euro 6 Exterior color: White Metallic paint: No Interior color: White/Black Upholstery: Full leather Air conditioning: Manual air conditioning Trip computer: Yes</p>	100€




		<p>Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 16/08/2025 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: star on windshield Condition: Used Quantity: 1</p>	
	78	<p>Make: Volvo Model: V60 Version: Inscription D4 Geartronic Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 02/01/2020 Fuel: Diesel Odometer reading (km): 173952 Chassis number: YV1ZWA8VDL2369545 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Estate Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1969 Engine power (kW): 140 Emission class: Euro 6 Exterior color: Beige Specific factory color: Birch Light Metallic paint: Yes Interior color: Black Upholstery: Full Leather</p>	100€



		<p>Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power tailgate: Yes Power windows: Yes Power seats: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Sport seats: Yes Seat heating: Yes Other options: DAB+ Harman Kardon sound system Power seats with memory function Additional information: Equipped with 4 additional Alutec alloy wheels, 1 of which has tires.</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 02/01/2026 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
--	--	--	--



	284	<p>Brand: Mini Model: Countryman Cooper Version: D Year of construction (yyyy): 2017 First registration (dd/mm/yyyy): 18/08/2017 Fuel: Diesel Odometer reading (km's): 105467 Chassis number: WMWYT910503D93022 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Berline Number of doors: 5-door Transmission: Manual transmission Cylinder capacity cc: 1995 Engine power kW: 110 Emission class: Euro 6b Exterior colour: Black Metallic colour: No Interior colour: Brown Upholstery: Full leather Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric windows: Yes Head up display: Yes Alloy rims: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Open roof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 18/08/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p>	100€
---	-----	---	------



AUCTIM
ONLINE AUCTIONS

		Condition: Used Quantity: 1	
--	--	--------------------------------	--