

CATALOG

Passenger cars



DESCRIPTION

Auction of passenger cars from various bankruptcies, seizures, breaches of contract, end of leasing, etc.

START

28 august 2025 to 08:00 [UTC]

END DATE

4 september 2025 from 17:00 [UTC]

VIEWING

- Wednesday September 03 2025 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
 +32 3 827 21 31 - info.moyersoens@auctim.be
 BTW BE 0452 153 622

ISSUE - COLLECTION

- Wednesday September 10 2025 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47

Online bidding only!


Catalog created on 4 september 2025 to 04:08

AUCTIM - MOYERSOEN NV


Helststraat 47
 2630 Aartselaar, Belgium
 VAT BE 0452 153 622

www.auctim.com
 info.moyersoens@auctim.be




	Item	Description	Start price
	8	<p>Brand: Porsche Model: Taycan Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 23/07/2021 Fuel: Electric Odometer reading (km): 96,470 Chassis number: WP0ZZZY1ZMSA03431 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Coupé Number of doors: 5-door Transmission: Automatic Engine power kW: 240 Exterior color: White</p> <p>Metallic paint: No Interior color: Black Upholstery: Full leather Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Power seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sport seats: Yes Seat heating: Yes Equipped with electric charging cable: Available</p> <p>Other options: BOSE sound system</p> <p>DAB tuner</p> <p>Registration certificate: Yes, available</p>	100€




		<p>Certificate of Conformity: Yes, available</p> <p>CARPASS: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 23/07/2025 Maintenance booklet: Not available Visible vehicle damage: No, except general wear and tear. (General wear and tear includes all damage that would be expected given the age and mileage or hours of use.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	13	<p>Brand: Volkswagen Model: Golf</p> <p>Version: 6 Year of manufacture (yyyy): 2009 First registration (dd/mm/yyyy): 31/07/2009 Fuel: Petrol Odometer reading (km): 149665 Chassis number: WVVZZZ1KZAW046984 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 5-door Transmission: Manual Engine capacity (cc): 1390 Engine power (kW): 59 Emission class: Euro 5 Exterior color: Black</p> <p>Metallic paint: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes</p>	100€



		<p>Power windows: Yes Alloy wheels: Yes Radio: Yes Registration certificate: Yes, present Certificate of Conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 02/16/2026 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Lock cover missing Various damages Condition: Used Quantity: 1</p>	
	16	<p>Brand: Jeep Model: Avenger Version: 1st Edition Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 25/09/2023 Fuel: Electric Odometer reading (km): 40,404 Chassis number: ZACNJAC53PJK27011 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic Engine power kW: 115 Exterior color: Black</p> <p>Specific factory paint: 601 Pastel Solid Metallic paint: No Interior color: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Fully automatic Air conditioning Trip computer: Yes Central locking: Yes</p>	100€



		<p>Cruise control: Yes Power-folding mirrors: Yes Power tailgate: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Equipped with an electric charging cable: Present</p> <p>Registration certificate: Not present: the buyer will receive a certificate of loss of registration Certificate of Conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 25/09/2027 Maintenance booklet: Not present Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that would be expected given the age and mileage or hours of use.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	30	<p>Brand: Dacia Model: Duster Version: All-New Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 12/12/2024 Fuel: Petrol Odometer reading (km): 9262 Chassis number: UU1DJF01473440109 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4</p>	100€




		<p>Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1598 Engine power (kW): 69 Emission class: Euro 6 Exterior color: Beige Metallic paint: No Interior color: Black Upholstery: Cloth Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Heated seats: Yes Other options: Heated steering wheel DAB tuner</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Yes, available Inspection certificate: Not available Maintenance booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the age and mileage or hours of use.) For a detailed overview, please consult the photo report. Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--




	34	<p>Make: Citroën Model: C3 Version: 1.2i</p> <p>Year of manufacture (yyyy): 2020</p> <p>First registration (dd/mm/yyyy): 26/02/2020 Fuel: Petrol Odometer reading (km): 81,470 Chassis number: VF7SXHNPUKT662891 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Saloon Number of doors: 5-door Transmission: Manual Engine capacity (cc): 1,199 Engine power (kW): 81 Emission class: Euro 6 Exterior color: Black</p> <p>Metallic paint: Yes Interior color: Black Upholstery: Cloth Reversing camera: Yes Air conditioning: Semi-automatic Air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 05/07/2025 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Various damage</p>	100€
---	----	--	------




		Maintenance report Condition: Used Quantity: 1	
	39	Brand: Toyota Model: C-HR Version: 1.8L Hybrid Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 16/01/2024 Fuel: Hybrid - Electric/Gasoline Odometer reading (km): 74667 Chassis number: NMTK33BX20R312750 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1798 Engine power (kW): 72 Emission class: Euro 6 Exterior color: Black Metallic paint: No Interior color: Black Upholstery: Partial Leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Heated seats: Yes Registration certificate: Yes, available	100€




		<p>Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 03/12/2025 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used</p> <p>Quantity: 1</p>	
	53	<p>Brand: Mercedes-Benz Model: Vito Version: 116 CDI Pro Tourer XL Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 31/01/2023 Fuel: Diesel Odometer reading (km): 47587 Chassis number: W1VVLGFZ5P4176114 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 4-door Transmission: Automatic Engine capacity (cc): 1950 Engine power (kW): 120 Emission class: Euro 6 CO2 emissions (g/km): 187 Exterior color: Silver Specific factory paint: Brilliant Silver Metallic paint: Yes Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes</p>	100€



		<p>Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Heated seats: Yes Other options: 9 seats DAB tuner Registration certificate: Yes, available Certificate of Conformity: Yes, available CARPASS: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 31/01/2027 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used</p> <p>Quantity: 1</p>	
	59	<p>Make: MG Model: EHS</p> <p>Version: PHEV Comfort Basic</p> <p>Year of manufacture (yyyy): 2022</p> <p>First registration (dd/mm/yyyy): 05/04/2022</p> <p>Fuel: Hybrid - Electric/Petrol Odometer reading (km): 110327 Chassis number: LSJA24395MN046222</p> <p>Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1490 Engine power (kW): 119 Emission class: Euro 6 Exterior color: Red</p>	100€



		<p>Metallic paint: Yes Interior color: Black</p> <p>Upholstery: Full Leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Power seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Equipped with an electric charging cable: Available</p> <p>Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 05/04/2026 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: driver's seat</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	63	<p>Make: Tesla Model: Model 3</p> <p>Version: Standard Plus Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 09/03/2020 Fuel: Electric</p>	100€



Odometer reading (km): 114,415
Chassis number: 5YJ3E7EA4LF673310
Number of keys: 2
Vehicle category: M1: passenger car
Vehicle type: Sedan
Number of doors: 5-door
Transmission: Automatic
Engine power kW: 239
Exterior color: White

Metallic paint: No
Interior color: Black
Upholstery: Full leather
Reversing camera: Yes
Air conditioning: Fully automatic climate control
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power-folding mirrors: Yes
Power windows: Yes
Power seats: Yes
Alloy wheels: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Heated seats: Yes
Equipped with electric charging cable: Available
Other options: Autopilot
Registration certificate: Yes, available
Certificate of Conformity: Yes, available
CARPASS: Yes, available
Inspection certificate: Not available
Maintenance booklet: Not available
Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.
Vehicle damage description: steering wheel damage
Condition: Used
Quantity: 1



AUCTIM
ONLINE AUCTIONS

--	--	--	--

AUCTIM - MOYERSON NV

Helststraat 47
2630 Aartselaar, Belgium
VAT BE 0452 153 622

www.auctim.com
info.moyersoan@auctim.be