

CATALOG

Paramedical Team Vehicles - Bankruptcy


DESCRIPTION

Patient transport vehicles including MERCEDES-BENZ, Volkswagen and Peugeot brands.

START

19 september 2025 to 08:00 [UTC]

END DATE

29 september 2025 from 16:00 [UTC]

VIEWING

- ---
 Wednesday September 24 2025 from 10:00 until 11:00
 BE-6900 MARCHE-EN-FAMENNE, RUE DU VIVIER 10

AUCTIM PARTNER
MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
 +32 3 827 21 31 - info.moyersoen@auctim.be
 BTW BE 0452 153 622

ISSUE - COLLECTION

- Aanmelden tussen
 Monday October 06 2025 from 11:00 until 12:00
 BE-6900 MARCHE-EN-FAMENNE, RUE DU VIVIER 10

Online bidding only!


Catalog created on 15 september 2025 to 04:52

AUCTIM - MOYERSOEN NV


Helststraat 47
 2630 Aartselaar, Belgium
 VAT BE 0452 153 622

www.auctim.com
 info.moyersoen@auctim.be




	Item	Description	Start price
	1	<p>Make: Mercedes Benz Model: Vito</p> <p>Year of manufacture (yyyy): 2015</p> <p>First registration (dd/mm/yyyy): 10/12/2015 Fuel: Diesel Odometer reading (km): 650015 Chassis number: WDF44770313096608 License plate: 1ETS819 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 2143 Engine power (kW): 100 Emission class: Euro 5b Exterior color: White Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes</p> <p>Additional information: The vehicle is equipped as an ambulance and includes a Dauphine stretcher, wheelchair, first aid kit, various compresses and bandages, a pulse oximeter, and a defibrillator. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available Identification report: Yes, available</p>	100€



		<p>Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 07/08/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Large cracks in the windshield, rust formation in several places, passenger window inoperable from the driver's side</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	1	<p>Make: Mercedes Benz Model: Vito</p> <p>Year of manufacture (yyyy): 2015</p> <p>First registration (dd/mm/yyyy): 10/12/2015 Fuel: Diesel Odometer reading (km): 650015 Chassis number: WDF44770313096608 License plate: 1ETS819 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 2143 Engine power (kW): 100 Emission class: Euro 5b Exterior color: White Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes</p>	100€



		<p>Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Additional information: The vehicle is equipped as an ambulance and includes a Dauphine stretcher, wheelchair, first aid kit, various compresses and bandages, a pulse oximeter, and a defibrillator. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 07/08/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Large cracks in the windshield, rust formation in several places, passenger window inoperable from the driver's side</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	2	<p>Make: Mercedes Model: V-Class</p> <p>Version: V220d Year of manufacture (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 31/08/2018 Fuel: Diesel Odometer reading (km): 339,445 Chassis number: WDF44781313406201 Number of keys: 2 Vehicle category: M1: passenger car</p>	100€




Vehicle type: MPV
Number of doors: 5-door
Transmission: Automatic
Engine capacity (cc): 2143
Engine power (kW): 120
Emission class: Euro 6
Exterior color: White
Interior color: Black
Upholstery: Full leather
Reversing camera: Yes
Air conditioning: Fully automatic climate control
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power-folding mirrors: Yes
Power windows: Yes
Power seats: Yes
LED lighting: Yes
Alloy wheels: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Shift paddles: Yes
Additional information: The vehicle is equipped as an ambulance. Equipped with flashing lights, a stretcher, a first aid kit, a defibrillator, a wheelchair, an inflatable stretcher, various bandages, and compresses. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate.
Certificate of conformity: Yes, available
CARPASS: Yes, available
Inspection certificate: Yes, available


Inspection certificate valid until (dd/mm/yyyy): 27/07/2025
Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.


Condition: Used



		Quantity: 1	
	2	<p>Make: Mercedes Model: V-Class</p> <p>Version: V220d Year of manufacture (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 31/08/2018 Fuel: Diesel Odometer reading (km): 339,445 Chassis number: WDF44781313406201 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 2143 Engine power (kW): 120 Emission class: Euro 6 Exterior color: White Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Power seats: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Additional information: The vehicle is equipped as an ambulance. Equipped with flashing lights, a</p>	100€



		<p>stretcher, a first aid kit, a defibrillator, a wheelchair, an inflatable stretcher, various bandages, and compresses. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available CARPASS: Yes, available Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 27/07/2025</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	3	<p>Make: Mercedes Model: Vito</p> <p>Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 14/05/2020 Fuel: Diesel Odometer reading (km): 263,772 Chassis number: W1V44770313695379 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 2143 Engine power (kW): 100 Emission class: Euro 6c Exterior color: White Interior color: Black Upholstery: Cloth Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes</p>	100€

		<p> Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Additional information: The vehicle is equipped as an ambulance. Equipped with flashing lights, a stretcher, a spineboard, a first aid kit, a defibrillator, a wheelchair, an inflatable stretcher, various bandages, and compresses. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 14/09/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Large crack in windshield, starting with booster. Condition: Used Quantity: 1 </p>	
	3	<p> Make: Mercedes Model: Vito Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 14/05/2020 Fuel: Diesel Odometer reading (km): 263,772 </p>	100€




Chassis number: W1V44770313695379
Number of keys: 1
Vehicle category: M1: passenger car
Vehicle type: MPV
Number of doors: 5-door
Transmission: Automatic
Engine capacity (cc): 2143
Engine power (kW): 100
Emission class: Euro 6c
Exterior color: White
Interior color: Black
Upholstery: Cloth
Reversing camera: Yes
Air conditioning: Manual air conditioning
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power-folding mirrors: Yes
Power windows: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Shift paddles: Yes
Additional information: The vehicle is equipped as an ambulance. Equipped with flashing lights, a stretcher, a spineboard, a first aid kit, a defibrillator, a wheelchair, an inflatable stretcher, various bandages, and compresses. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate.
Certificate of conformity: Yes, available
Identification report: Yes, available

Inspection certificate: Yes, available


Inspection certificate valid until (dd/mm/yyyy): 14/09/2025
Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.

Description of vehicle damage: Large crack in





		windshield, starting with booster. Condition: Used Quantity: 1	
	4	<p>Make: Mercedes Model: Sprinter Year of manufacture (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 11/04/2018 Fuel: Diesel Odometer reading (km): 511734 Chassis number: WDB9067311P593182 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 4-door Transmission: Manual Engine capacity (cc): 2143 Engine power (kW): 105 Emission class: Euro 6b Exterior color: Yellow Interior color: Black Upholstery: Partial leather Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Additional information: Vehicle is equipped for the transport of disabled persons. Equipped with a ramp and 10 adjustable floor hooks Registration certificate: Not available: the buyer will receive a certificate of loss of registration Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 23/04/2026</p>	100€




		<p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: To start with a booster.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	4	<p>Make: Mercedes</p> <p>Model: Sprinter</p> <p>Year of manufacture (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 11/04/2018</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 511734</p> <p>Chassis number: WDB9067311P593182</p> <p>Number of keys: 2</p> <p>Vehicle category: M1: passenger car</p> <p>Vehicle type: MPV</p> <p>Number of doors: 4-door</p> <p>Transmission: Manual</p> <p>Engine capacity (cc): 2143</p> <p>Engine power (kW): 105</p> <p>Emission class: Euro 6b</p> <p>Exterior color: Yellow</p> <p>Interior color: Black</p> <p>Upholstery: Partial leather</p> <p>Air conditioning: Manual air conditioning</p> <p>Trip computer: Yes</p> <p>Central locking: Yes</p> <p>Cruise control: Yes</p> <p>Power windows: Yes</p> <p>Fog lights: Yes</p> <p>Multifunction steering wheel: Yes</p> <p>Radio: Yes</p> <p>Additional information: Vehicle is equipped for the transport of disabled persons. Equipped with a ramp and 10 adjustable floor hooks</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration</p> <p>Certificate of conformity: Yes, available</p> <p>Inspection certificate: Yes, available</p>	100€




		<p>Inspection certificate valid until (dd/mm/yyyy): 23/04/2026</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: To start with a booster.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	5	<p>Make: Mercedes</p> <p>Model: Sprinter</p> <p>Year of manufacture (yyyy): 2015</p> <p>First registration (dd/mm/yyyy): 09/10/2019</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 517682</p> <p>Chassis number: WDB9066331P179319</p> <p>Number of keys: 2</p> <p>Vehicle category: M1: passenger car</p> <p>Vehicle type: MPV</p> <p>Number of doors: 4-door</p> <p>Transmission: Automatic</p> <p>Engine capacity (cc): 2143</p> <p>Engine power (kW): 120</p> <p>Emission class: Euro 5b</p> <p>Exterior color: Yellow</p> <p>Interior color: Black</p> <p>Upholstery: Cloth</p> <p>Reversing camera: Yes</p> <p>Air conditioning: Manual air conditioning</p> <p>Trip computer: Yes</p> <p>Central locking: Yes</p> <p>Power windows: Yes</p> <p>Fog lights: Yes</p> <p>Navigation: Yes</p> <p>Radio: Yes</p> <p>Additional information: The vehicle is equipped as an ambulance. Equipped with flashing lights, a Rugged stretcher, a first aid bag, a freezer compartment, a Spencer wheelchair, an inflatable stretcher, an Edan saturation meter, a manual blood pressure monitor, and various bandages</p>	100€

		<p>and compresses.</p> <p>Registration certificate: Not present: the buyer will receive a certificate of loss of registration.</p> <p>Certificate of conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 01/05/2024</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Does not start.</p> <p>Broken right side mirror</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	5	<p>Make: Mercedes</p> <p>Model: Sprinter</p> <p>Year of manufacture (yyyy): 2015</p> <p>First registration (dd/mm/yyyy): 09/10/2019</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 517682</p> <p>Chassis number: WDB9066331P179319</p> <p>Number of keys: 2</p> <p>Vehicle category: M1: passenger car</p> <p>Vehicle type: MPV</p> <p>Number of doors: 4-door</p> <p>Transmission: Automatic</p> <p>Engine capacity (cc): 2143</p> <p>Engine power (kW): 120</p> <p>Emission class: Euro 5b</p> <p>Exterior color: Yellow</p> <p>Interior color: Black</p> <p>Upholstery: Cloth</p> <p>Reversing camera: Yes</p> <p>Air conditioning: Manual air conditioning</p> <p>Trip computer: Yes</p> <p>Central locking: Yes</p> <p>Power windows: Yes</p>	100€




		<p>Fog lights: Yes Navigation: Yes Radio: Yes Additional information: The vehicle is equipped as an ambulance. Equipped with flashing lights, a Rugged stretcher, a first aid bag, a freezer compartment, a Spencer wheelchair, an inflatable stretcher, an Edan saturation meter, a manual blood pressure monitor, and various bandages and compresses. Registration certificate: Not present: the buyer will receive a certificate of loss of registration. Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 01/05/2024 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Does not start.</p> <p>Broken right side mirror Condition: Used</p> <p>Quantity: 1</p>	
	6	<p>Brand: Volkswagen Model: Crafter Year of manufacture (yyyy): 2014</p> <p>First registration (dd/mm/yyyy): 20/05/2014 Fuel: Diesel Odometer reading (km): 309117 Chassis number: WV1ZZZ2EZF6002352 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 4-door Transmission: Manual Engine capacity (cc): 1968</p>	100€




		<p>Engine power (kW): 100 Emission class: Euro 5b Exterior color: White Interior color: Gray Upholstery: Partial leather Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Radio: Yes Additional information: The vehicle is equipped for disabled transport. It is equipped with a ramp. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 10/10/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Part of the engine has been removed, the battery is missing Condition: Used Quantity: 1</p>	
	6	<p>Brand: Volkswagen Model: Crafter Year of manufacture (yyyy): 2014</p> <p>First registration (dd/mm/yyyy): 20/05/2014 Fuel: Diesel Odometer reading (km): 309117 Chassis number: WV1ZZZ2EZF6002352 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 4-door Transmission: Manual Engine capacity (cc): 1968</p>	100€




		<p>Engine power (kW): 100 Emission class: Euro 5b Exterior color: White Interior color: Gray Upholstery: Partial leather Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Radio: Yes Additional information: The vehicle is equipped for disabled transport. It is equipped with a ramp. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 10/10/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Part of the engine has been removed, the battery is missing Condition: Used Quantity: 1</p>	
	8	<p>Make: Volkswagen Model: Caddy Year of manufacture (yyyy): 2013 First registration (dd/mm/yyyy): 02/01/2014 Fuel: Diesel Odometer reading (km): 336657 Chassis number: WV2ZZZ2KZEX014611 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 5-door Transmission: Manual Engine capacity (cc): 1598</p>	100€




		<p>Engine power (kW): 75 Emission class: Euro 5b Exterior color: Gray Interior color: Black Upholstery: Cloth Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Electric windows: Yes Fog lights: Yes Radio: Yes Additional information: Vehicle is suitable for wheelchair users. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 19/05/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Damage to the front right bodywork. Engine runs but smokes heavily and error messages appear on the dashboard. Condition: Used Quantity: 1</p>	
	8	<p>Make: Volkswagen Model: Caddy Year of manufacture (yyyy): 2013</p> <p>First registration (dd/mm/yyyy): 02/01/2014 Fuel: Diesel Odometer reading (km): 336657 Chassis number: WV2ZZZ2KZEX014611 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 5-door</p>	100€



		<p>Transmission: Manual Engine capacity (cc): 1598 Engine power (kW): 75 Emission class: Euro 5b Exterior color: Gray Interior color: Black Upholstery: Cloth Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Electric windows: Yes Fog lights: Yes Radio: Yes Additional information: Vehicle is suitable for wheelchair users. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 19/05/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Damage to the front right bodywork. Engine runs but smokes heavily and error messages appear on the dashboard. Condition: Used Quantity: 1</p>	
	9	<p>Make: Peugeot Model: Partner</p> <p>Year of manufacture (yyyy): 2013</p> <p>First registration (dd/mm/yyyy): 31/03/2014</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 143,797</p>	100€



		<p>Chassis number: VF37J9HN0DN553175 License plate: 1FJP572</p> <p>Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 5-door</p> <p>Transmission: Manual</p> <p>Engine capacity (cc): 1560 Engine power (kW): 55 Emission class: Euro 5b Exterior color: Gray Interior color: Black</p> <p>Upholstery: Cloth Air conditioning: Manual air conditioning Electric windows: Yes</p> <p>Radio: Yes Additional information: Vehicle is suitable for transport by people with disabilities, equipped with a ramp and wheelchair Registration certificate: Not available: the buyer will receive a certificate of loss of registration Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 26/12/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1</p>	
	9	<p>Make: Peugeot Model: Partner</p> <p>Year of manufacture (yyyy): 2013</p> <p>First registration (dd/mm/yyyy): 31/03/2014</p>	100€



Fuel: Diesel

Odometer reading (km): 143,797
Chassis number: VF37J9HN0DN553175
License plate: 1FJP572

Number of keys: 1
Vehicle category: M1: passenger car
Vehicle type: MPV
Number of doors: 5-door

Transmission: Manual

Engine capacity (cc): 1560
Engine power (kW): 55
Emission class: Euro 5b
Exterior color: Gray
Interior color: Black

Upholstery: Cloth
Air conditioning: Manual air conditioning
Electric windows: Yes

Radio: Yes
Additional information: Vehicle is suitable for transport by people with disabilities, equipped with a ramp and wheelchair
Registration certificate: Not available: the buyer will receive a certificate of loss of registration
Certificate of conformity: Yes, available
Inspection certificate: Yes, available
Inspection certificate valid until (dd/mm/yyyy): 26/12/2025
Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.
Condition: Used
Quantity: 1



10

Make: Mercedes Benz
Model: Vito

100€

Year of manufacture (yyyy): 2012

First registration (dd/mm/yyyy): 22/03/2013

Fuel: Diesel

Odometer reading (km): 337356

Chassis number: WDF63960313774830

License plate: 1WAD920

Number of keys: 1

Vehicle category: M1: passenger car

Vehicle type: MPV

Number of doors: 4-door

Transmission: Manual

Engine capacity (cc): 2143

Engine power (kW): 100

Emission class: Euro 5b

Exterior color: White

Upholstery: Cloth

Air conditioning: Manual air conditioning

Electric windows: Yes

Radio: Yes

Additional Information: The vehicle is equipped as an ambulance, equipped with a stretcher, first aid kit, various compresses and bandages, 24V plugs, and interior lighting.

Registration certificate: Not present: the buyer will receive a certificate of loss of registration.

Certificate of conformity: Yes, present.

Inspection certificate: Yes, present.

Inspection certificate valid until (dd/mm/yyyy): 02/12/2025.

Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.

Vehicle damage description: Starting with booster.

Condition: Used.

Quantity: 1.



10

Make: Mercedes Benz
Model: Vito

100€

Year of manufacture (yyyy): 2012

First registration (dd/mm/yyyy): 22/03/2013

Fuel: Diesel

Odometer reading (km): 337356

Chassis number: WDF63960313774830

License plate: 1WAD920

Number of keys: 1

Vehicle category: M1: passenger car

Vehicle type: MPV

Number of doors: 4-door

Transmission: Manual

Engine capacity (cc): 2143

Engine power (kW): 100

Emission class: Euro 5b

Exterior color: White

Upholstery: Cloth

Air conditioning: Manual air conditioning

Electric windows: Yes

Radio: Yes

Additional Information: The vehicle is equipped as an ambulance, equipped with a stretcher, first aid kit, various compresses and bandages, 24V plugs, and interior lighting.

Registration certificate: Not present: the buyer will receive a certificate of loss of registration.

Certificate of conformity: Yes, present.

Inspection certificate: Yes, present.

Inspection certificate valid until (dd/mm/yyyy): 02/12/2025.

Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.

Vehicle damage description: Starting with booster.

Condition: Used.

Quantity: 1.