

CATALOG

Commercial vehicles

DESCRIPTION	Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.
START	9 october 2025 to 08:00 [UTC]
END DATE	16 october 2025 from 16:00 [UTC]
VIEWING	--- Wednesday October 15 2025 from 15:00 until 17:00 BE-2630 Aartselaar, Helststraat 47
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
ISSUE - COLLECTION	- Lots: 1 Only by appointment through the organizer. Thursday October 23 2025 from 10:00 until 10:00 BE-6900 MARCHE-EN-FAMENNE, RUE DU VIVIER 10 --- Wednesday October 22 2025 from 10:00 until 12:00 BE-2630 Aartselaar, Helststraat 47

Online bidding only!

Catalog created on 12 october 2025 to 04:05



	Item	Description	Start price
	1	Make: Peugeot Model: Boxer Version: MS Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 20/08/2020 Fuel: Diesel Odometer reading (km): 81,412 Chassis number: VF3YUCCNFB12P40361 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 3 Number of axles: 2 Transmission: Manual Engine capacity (cc): 2179 Engine power (kW): 121 Emission class: Euro 6d-TEMP CO2 emissions (g/km): 165 Exterior color: White Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Additional information: Equipped with a roof rack with mounted Roll & Fix tension straps and a wooden floor in the load compartment. Please note: the electric controls for the driver's window are not working. This lot can be picked up by appointment only at	100€



		BE-6900 MARCHE-EN-FAMENNE, RUE DU VIVIER 10. Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 27/08/2023 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1	
	129	Make: Fiat Model: Fiorino Year of manufacture (yyyy): 2018 First registration (dd/mm/yyyy): 21/10/2019 Fuel: Diesel Odometer reading (km): 210,071 Chassis number: ZFA22500006N76127 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 2 Number of axles: 21,820 Transmission: Manual Cylinder capacity (cc): 1,248 Engine power (kW): 59 Emission class: Euro 6b Exterior color: Gray Interior color: Black Upholstery: Fabric	10€



		Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of Conformity: Yes, present Identification report: Yes, present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1	
	130	Make: Ford Model: Transit Year of manufacture (yyyy): 2015 First registration (dd/mm/yyyy): 27/07/2015 Fuel: Diesel Odometer reading (km): 257364 Chassis number: WF0XXTTGXFL60523 Number of keys: 4 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2198 Engine power (kW): 114 Emission class: Euro 5b Exterior color: White Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes	100€



		Rear parking sensors: Yes Radio: Yes Other options: Heated windscreen Retractable step Rear compartment cooling system Registration certificate: Yes, available Certificate of Conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes Available Inspection certificate valid until (dd/mm/yyyy): September 25, 2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1	
--	--	---	--