

CATALOG

Transport & Logistics

DESCRIPTION	Auction of Transport and Logistics
START	18 october 2025 to 08:00 [UTC]
END DATE	28 october 2025 from 10:00 [UTC]
VIEWING	--- Wednesday October 22 2025 from 15:00 until 17:00 Helststraat 47, 2630 Aartselaar --- Wednesday November 05 2025 from 10:00 until 12:00 Helststraat 47, 2630 Aartselaar
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
ISSUE - COLLECTION	

Online bidding only!

Catalog created on 12 october 2025 to 04:51

	Item	Description	Start price
	131	Brand: Chereau Model: CSD3 Year of manufacture (yyyy): 2010 First registration (dd/mm/yyyy): 15/03/2010 Trailer category: O4: max. weight >10000kg Trailer type: Refrigerated trailer Chassis number: VM4CD381HAA015007 Maximum Permissible Weight (kg): 39000 Internal dimensions (L x W x H) in mm: 13000x2500 Trailer registration certificate: Yes, available Trailer certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 26/03/2026 Number of axles: 3 Visible vehicle damage: Yes, for a detailed overview You can always consult the photo report for any visible damage. Condition: Used Quantity: 1	2.500€
	810	Make: Scania Model: P420 Year of manufacture (yyyy): 2011 First registration (dd/mm/yyyy): 27/03/2012 Fuel: Diesel Odometer reading (km): Last read 1145925 24/02/2025 Chassis number: XLEP4X20005284766 Number of keys: 2 Category: N3: max. weight >12 t	1€



		Tractor type: Standard tractor Number of axles: 2 Permitted Gross Vehicle Weight (kg): 18,000 Transmission: Automatic Cylinder capacity (cc): 11,705 Engine power (kW): 309 Emission class: Euro 5 Exterior color: White Interior color: Black Upholstery: Partial leather Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 26/02/2026 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Vehicle does not start, no battery present Condition: Used Quantity: 1	
	811	Make: Iveco Model: AD440T/P Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 24/06/2019 Fuel: Diesel Odometer reading (km): Last read 509,112 on 10/07/2025 Chassis number: WJMM62AS10C416145 Number of keys: 2 Category: N3: max. weight >12 t	100€



		Tractor type: Standard tractor Number of axles: 2 Permitted Gross Vehicle Weight (kg): 19,000 Transmission: Manual transmission Cylinder capacity (cc): 1,112 Engine power (kW): 309 Emission class: Euro 1 Exterior color: White Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 10/07/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1	
	812	Make: Volvo Model: FLB3C Year of manufacture (yyyy): 2014 First registration (dd/mm/yyyy): 19/05/2014 Fuel: Diesel Odometer reading (km): 539426 Chassis number: YV2TN12A9EB678645 Number of keys: 2 Category: N3: max. weight >12 t Truck type: Panel truck Number of axles: 2 Length (meters): 9 Maximum Permissible Weight (kg): 16,000 Transmission: Manual transmission Engine capacity (cc): 7,146 Engine power (kW): 181 Emission class: Euro 5	100€



		Exterior color: White Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Cruise control: Yes Power windows: Yes Air suspension seat: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Tachograph: No Tow bar: Yes Additional information: Tail lift not working Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 25/06/26 Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Tail lift not working Condition: Used Quantity: 1	
	813	Brand: DAF Model: FA-55LF Year of manufacture (yyyy): 2009 First registration (dd/mm/yyyy): 04/09/2009 Fuel: Diesel Odometer reading (km): 781788 Chassis number: XLRAE55GF0L353493 Number of keys: 2 Category: N3: max. weight >12 t Truck type: Panel van Number of axles: 2 Length (meters): 13	100€



		Permitted Gross Vehicle Weight (kg): 18,600 Transmission: Manual Cylinder capacity (cc): 6,693 Engine power (kW): 165 Emission class: Euro 4 Exterior color: Red Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Power windows: Yes Air-suspended seats: Yes Multifunction steering wheel: Yes Tachograph: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): September 29, 2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1	
	814	Make: Volvo Model: FLH.240.18 Year of manufacture (yyyy): 2008 First registration (dd/mm/yyyy): 18/06/2008 Fuel: Diesel Odometer reading (km): 879,435 Chassis number: YV2TBM0A08B522754 Number of keys: 1 Category: N3: max. weight >12 t Truck type: Panel truck	100€



Number of axles: 2
Length (meters): 12

Maximum Permissible Weight (kg): 18,000

Transmission: Manual transmission
Cylinder capacity (cc): 7,146

Engine power (kW): 177

Emission class: Euro 4
Exterior color: Red

Interior color: Gray

Upholstery: Fabric
Air conditioning: Manual air conditioning

Cruise control: Yes
Power windows: Yes
Air suspension seats: Yes
Fog lights: Yes
Radio: Yes
Tachograph: No
Other options: Tail lift
Registration certificate: Yes, available
Certificate of conformity: Yes, available
Identification report: Yes, available
Inspection certificate: Yes, available
Inspection certificate valid until (dd/mm/yyyy):
August 29, 2025
Visible vehicle damage: Yes. For a detailed
overview of the visible damage, please consult
the photo report.

Condition: Used

Quantity: 1