

CATALOG

Commercial vehicles

DESCRIPTION	Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.
START	16 october 2025 to 08:00 [UTC]
END DATE	23 october 2025 from 16:00 [UTC]
VIEWING	--- Wednesday October 22 2025 from 15:00 until 17:00 BE-2630 Aartselaar, Helststraat 47
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
ISSUE - COLLECTION	--- Wednesday October 29 2025 from 10:00 until 12:00 BE-2630 Aartselaar, Helststraat 47

Online bidding only!

Catalog created on 14 october 2025 to 04:38



	Item	Description	Start price
	118	Make: Renault Model: Master Year of manufacture (yyyy): Unknown First registration (dd/mm/yyyy): Unknown Fuel: Diesel Odometer reading (km): 119265 Chassis number: VF1MA000870775430 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 3 Number of axles: 2 Transmission: Manual transmission Exterior color: White Interior color: Black Upholstery: Fabric Reversing camera: Yes Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Not available: the buyer will receive a certificate of loss of conformity certificate Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1	100€



122

Make: Peugeot
Model: Boxer
Year of manufacture (yyyy): 2022
First registration (dd/mm/yyyy): 13/10/2022
Fuel: Diesel
Odometer reading (km): 86532
Chassis number: VF3YCBPFCNG011660
Number of keys: 1
Vehicle category: N1: max. weight <3.5 t

Body: Panel van
Number of seats: 3
Number of axles: 2
Permitted Gross Vehicle Weight (kg): 3500
Transmission: Manual transmission
Engine capacity (cc): 2179
Engine power (kW): 103
Emission class: Euro 6
Exterior color: White

Metallic body: No
Interior color: Black
Upholstery: Fabric
Reversing camera: Yes
Air conditioning: Manual air conditioning
Central locking: Yes
Cruise control: Yes
Power windows: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Radio: Yes
Tow bar: Yes
Registration certificate: Yes, available
Certificate of conformity: Yes, available
Identification report: Yes, available
Inspection certificate: Yes, available
Inspection certificate valid until (dd/mm/yyyy):
26/11/2025
Maintenance booklet: Not available
Visible vehicle damage: Yes. For a detailed
overview of the visible damage, please consult
the photo report.

Condition: Used

100€

		Quantity: 1	
	135	Make: Ford Model: Transit Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 29/07/2021 Fuel: Diesel Odometer reading (km): 61034 Chassis number: WF0YXXTTGYMU09528 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3400 Transmission: Manual transmission Engine capacity (cc): 1995 Engine power (kW): 95.60 Emission class: Euro 6d-TEMP Exterior color: Red Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 24/08/2026 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult	10€



		the photo report. Condition: Used Quantity: 1	
	139	Make: Peugeot Model: Expert Year of manufacture (yyyy): 2016 First registration (dd/mm/yyyy): 26/04/2016 Fuel: Diesel Odometer reading (km): 119248 Chassis number: VF3XS9HM0GZ014649 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 3 Number of axles: 2 Maximum Permissible Weight (kg): 2661 Transmission: Manual transmission Cylinder capacity (cc): 1560 Engine power (kW): 66 Emission class: Euro 5b CO2 emissions (g/km): 177 Exterior color: White Interior color: Black Upholstery: Fabric Central locking: Yes Power windows: Yes Radio: Yes Registration certificate: Yes, available Certificate of Conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 03/05/2026 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1	10€



	140	Make: Ford Model: Connect Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 08/04/2021 Fuel: Diesel Odometer reading (km): 39,482 Chassis number: WF0RXXWPGRMU6832 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2385 Transmission: Manual transmission Engine capacity (cc): 1499 Engine power (kW): 73.3 Emission class: Euro 6d-TEMP Exterior color: Red Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of Conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 28/04/2026 Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report. Condition: Used	10€
---	-----	---	-----

		Quantity: 1	
	148	Make: Nissan Model: NV400 Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 28/05/2020 Fuel: Diesel Odometer reading (km): 98510 Chassis number: VNVM1000664762968 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2299 Engine power (kW): 100 Emission class: Euro 6d-TEMP Exterior color: Red Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 14/12/2024 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.	100€

		Condition: Used Quantity: 1	
	165	Make: Peugeot Model: Boxer Year of manufacture (yyyy): 2008 First registration (dd/mm/yyyy): 18/02/2008 Fuel: Diesel Odometer reading (km): 99,495 Chassis number: VF3YCBMFB11297447 Number of keys: 3 Vehicle category: N1: max. weight <3.5 t Body: Ambulance Number of seats: 3 Number of axles: 2 Transmission: Manual Emission class: Euro 4 Exterior color: Yellow Interior color: Gray Upholstery: Partial leather Power windows: Yes Radio: Yes Additional information: Equipped as an ambulance with a stretcher and wheelchair Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 13/07/2023 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1	10€



174

Make: Renault
Model: Master
Year of manufacture (yyyy): 2018
First registration (dd/mm/yyyy): 02/01/2019
Fuel: Diesel
Odometer reading (km): 337,890
Chassis number: VF1MA000X62154533
Number of keys: 1
Vehicle category: N1: max. weight <3.5 t

10€

Body: Panel van
Number of seats: 3
Number of axles: 2
Permitted Gross Vehicle Weight (kg): 3500
Transmission: Manual transmission
Engine capacity (cc): 2299
Engine power (kW): 96
Emission class: Euro 6b
Exterior color: White
Interior color: Black
Upholstery: Fabric
Reversing camera: Yes
Air conditioning: Manual air conditioning
Trip computer: Yes
Power windows: Yes
Fog lights: Yes
Navigation: Yes
Rear parking sensors: Yes
Radio: Yes
Other options: Suspension seat
Registration certificate: Not available: the buyer will receive a certificate of loss of registration
Certificate of Conformity: Yes, available
CARPASS: Yes, available
Identification report: Yes, available
Inspection certificate: Yes, available
Inspection certificate valid until (dd/mm/yyyy): July 15, 2025
Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.
Description of vehicle damage: sliding door does not open, sound damaged
Condition: Used
Quantity: 1



	176	Make: Citroen Model: Berlingo Year of manufacture (yyyy): 2012 First registration (dd/mm/yyyy): 27/03/2013 Fuel: Diesel Odometer reading (km): 225367 Chassis number: VF77B9HN0DJ588567 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 1945 Transmission: Manual Cylinder capacity (cc): 1560 Engine power (kW): 55 Emission class: Euro 5b CO2 emissions (g/km): 133 Exterior color: White Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Power windows: Yes Fog lights: Yes Radio: Yes Tow bar: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration Certificate of Conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): February 17, 2026 Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: left trunk door	10€



		partially hanging loose Condition: Used Quantity: 1	
	178	Make: Ford Model: Fiesta Year of manufacture (yyyy): 2016 First registration (dd/mm/yyyy): 29/07/2016 Fuel: Petrol Odometer reading (km): 102628 Chassis number: WF0RXXGAKRGD16279 Number of keys: 4 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 1500 Transmission: Manual transmission Engine capacity (cc): 998 Engine power (kW): 59 Emission class: Euro 6b Exterior color: White Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Multifunction steering wheel: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 11/08/2026 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Vehicle does not start, engine defective Condition: Used	10€



		Quantity: 1	
	310	Make: Peugeot Model: Partner Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 03/05/2019 Fuel: Diesel Odometer reading (km): 139291 Chassis number: VR3EFYHZRKJ571451 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2370 Transmission: Automatic Engine capacity (cc): 1499 Engine power (kW): 96 Emission class: Euro 6d-TEMP CO2 emissions (g/km): 158 Exterior color: Black Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Shift paddles: Yes Registration certificate: Yes, available Certificate of Conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 07/05/2026	10€



		Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1	
--	--	---	--