

CATALOG

Dumper BELL B40E

DESCRIPTION	This auction features a 2020 BELL ADT B40E 6x6 dump truck. This machine is equipped with a Mercedes OM 471 engine, Allison transmission, and 6x6 drivetrain, and is used worldwide in heavy industry and earthmoving.
START	4 november 2025 to 09:00 [UTC]
END DATE	14 november 2025 from 14:00 [UTC]
VIEWING	Only by appointment through the organizer. Wednesday November 12 2025 from 14:30 until 15:00 BE-6220 HEPPIGNIES, ROUTE DE GOSSLIES 568
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
ISSUE - COLLECTION	--- Thursday November 20 2025 from 10:00 until 12:00 BE-6220 HEPPIGNIES, ROUTE DE GOSSLIES 568

Online bidding only!

Catalog created on 30 october 2025 to 05:01



	Item	Description	Start price
	1	Brand: BELL Model: ADT B40E 6X6 Dump Truck Type: Articulated Dump Truck Year of Manufacture (YYYY): 2020 Odometer Reading (Hours): 4297 Serial Number: B93A640EL03007443 Fuel: Diesel Engine Power kW: 361 Number of Keys: 1 Exterior Color: Yellow Reversing Camera: Yes Air Conditioning: Manual Air Conditioning Lighting: Yes Heating: Yes Other Options: Equipped with a radio, rearview mirror, and trip computer Additional Information: Engine: MERCEDES OM 471 LA Serial Number: 471 945 C 0586827 Transmission: Model: Allison 4700 ORS Serial Number: 6620037951 Transfer case: Model: W3866 Serial number: 809472 Front differential Model: SC 461 Serial number: HNO 7810738 Mid-axle differential: Model: TC 461	37.500€



		Serial number: HNO 7799326 Rear differential: Model: SC 461 Serial number: HNO 7810732 6x Tire size: 39.5R25-GP40 Maintenance booklet: A complete history is available upon request. Please find the FR brochure in Appendix 1. Registration certificate not applicable: This vehicle cannot be registered and is only transported in exceptional convoy. It works in quarries, sand pits, or closed construction sites, never on public roads. Registration certificate: Not available, see additional information Certificate of Conformity: Yes, available Inspection certificate: Not applicable Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Condition: Used Quantity: 1	
--	--	---	--