



**CATALOG**  
Motorcycles & mopeds

<b>DESCRIPTION</b>	Auction of various motorcycles and mopeds
<b>START</b>	8 december 2025 to 09:00 [UTC]
<b>END DATE</b>	18 december 2025 from 17:30 [UTC]
<b>VIEWING</b>	<ul style="list-style-type: none"><li>--- Wednesday December 10 2025 from 15:00 until 17:00 Helststraat 47, 2630 Aartselaar</li></ul>
<b>AUCTIM PARTNER</b>	<b>MOYERSOEN NV</b> Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
<b>ISSUE - COLLECTION</b>	<ul style="list-style-type: none"><li>--- Tuesday December 30 2025 from 10:00 until 12:00 Helststraat 47, 2630 Aartselaar</li></ul>

**Online bidding only!**

Catalog created on 18 december 2025 to 04:03



	Item	Description	Start price
	140	<p>Brand: Yamaha Model: X-Max</p> <p>Version: 400 Year of manufacture (yyyy): 2014 First registration (dd/mm/yyyy): 19/02/2014 Fuel: Petrol Odometer reading (km): 14103 Chassis number: VG5SH072000001606 Motorcycle type: Scooter Transmission: Semi-automatic transmission Engine capacity (cc): 395 Engine power (kW): 23 Emission class: Euro 3 Exterior color: White Number of keys: 2 Number of seats: 2 Electric starter: Yes Top case: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Maintenance booklet: Not present Visible vehicle damage: No Excluding general wear and tear. (General wear and tear includes all damage that would be expected given the age and mileage or hours of use.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	100€
	416	<p>Brand: Ligier Model: Pulse 3 Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 29/11/2019 Fuel: Electric Odometer reading (km): 17916 Chassis number: VJRC2BB2X00009040 Motorcycle type: Scooter</p>	100€



		<p>Transmission: Automatic Engine power kW: 3.6 Emission class: Euro 4 Exterior color: White Number of keys: 1 Number of seats: 1 Electric starter: Yes Additional information: Vehicle category: L2e-P Registration certificate: Yes, available Certificate of conformity: Yes, available Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the Consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--