



**CATALOG**  
COMMERCIAL VEHICLES

<b>DESCRIPTION</b>	Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.
<b>START</b>	8 january 2026 to 09:00 [UTC]
<b>END DATE</b>	15 january 2026 from 17:00 [UTC]
<b>VIEWING</b>	<ul style="list-style-type: none"><li>---</li><li>Wednesday January 14 2026 from 10:00 until 12:00 Helststraat 47, 2630 Aartselaar</li></ul>
<b>AUCTIM PARTNER</b>	<b>MOYERSOEN NV</b> Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
<b>ISSUE - COLLECTION</b>	<ul style="list-style-type: none"><li>---</li><li>Wednesday January 21 2026 from 10:00 until 12:00 Helststraat 47, 2630 Aartselaar</li></ul>

**Online bidding only!**

Catalog created on 15 january 2026 to 04:02



	Item	Description	Start price
	5	<p>Make: Renault Model: Master Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 01/12/2024 Fuel: Diesel Odometer reading (km): 31922 Chassis number: VF1RDA00173906750 Number of keys: 3 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 1997 Engine power (kW): 110 Emission class: Euro 6e Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Fabric Reversing camera: Yes Air conditioning: Semi-automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Other options: Q-Top roof rack Ladder Registration certificate: Yes Available</p> <p>Certificate of Conformity: Yes, available Identification Report: Yes, available</p>	100€



		<p>Inspection Certificate: Yes, available Inspection Certificate Valid Until (dd/mm/yyyy): 04/12/2025 Maintenance Booklet: Not available Visible Vehicle Damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle Damage Description: Rear Left</p> <p>Lower Right Side</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	11	<p>Make: Nissan Model: NV300</p> <p>Version: L2H1 2.0 dCi 145 Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 21/06/2021</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 155,491 Chassis number: VNVF4000267037186 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2900 Transmission: Automatic Cylinder capacity (cc): 1997 Engine power (kW): 107 Emission class: Euro 6 Exterior color: Gray</p>	100€



		<p>Metallic paint: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Other options: Roof rack with long roof box Additional information: Includes remaining waste Registration certificate: Not available: the buyer will receive a certificate of loss Registration certificate Certificate of Conformity: Not available: the buyer will receive a certificate of loss of the certificate of conformity Inspection certificate: Not available Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: cracked windshield missing side window maintenance report Invoice amount (€ incl. VAT): €27,907.08 Invoice date (dd/mm/yyyy): 09-06-2021</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	12	<p>Make: Renault Model: Trafic Version: Confort L1H1 dCi Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 24/05/2024 Fuel: Diesel</p>	100€



		<p>Odometer reading (km): 50,232 Chassis number: VF1FL000572916915 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Crew cab van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3010 Transmission: Manual Engine capacity (cc): 1997 Engine power (kW): 96 Emission class: Euro 6e CO2 emissions g/km: 184 Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Other options: crew cab Registration certificate: Not available: the buyer will receive a certificate of loss of registration Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 22/07/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Flat left rear tire Condition: Used</p>	
--	--	---	--



		Quantity: 1	
	13	<p>Make: Mercedes-Benz Model: V 300 d Version: Avantgarde</p> <p>Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 01/06/2021</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 151332 Chassis number: WDF44781313661688 Number of keys: 2 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2820 Transmission: Automatic Engine capacity (cc): 1950 Engine power (kW): 176 Emission class: Euro 6 CO2 emissions (g/km): 154 Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power tailgate: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes</p>	100€



		<p>Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Seat heating: Yes Additional information: Vehicle category: N1 - Van! Rear seats with seats present!</p> <p>Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 13/06/2026 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: various damage Condition: Used Quantity: 1</p>	
	14	<p>Make: Fiat Model: Ducato Version: Fourgon Toile L2H2 - 2.2 Turbo Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 24/09/2024 Fuel: Diesel Odometer reading (km): 20374 Chassis number: ZFA250004R2Z86734 Number of keys: 2 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2184</p>	100€



		<p>Engine power (kW): 103 Emission class: Euro 6e Exterior color: White</p> <p>Metallic body: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes Available Inspection certificate valid until (dd/mm/yyyy): 18/10/2026 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Invoice amount (€ incl. VAT): €33,753.07 Invoice date (dd/mm/yyyy): 23-09-2024 Condition: Used Quantity: 1</p>	
	17	<p>Make: Ford Model: Transit Version: 2.0 TDCI Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 11/01/2022 Fuel: Diesel Odometer reading (km): 84,819 Chassis number: WF0FXXTTRFMD37104 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p>	100€



Body: Panel van  
Number of seats: 3  
Number of axles: 2  
Permitted Gross Vehicle Weight (kg): 3500  
Transmission: Automatic  
Engine capacity (cc): 1995  
Engine power (kW): 125  
Emission class: Euro 6  
Exterior color: Gray

Metallic body: Yes  
Interior color: Black

Upholstery: Fabric  
Reversing camera: Yes  
Air conditioning: Manual air conditioning  
Trip computer: Yes  
Central locking: Yes  
Cruise control: Yes  
Power folding mirrors: Yes  
Power windows: Yes  
Alloy wheels: Yes  
Fog lights: Yes  
Multifunction steering wheel: Yes  
Rear parking sensors: Yes  
Front parking sensors: Yes  
Radio: Yes  
Tow bar: Yes  
Other options: Double Cabin

Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate.

Certificate of Conformity: Yes, available  
CARPASS: Yes, available  
Identification report: Yes, available

Inspection certificate: Yes, available

Inspection certificate valid until (dd/mm/yyyy):  
14/12/2025

Maintenance booklet: Not available  
Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult



		<p>the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	18	<p>Make: Iveco Model: 35S18</p> <p>Version: HA8</p> <p>Year of manufacture (yyyy): 2023</p> <p>First registration (dd/mm/yyyy): 15/04/2024</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 47981 Chassis number: ZCFC535C405547545 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Crew cab van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2998 Engine power (kW): 129 Emission class: Euro 6 Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Full leather Reversing camera: Yes</p> <p>Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes</p>	100€



		<p>Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Tow bar: Yes Other options: Additional signaling Additional door locks with key Crew cab Additional information: Start with booster! Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 07/01/2026 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Start with booster! Invoice amount (€ incl. VAT): 67760 Invoice date (dd/mm/yyyy): 11/04/2024</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	19	<p>Make: Iveco Model: 35C21</p> <p>Year of manufacture (yyyy): 2024</p> <p>First registration (dd/mm/yyyy): 14/08/2024</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 15,113</p> <p>Chassis number: ZCFCE35F605653277</p>	100€



		<p>Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: panel van with flatbed Number of seats: 7 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Automatic Engine capacity (cc): 2998 Engine power (kW): 152 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: Yes Interior color: Black</p> <p>Upholstery: Full leather Reversing camera: Yes Air conditioning: Semi-automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Tow bar: Yes Additional information: Equipped with a touchscreen, signaling system, and flatbed. Dimensions: 4100 x 2100 x 4100 cm 400mm with aluminum side panels and an ADF cover. Registration certificate: Not available: the buyer will receive a certificate of loss of registration. Certificate of Conformity: Yes, available. Identification report: Yes, available. Inspection certificate: Yes, available. Inspection certificate valid until (dd/mm/yyyy): 26/08/2025. Maintenance booklet: Not available. Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the age and mileage or hours.) For a detailed overview, please consult the photo report.</p>	
--	--	---	--



		Condition: Used Quantity: 1	
	21	<p>Make: Man Model: Tgl 12.180 Year of manufacture (yyyy): 2014</p> <p>First registration (dd/mm/yyyy): 27/11/2014 Fuel: Diesel Odometer reading (km): 93,336 Chassis number: WMAN15ZZ9FY323106 Number of keys: 5 Category: N2: max. weight &gt;3.5 t - &lt;12 t</p> <p>Number of axles: 2 Permitted Gross Vehicle Weight (kg): 11990 Transmission: Automatic Cylinder capacity (cc): 4580 Engine power (kW): 132 Emission class: Euro 6 Exterior color: White Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Power windows: Yes Air suspension seat: Yes Radio: Yes Tachograph: Yes Additional information: Equipped with various storage cabinets and a work table with a vice Roller shutter code: 3333 Registration certificate: Yes, available Certificate of Conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Visible vehicle damage: Yes, for a detailed inspection report You can always consult the photo report for an overview of the visible damage.</p>	100€



		Condition: Used Quantity: 1	
	40	<p>Make: Mercedes-Benz Model: Sprinter Version: 317 CDI L3 Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 17/10/2023 Fuel: Diesel Odometer reading (km): 113,458 Chassis number: W1V3KCFZ1RP629875 Number of keys: 2 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Automatic Engine capacity (cc): 1950 Engine power (kW): 125 Emission class: Euro 6 Exterior color: White</p> <p>Metallic paint: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes</p>	100€



		<p>Seat heating: Yes Registration certificate: Yes Available Certificate of Conformity: Yes, available Identification Report: Yes, available Inspection Certificate: Yes, available Inspection Certificate Valid Until (dd/mm/yyyy): 19/10/2025 Maintenance Booklet: Not available Visible Vehicle Damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Description of Vehicle Damage: Tire Pressure Message Cracked Windshield Various Damage! Invoice Amount (€ incl. VAT): 58806 Invoice Date (dd/mm/yyyy): 23-10-2023</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	41	<p>Make: Addax Model: MTN</p> <p>Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 22/03/2021</p> <p>Fuel: Electric</p> <p>Odometer reading (km): 7425 Chassis number: YBDNUL600FA000298 Number of keys: 2 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Utility vehicle Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 1840 Transmission: Automatic Engine power (kW): 12.50</p>	100€



		<p>Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Leatherette</p> <p>Reversing camera: Yes Trip computer: Yes Central locking: Yes Radio: Yes Other options: Equipped with 2 roller doors and 2 rear doors. Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 27/03/2026 Maintenance booklet: Not present Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the vehicle's age and mileage or hours.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	44	<p>Make: Ford Model: Transit Version: 2T 350L L3 Trend Electric Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 29/02/2024 Fuel: Electric Odometer reading (km): 41239 Chassis number: WF0EXXTTRBNA89551 Number of keys: 4 Vehicle category: N1: max. weight &lt;3.5 t</p>	100€



Body: Panel van  
Number of seats: 3  
Number of axles: 2  
Permitted Gross Vehicle Weight (kg): 3500  
Transmission: Automatic  
Engine power kW: 135  
Exterior color: White

Metallic body: No  
Interior color: Black  
Upholstery: Fabric  
Reversing camera: Yes  
Air conditioning: Fully automatic air conditioning  
Trip computer: Yes  
Central locking: Yes  
Cruise control: Yes  
Power folding mirrors: Yes  
Power windows: Yes  
Fog lights: Yes  
Multifunction steering wheel: Yes  
Navigation: Yes  
Rear parking sensors: Yes  
Front parking sensors: Yes  
Radio: Yes  
Seat heating: Yes  
Equipped with electric charging cable: Available  
Registration certificate: Yes, available  
Certificate of conformity: Yes Available  
Identification report: Yes, available  
Inspection certificate: Yes, available  
Inspection certificate valid until (dd/mm/yyyy):  
22/10/2025  
Maintenance booklet: Not available  
Visible vehicle damage: Yes, for a detailed  
overview of the visible damage, please consult  
the photo report.  
Description of vehicle damage: Various damage  
Crack in the windshield  
Invoice amount (€ incl. VAT): 59651  
Invoice date (dd/mm/yyyy): 14-03-2024  
Condition: Used

Quantity: 1



	105	<p>Make: Opel Model: Movano Version: Citybox F3500 Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 15/11/2021 Fuel: Diesel Odometer reading (km): unknown (min. 200,000km) Chassis number: W0VVS2607MB257224 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Truck Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Cylinder capacity (cc): 2299 Engine power (kW): 120 Emission class: Euro 6 Exterior color: Black</p> <p>Metallic body: No</p> <p>Interior color: Black Upholstery: Fabric Power windows: Yes Other options: Equipped with a D'Hollandia tail lift Additional information: Vehicle will not start! Engine damage: hole in the engine!</p> <p>Mileage unknown, battery defective Registration certificate: Yes, available</p> <p>Certificate of Conformity: Yes, available Identification report: Yes, available</p> <p>Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 03/12/2024 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed</p>	10€
---	-----	--	-----



		<p>overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: Engine damage: hole in the engine!!</p> <p>Vehicle does not start! Mileage unknown, battery defective. Condition: Used</p> <p>Quantity: 1</p>	
	213	<p>Make: Citroën Model: Jumper Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 03/04/2019 Fuel: Diesel Odometer reading (km): 173,469 Chassis number: VF7YD3MFC12K34409 Number of keys: 2 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 6 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 1997 Engine power (kW): 120 Emission class: Euro 6b Exterior color: White</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes</p>	100€



		<p>Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: Crew cab Registration certificate: Yes, available Certificate of Conformity: Yes, available Inspection certificate: Yes Available Inspection certificate valid until (dd/mm/yyyy): May 26, 2026 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: chip in the windshield driver's seat</p> <p>Condition: Used Quantity: 1</p>	
	214	<p>Make: Ford Model: Transit</p> <p>Version: Custom Year of manufacture (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 12/02/2019 Fuel: Diesel Odometer reading (km): 348513 Chassis number: WF0YXXTTGYJA65748 Number of keys: 2 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3200 Transmission: Manual transmission Engine capacity (cc): 1995 Engine power (kW): 96</p>	100€



		<p>Emission class: Euro 6b Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, available Certificate of Conformity: Yes Available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 11/07/2025 Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Various damage Star in the windshield</p> <p>Condition: Used Quantity: 1</p>	
	229	<p>Make: Citroën Model: Jumper Year of manufacture (yyyy): 2018 First registration (dd/mm/yyyy): 19/04/2018 Fuel: Diesel Odometer reading (km): 357607 Chassis number: VF7YC3MFC12G34036</p>	100€



		<p>Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Engine capacity (cc): 1997 Engine power (kW): 120 Emission class: Euro 6b CO2 emissions (g/km): 159 Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: Fitted cargo space Registration certificate: Yes, available</p> <p>Certificate of Conformity: Yes, available</p> <p>Identification report: Yes, available</p> <p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 23/04/2026 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p>	
--	--	--	--



		<p>Description of vehicle damage: The key does not fit in the lock, but it does fit in the ignition.</p> <p>Various damages Condition: Used</p> <p>Quantity: 1</p>	
	230	<p>Make: Ford Model: Transit</p> <p>Version: Custom Year of manufacture (yyyy): 2015 First registration (dd/mm/yyyy): 05/06/2015 Fuel: Diesel Odometer reading (km): 360,836 Chassis number: WF0ZXXTTGZEB85244 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 6 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2900 Transmission: Manual transmission Engine capacity (cc): 2198 Engine power (kW): 114 Emission class: Euro 5b CO2 emissions (g/km): 191 Exterior color: Black</p> <p>Metallic body: No</p> <p>Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes</p>	100€



		<p>Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Other options: crew cab Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present Identification Report: Yes, present</p> <p>Inspection Certificate: Yes, present Inspection Certificate Valid Until (dd/mm/yyyy): 05/07/2026</p> <p>Maintenance Booklet: Not present Visible Vehicle Damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of Vehicle Damage: Chips in the Windshield</p> <p>Various Damage</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	248	<p>Make: Renault Model: Master Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 29/05/2019 Fuel: Diesel Odometer reading (km): 166294 Chassis number: VF1MA000562634012 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van</p>	10€



		<p>Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Engine capacity (cc): 2299 Engine power (kW): 96 Emission class: Euro 6b Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Power windows: Yes Tow bar: Yes Other options: Ladder Roof rack Furnished cargo area Additional information: Vehicle will not start!</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Not available: the buyer will receive a certificate of loss of conformity certificate. Inspection certificate: Not available Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: Vehicle does not start!</p> <p>Various damages!</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--