



**CATALOG**  
Commercial vehicles

<b>DESCRIPTION</b>	Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.
<b>START</b>	29 january 2026 to 09:00 [UTC]
<b>END DATE</b>	5 february 2026 from 17:00 [UTC]
<b>VIEWING</b>	<ul style="list-style-type: none"><li>--- Wednesday February 04 2026 from 15:00 until 17:00 BE-2630 AARTSELAAR, HELSTSTRAAT 47</li></ul>
<b>AUCTIM PARTNER</b>	<b>MOYERSOEN NV</b> Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
<b>ISSUE - COLLECTION</b>	<ul style="list-style-type: none"><li>--- Wednesday February 11 2026 from 10:00 until 12:00 BE-2630 AARTSELAAR, HELSTSTRAAT 47</li></ul>

**Online bidding only!**

Catalog created on 5 february 2026 to 04:06



	Item	Description	Start price
	43	<p>Make: Peugeot Model: Expert Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 05/06/2020 Fuel: Diesel Odometer reading (km): 144599 Chassis number: VF3VFAHKKL7017695 Number of keys: 2 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3100 Transmission: Manual Cylinder capacity (cc): 1997 Engine power (kW): 90 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Partial leather Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes Available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 17/02/2026</p>	100€



		Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: various damages Condition: Used Quantity: 1	
	44	Make: Ford Model: Transit Version: 2T 350L L3 Trend Electric Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 29/02/2024 Fuel: Electric Odometer reading (km): 41239 Chassis number: WF0EXXTTRBNA89551 Number of keys: 4 Vehicle category: N1: max. weight <3.5 t  Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Automatic Engine power kW: 135 Exterior color: White  Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes	100€



		<p>Radio: Yes Seat heating: Yes Equipped with electric charging cable: Available Registration certificate: Yes, available Certificate of conformity: Yes Available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 22/10/2025 Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Various damage Crack in the windshield Invoice amount (€ incl. VAT): 59651 Invoice date (dd/mm/yyyy): 14-03-2024 Condition: Used</p> <p>Quantity: 1</p>	
	51	<p>Make: Dodge Model: Ram 1500 Version: E-Torque Limited Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 02/06/2022 Fuel: LPG/gasoline Odometer reading (km): 82,759 Chassis number: 1C6SRFHT1NN135134 Number of keys: 2 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Pickup Number of seats: 5 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Automatic Engine capacity (cc): 5654 Engine power (kW): 295 Emission class: Euro 6d-TEMP Exterior color: Black</p>	100€



		<p>Metallic body: No Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Power seats: Yes Head-up display: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic Roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat ventilation: Yes Tow bar: Yes Seat heating: Yes Other options: Heated steering wheel Electric step Electric seats with memory function</p> <p>Diamondback cover Harman/Kardon sound system Additional information: Equipped with a Prins 120-liter LPG system Registration certificate: Yes, available Certificate of Conformity: Yes, available CARPASS: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 30/07/2026 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Invoice amount (€ incl. VAT): €93,525</p> <p>Invoice date (dd/mm/yyyy): April 19, 2022</p>	
--	--	---	--



		Condition: Used Quantity: 1	
	52	Make: Fiat Model: Ducato Version: 150 Multijet Year of manufacture (yyyy): 2011 First registration (dd/mm/yyyy): 04/01/2012 Fuel: Diesel Odometer reading (km): 285,193 Chassis number: ZFA25000002124486 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t  Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3300 Transmission: Manual transmission Engine capacity (cc): 2287 Engine power (kW): 109 Emission class: Euro 5 Exterior color: White  Metallic body: No  Interior color: Black  Upholstery: Fabric Central locking: Yes Power windows: Yes  Radio: Yes Other options: Alurack roof rack Additional information: Vehicle will not start!  Side door is loose  Registration certificate: Yes, available	100€



		<p>Certificate of Conformity: Yes, available</p> <p>Identification report: Yes, available</p> <p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 10/01/2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: Vehicle will not start! Side door is loose</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	54	<p>Make: Mercedes-Benz Model: Sprinter Version: 319 CDI GB L3 RWD Year of manufacture (yyyy): 2024</p> <p>First registration (dd/mm/yyyy): 13/02/2024 Fuel: Diesel Odometer reading (km): 53,899 Chassis number: W1V3MCFZ8RP675214 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Crew-cab van Number of seats: 6 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Automatic Engine capacity (cc): 1950 Engine power (kW): 140 Emission class: Euro 6 CO2 emissions (g/km): 280 Exterior color: Gray</p>	100€



		<p>Metallic body: Yes</p> <p>Interior color: Black</p> <p>Upholstery: Leatherette</p> <p>Reversing camera: Yes</p> <p>Air conditioning: Fully automatic climate control</p> <p>Trip computer: Yes</p> <p>Central locking: Yes</p> <p>Cruise control: Yes</p> <p>Power-folding mirrors: Yes</p> <p>Power windows: Yes</p> <p>LED lighting: Yes</p> <p>Fog lights: Yes</p> <p>Multifunction steering wheel: Yes</p> <p>Navigation: Yes</p> <p>Rear parking sensors: Yes</p> <p>Front parking sensors: Yes</p> <p>Radio: Yes</p> <p>Tow bar: Yes</p> <p>Additional information: Vehicle has difficulty starting</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 15/02/2026</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: Vehicle has difficulty starting</p> <p>Invoice amount (€ incl. VAT): 79618</p> <p>Invoice date (dd/mm/yyyy): 19-02-2024</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	--	--



	55	<p>Make: Opel Model: Movano Version: BI Turbo F3500 Year of manufacture (yyyy): 2018 First registration (dd/mm/yyyy): 28/06/2018 Fuel: Diesel Odometer reading (km): 221108 Chassis number: W0VMRS601JB151497 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Emission class: Euro 6b Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Leatherette Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Fog lights: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Seat ventilation: Yes Tow bar: Yes Other options: Vehicle equipped with various tool racks Vehicle equipped with door locks (keyless) Additional information: Vehicle is being sold under the supervision of bailiff Johan Vanquatem. Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate.</p>	100€
---	----	--	------



		<p>Certificate of conformity: Not available: the buyer will receive a certificate of loss of conformity certificate. Inspection certificate: Not available</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: damaged sliding door handle + door locks (door does not open)</p> <p>various damage!</p> <p>various dashboard notifications</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	90	<p>Make: Nissan Model: Interstar Version: X62FGBN35-10 Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 27/03/2024 Fuel: Diesel Odometer reading (km): 32749 Chassis number: VNVM1000871655990 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2299 Engine power (kW): 110 Emission class: Euro 6e Exterior color: White</p> <p>Metallic body: No</p>	100€



		<p>Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Tow bar: Yes Additional information: Includes remaining contents: old freezer and waste. Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 03/04/2025</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: various damages Condition: Used</p> <p>Quantity: 1</p>	
	103	<p>Brand: Citroën Model: Jumpy Year of manufacture (yyyy): 2014 First registration (dd/mm/yyyy): 30/06/2014 Fuel: Diesel Odometer reading (km): 309,452</p>	100€



		<p>Chassis number: VF7XS9HM0EZ016016 Number of keys: 1 Vehicle category: N1: max. weight &lt;3.5 t</p> <p>Body: Panel van Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2661 Transmission: Manual Engine capacity (cc): 1560 Engine power (kW): 66 Emission class: Euro 5b Exterior color: Green</p> <p>Metallic body: No</p> <p>Interior color: Gray</p> <p>Upholstery: Cloth Air conditioning: Manual air conditioning Power windows: Yes Radio: Yes Additional information: Side and rear doors do not open!</p> <p>Side door handle defective Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Not available: the buyer will receive a certificate of loss of conformity certificate Inspection certificate: Not available Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: various damages Condition: Used Quantity: 1</p>	
--	--	---	--