



CATALOG
Passenger cars

DESCRIPTION	Auction of passenger cars from various bankruptcies, seizures, breaches of contract, end of leasing, etc.
START	29 january 2026 to 09:00 [UTC]
END DATE	5 february 2026 from 18:00 [UTC]
VIEWING	<ul style="list-style-type: none">--- Wednesday February 04 2026 from 15:00 until 17:00 BE-2630 AARTSELAAR, HELSTSTRAAT 47
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
ISSUE - COLLECTION	<ul style="list-style-type: none">--- Wednesday February 11 2026 from 10:00 until 12:00 BE-2630 AARTSELAAR, HELSTSTRAAT 47

Online bidding only!

Catalog created on 5 february 2026 to 04:12



	Item	Description	Start price
	17	<p>Make: Audi Model: A6</p> <p>Version: S-line Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 11/02/2021 Fuel: Hybrid - Electric/Gasoline Odometer reading (km): 54670 Chassis number: WAUZZZF29MN045101 License plate: 1BFT872 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Sedan Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1984 Engine power (kW): 185 Emission class: Euro 6d-TEMP Exterior color: Black</p> <p>Metallic paint: No Interior color: Black Upholstery: Partial leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Sport seats: Yes Seat heating: Yes Equipped with electric charging cable: Available Other options: Quattro all-wheel drive</p>	100€



		<p>S-Line exterior + interior Additional information: GE/2025/003 Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes, available Identification report: Yes Available Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): June 21, 2025</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	18	<p>Brand: Volkswagen Model: Golf</p> <p>Year of manufacture (yyyy): 2009</p> <p>First registration (dd/mm/yyyy): 14/10/2009 Fuel: Petrol Odometer reading (km): 94153 Chassis number: WVVZZZ1KZAW075879 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Estate Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1390 Engine power (kW): 90 Emission class: Euro 5 Exterior color: Black Interior color: Black Upholstery: Cloth Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes</p>	100€



		<p>Cruise control: Yes</p> <p>Electric folding Mirrors: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes</p> <p>Additional information: Vehicle has a French registration certificate and is equipped with an E705 sticker</p> <p>Registration certificate: Yes, present Certificate of Conformity: Not present. (Import within the European Union) Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 14/09/2022</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	19	<p>Make: Volkswagen Model: Golf GTI Year of manufacture (yyyy): 2005 First registration (dd/mm/yyyy): 27/07/2005 Fuel: Petrol Odometer reading (km): 238,147 Chassis number: WVWZZZ1KZ6P006890 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Estate Number of doors: 5-door Transmission: Manual Engine capacity (cc): 1984 Engine power (kW): 147 Emission class: Euro 4 Exterior color: Blue Interior color: Beige</p>	100€



		<p>Upholstery: Full leather Air conditioning: Manual air conditioning Central locking: Yes</p> <p>Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Additional information: Vehicle has a Dutch registration certificate and E705 sticker Registration certificate: Yes, present Certificate of Conformity: Not present. (Import within the European Union) Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	20	<p>Brand: Volkswagen Model: Golf GTE Year of manufacture (yyyy): 2015 First registration (dd/mm/yyyy): 30/0/2015 Fuel: Hybrid - Electric/Petrol Odometer reading (km): 163955 Chassis number: WVWZZZAUZFW805103 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Estate Transmission: Automatic Engine capacity (cc): 1395 Engine power (kW): 110 Emission class: Euro 6 Exterior color: Gray Interior color: Gray Upholstery: Cloth Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Electric Folding mirrors: Yes</p>	100€



		<p>Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Heated seats: Yes Additional information: Vehicle has French registration and E705 Vignette Registration certificate: Yes, available Certificate of Conformity: Not available. (Import within the European Union) Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	30	<p>Brand: Volvo Model: XC60 Version: Recharge R-Design T6 AWD Plug-In Hybrid Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 22/06/2021 Fuel: Hybrid - Electric/Gasoline Odometer reading (km): 59,078 Chassis number: YV1UZBFVDM1778180 License plate: 2BWT606 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1969 Engine power (kW): 186 Emission class: Euro 6d-TEMP Exterior color: Black Specific factory color: Onyx Black Metallic paint: Yes Interior color: Black</p> <p>Upholstery: Partial leather</p>	100€



		<p>Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power tailgate: Yes Power windows: Yes Power seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Sport seats: Yes Seat heating: Yes Other options: Steering wheel heating R-Design Power seats with Memory function Harman/Kardon sound system</p> <p>Registration certificate: Not present: the buyer will receive a certificate of loss of registration Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 22/06/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Invoice amount (€ incl. VAT): €58,902.98</p> <p>Invoice date (dd/mm/yyyy): 23-06-2021</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--



	31	<p>Brand: Mini Model: One</p> <p>Year of manufacture (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 19/04/2018 Fuel: Petrol Odometer reading (km): 103116 Chassis number: WMWXR11000TE55504 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 3-door Transmission: Manual Engine capacity (cc): 1499 Engine power (kW): 75 Emission class: Euro 6c Exterior color: Gray</p> <p>Metallic paint: Yes Interior color: Black</p> <p>Upholstery: Partial leather Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 11/07/2026 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: various damage</p>	100€
---	----	--	------



		Condition: Used Quantity: 1	
	32	Brand: Tesla Model: Model X Version: Long Range Plus Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 14/12/2020 Fuel: Electric Odometer reading (km): 107,287 Chassis number: 5YJXCCE26MF316334 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: MPV Number of doors: 5-door Transmission: Automatic Engine power kW: 219 Exterior color: White Metallic paint: No Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power tailgate: Yes Power windows: Yes Power seats: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Seat heating: Yes	100€



		<p>Equipped with electric charging cable: Available Other options: Rear gullwing doors Tow bar still to be installed 7 seats Heated steering wheel Autopilot Full Self-Driving capability Registration certificate: Yes, available Certificate of Conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): December 14, 2026</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Invoice amount (€ incl. VAT): 101170</p> <p>Invoice date (dd/mm/yyyy): December 23, 2020</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	53	<p>Brand: Volkswagen Model: Golf Version: GTE Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 17/03/2021 Fuel: Hybrid - Electric/Gasoline Odometer reading (km): 69728 Chassis number: WVVZZZCDZMW345387 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: City car Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1395 Engine power (kW): 110 Exterior color: White Metallic paint: No</p>	100€



		<p>Interior color: Black Upholstery: Fabric Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sport seats: Yes Equipped with electric charging cable: Present</p> <p>Registration certificate: Yes, present Certificate of Conformity: Yes, present CARPASS: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 17/03/2027 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: side mirror Condition: Used Quantity: 1</p>	
	60	<p>Make: Mercedes-Benz</p> <p>Model: C 200</p> <p>Version: D</p> <p>Year of manufacture (yyyy): 2022</p> <p>First registration (dd/mm/yyyy): 25/01/2023</p>	100€



Fuel: Hybrid - Electric/Diesel
Odometer reading (km): 88347
Chassis number: W1KAH0DB4PF079551
Number of keys: 2
Vehicle category: M1: passenger car
Vehicle type: Estate
Number of doors: 5-door
Transmission: Automatic
Engine capacity (cc): 1993
Engine power (kW): 120
Emission class: Euro 6
Exterior color: Black

Metallic paint: No
Interior color: Black
Upholstery: Fabric
Reversing camera: Yes
Air conditioning: Fully automatic air conditioning
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power-folding mirrors: Yes
Power tailgate: Yes
Power windows: Yes
Alloy wheels: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Navigation: Yes
Rear parking sensors: Yes
Front parking sensors: Yes
Radio: Yes
Heated seats: Yes
Additional information: Crack in the windshield
Registration certificate: Yes, available
Certificate of Conformity: Yes, available
CARPASS: Yes, available
Inspection certificate: Yes, available
Inspection certificate valid until (dd/mm/yyyy):
25/01/2027
Visible vehicle damage: Yes. For a detailed
overview of the visible damage, please consult
the photo report.
Vehicle damage description: crack in the
windshield



		Condition: Used Quantity: 1	
	80	Brand: Tesla Model: Model 3 Version: Long Range Dual Motor Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 19/03/2024 Fuel: Electric Odometer reading (km): 38,848 Chassis number: LRW3E7EK9RC077959 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Sedan Number of doors: 5-door Transmission: Automatic Engine power kW: 366 Exterior color: Gray Metallic paint: No Interior color: Black Upholstery: Leatherette Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power tailgate: Yes Power windows: Yes Power seats: Yes LED lighting: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Heated seats: Yes	100€



		<p>Equipped with electric charging cable: Available Other options: Autopilot 18" Photon rims Registration certificate: Yes, available Certificate of Conformity: Yes, available Inspection certificate: Not available Maintenance booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the car's age and mileage or hours.) For a detailed overview, please consult the photo report. Consult.</p> <p>Invoice amount (€ incl. VAT): 55980</p> <p>Invoice date (dd/mm/yyyy): 22-03-2024</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	81	<p>Brand: BMW Model: X3</p> <p>Version: xDrive 30e Year of manufacture (yyyy): 2022</p> <p>First registration (dd/mm/yyyy): 12/05/2022</p> <p>Fuel: Hybrid - Electric/Gasoline Odometer reading (km): 89330 Chassis number: WBA61DP0509L83611 Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 1998 Engine power (kW): 135 Emission class: Euro 6 Exterior color: Black</p>	100€



		<p>Specific factory color: Sapphire black Metallic paint: Yes Interior color: Brown Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power tailgate: Yes Power windows: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Shift paddles: Yes Sports package: Yes Sport seats: Yes Seat heating: Yes Equipped with electric charging cable: Available Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes Available Inspection certificate: Not available Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Invoice amount (€ incl. VAT): €68,843.99 Invoice date (dd/mm/yyyy): 09-05-2022</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	--	--



	84	<p>Brand: Mercedes-Benz</p> <p>Model: EQA 250</p> <p>Version: Business Solution</p> <p>Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 09/12/2021</p> <p>Fuel: Electric</p> <p>Odometer reading (km): 55363 Chassis number: W1N2437011J007528</p> <p>Number of keys: 2 Vehicle category: M1: passenger car Vehicle type: Estate Number of doors: 5-door</p> <p>Transmission: Automatic Engine power kW: 140 Exterior color: Gray</p> <p>Specific factory color: Mountain Gray</p> <p>Metallic paint: Yes Interior color: Black</p> <p>Upholstery: Partial leather Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power tailgate: Yes Power windows: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes</p>	100€
---	----	--	------



		<p>Shift paddles: Yes Sports package: Yes Sport seats: Yes Seat heating: Yes Equipped with electric charging cable: Available Other options: 18" AMG wheels AMG line</p> <p>Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 09/12/2027 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Invoice amount (€ incl. VAT): €54,758.02</p> <p>Invoice date (dd/mm/yyyy): 14-12-2021</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	89	<p>Brand: Lexus Model: NX350H Year of manufacture (yyyy): 2023</p> <p>First registration (dd/mm/yyyy): 10/08/2023</p> <p>Fuel: Hybrid - Electric/Gasoline Odometer reading (km): 74,543 Chassis number: JTJCKBEZ702001321 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: SUV or 4x4 Number of doors: 5-door Transmission: Automatic Engine capacity (cc): 2487 Engine power (kW): 140 Emission class: Euro 6</p>	100€



		<p>Exterior color: Green</p> <p>Metallic paint: Yes Interior color: Brown Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power tailgate: Yes Power windows: Yes Power seats: Yes LED lighting: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat ventilation: Yes Seat heating: Yes Other options: Steering wheel heating</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Not available: the buyer will receive a certificate of loss of conformity certificate Inspection certificate: Not available Maintenance booklet: Not available Present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--



AUCTIM
ONLINE AUCTIONS

AUCTIM - MOYERSON NV
Helststraat 47
2630 Aartselaar, Belgium
VAT BE 0452 153 622

www.auctim.com
info.moyersoem@auctim.be