



CATALOG
Commercial vehicles

DESCRIPTION	Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.
START	5 february 2026 to 09:00 [UTC]
END DATE	12 february 2026 from 17:00 [UTC]
VIEWING	<ul style="list-style-type: none">--- Wednesday February 11 2026 from 15:00 until 17:00 BE-2630 AARTSELAAR, HELSTSTRAAT 47
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
ISSUE - COLLECTION	<ul style="list-style-type: none">--- Wednesday February 18 2026 from 10:00 until 12:00 BE-2630 AARTSELAAR, HELSTSTRAAT 47

Online bidding only!

Catalog created on 12 february 2026 to 04:00



	Item	Description	Start price
	10	<p>Make: Mercedes-Benz</p> <p>Model: Sprinter</p> <p>Version: 314 CDI</p> <p>Year of manufacture (yyyy): 2019</p> <p>First registration (dd/mm/yyyy): 15/05/2019</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 212268</p> <p>Chassis number: WDB9076351P114439</p> <p>Number of keys: 1</p> <p>Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Permitted Gross Vehicle Weight (kg): 3500</p> <p>Transmission: Manual transmission</p> <p>Engine capacity (cc): 2143</p> <p>Engine power (kW): 105</p> <p>Emission class: Euro 6c</p> <p>Exterior color: Brown</p> <p>Metallic paint: No</p> <p>Interior color: Black</p> <p>Upholstery: Fabric</p> <p>Reversing camera: Yes</p> <p>Air conditioning: Fully automatic air conditioning</p> <p>Trip computer: Yes</p> <p>Central locking: Yes</p> <p>Power windows: Yes</p> <p>Multifunction steering wheel: Yes</p> <p>Radio: Yes</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration</p> <p>Certificate of conformity: Yes, available</p> <p>CARPASS: Yes, available</p>	100€



		<p>Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate Valid until (dd/mm/yyyy): June 18, 2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: various damages</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	22	<p>Make: Fiat Model: Ducato Version: 150 Multijet Year of manufacture (yyyy): 2011 First registration (dd/mm/yyyy): 04/01/2012 Fuel: Diesel Odometer reading (km): 294716 Chassis number: ZFA25000002124813 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3300 Transmission: Manual transmission Engine capacity (cc): 2287 Engine power (kW): 109 Emission class: Euro 5 Exterior color: White</p> <p>Metallic paint: No Interior color: Red/Black Upholstery: Fabric Central locking: Yes</p>	100€



		<p>Power windows: Yes Radio: Yes Tow bar: Yes Other options: Ladder</p> <p>Locks</p> <p>Additional information: Start with booster!</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 11/01/2026</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Various damage, including rust</p> <p>Start with booster!</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	45	<p>Make: Citroën Model: Jumper Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 20/11/2020 Fuel: Diesel Odometer reading (km): 119,099 Chassis number: VF7YDCNFC12P95360</p>	100€



		<p>Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Engine capacity (cc): 2179 Engine power (kW): 121 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, available Certificate of Conformity: Yes, available</p> <p>Identification report: Yes, available</p> <p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 10/06/2026</p> <p>Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p>	
--	--	--	--



		Quantity: 1	
	46	<p>Make: Renault Model: Master Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 16/07/2019 Fuel: Diesel Odometer reading (km): 116,117 Chassis number: VF6MF000963398129 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2299 Engine power (kW): 125 Emission class: Euro 6b Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, available Certificate of Conformity: Yes, available CARPASS: Yes, available Identification report: Yes, available Inspection certificate: Yes, available</p>	100€



		<p>Inspection certificate valid until (dd/mm/yyyy): 07/02/2026 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	48	<p>Make: Fiat Model: Ducato Version: 130 Multijet Year of manufacture (yyyy): 2015 First registration (dd/mm/yyyy): 17/06/2015 Fuel: Diesel Odometer reading (km): 244004 Chassis number: ZFA25000002875641 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2287 Engine power (kW): 96 Emission class: Euro 5b CO2 emissions g/km: 183 Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Trip computer: Yes Central locking: Yes Power windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Other options: Alurack roof rack</p>	100€



		<p>Registration certificate: Yes, available Certificate of Conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): June 25, 2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: Various damage</p> <p>Star in the windshield</p> <p>Gear lever</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	50	<p>Brand: Humbaur Model: KTA 3500-160 Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 10/03/2023 Trailer category: O2: max. weight >750kg - <3500kg Trailer type: Cable reel trailer Chassis number: WHDS3542BN1129977 Maximum Permissible Weight (kg): 3500 Internal dimensions (L x W x H) in mm: 2200x1600x2850 Additional information: Equipped with a hand winch and Simol outriggers.</p> <p>Trailer registration certificate: Yes, available</p> <p>Trailer conformity certificate: Yes, available</p> <p>Identification report: Yes, available</p>	100€



		<p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 15/03/2024</p> <p>Number of axles: 2</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: hand winch, electrical outlet, front lights.</p> <p>Invoice amount (€ incl. VAT): 10890</p> <p>Invoice date (dd/mm/yyyy): 16-03-2023</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	51	<p>Brand: Humbaur</p> <p>Model: KTA 3500-160</p> <p>Year of manufacture (yyyy): 2022</p> <p>First registration (dd/mm/yyyy): 13/03/2023</p> <p>Trailer category: O2: max. weight >750kg - <3500kg</p> <p>Trailer type: Cable reel trailer</p> <p>Chassis number: WHDS3542BN1129980</p> <p>Maximum Permissible Weight (kg): 3500</p> <p>Internal dimensions (L x W x H) in mm: 2200x1600x2850</p> <p>Additional information: Equipped with a hand winch, pulley block, and Simol support legs.</p> <p>Trailer registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate.</p> <p>Trailer conformity certificate: Not available: the buyer will receive a certificate of loss of conformity certificate.</p> <p>Inspection certificate: Not available</p> <p>Number of axles: 2</p> <p>Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all</p>	100€



		<p>damage that may be expected given the vehicle's age and mileage or hours.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	97	<p>Brand: Twintech Model: Twintrailer</p> <p>Year of manufacture (yyyy): 2019</p> <p>First registration (dd/mm/yyyy): 04/09/2019</p> <p>Trailer category: O2: max. weight >750kg - <3500kg</p> <p>Trailer type: Tipper Chassis number: YA9TT354019255104</p> <p>Maximum Permissible Weight (kg): 3500 Internal dimensions (L x W x H) in mm: 3960x1925 Additional information: Equipped with a tarpaulin, lock with key, loading ramp, and aluminum sidewalls. Electric tipping function.</p> <p>Trailer filled with garden waste.</p> <p>Trailer registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Trailer conformity certificate: Not available: the buyer will receive a certificate of loss of conformity certificate. Inspection certificate: Not available Number of axles: 2 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p>	100€



		Condition: Used Quantity: 1	
--	--	--------------------------------	--