



CATALOG
Commercial vehicles

DESCRIPTION	Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.
START	12 february 2026 to 09:00 [UTC]
END DATE	19 february 2026 from 17:00 [UTC]
VIEWING	<ul style="list-style-type: none">--- Wednesday February 18 2026 from 15:00 until 17:00 BE-2630 AARTSELAAR, HELSTSTRAAT 47
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
ISSUE - COLLECTION	<ul style="list-style-type: none">--- Wednesday February 25 2026 from 10:00 until 12:00 BE-2630 AARTSELAAR, HELSTSTRAAT 47

Online bidding only!

Catalog created on 19 february 2026 to 04:09



	Item	Description	Start price
	7	<p>Make: Toyota Model: Proace Version: City 1.5L Active</p> <p>Year of manufacture (yyyy): 2025 First registration (dd/mm/yyyy): 10/03/2025 Fuel: Diesel Odometer reading (km): 27,010 Chassis number: YAREDYHT2RJ023319 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2020 Transmission: Manual transmission Engine capacity (cc): 1499 Engine power (kW): 75 Emission class: Euro 6e Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 04/18/2026</p>	100€



		<p>Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Invoice amount (€ incl. VAT): €24,301.60</p> <p>Invoice date (dd/mm/yyyy): 02/27/2025</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	12	<p>Make: Renault Model: Trafic Version: Confort L1H1 dCi Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 24/05/2024 Fuel: Diesel Odometer reading (km): 50,232 Chassis number: VF1FL000572916915 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Crew cab van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3010 Transmission: Manual Engine capacity (cc): 1997 Engine power (kW): 96 Emission class: Euro 6e CO2 emissions g/km: 184 Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes</p>	100€



		<p>Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Other options: crew cab Registration certificate: Not available: the buyer will receive a certificate of loss of registration Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 22/07/2025 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Flat left rear tire Condition: Used Quantity: 1</p>	
	21	<p>Make: Renault Model: Master</p> <p>Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 16/01/2023 Fuel: Diesel Odometer reading (km): 62,453 Chassis number: VF1MA000X70465859 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Cylinder capacity (cc): 2299 Engine power (kW): 100</p>	100€



		<p>Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: Roof rack Glass rack Additional locks Fitted cargo area Registration certificate: Yes, available Certificate of Conformity: Yes Available</p> <p>CARPASS: Yes, available</p> <p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 05/06/2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Invoice amount (€ incl. VAT): 38667</p> <p>Invoice date (dd/mm/yyyy): 12-07-2023</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--



	89	<p>Make: Ford Model: Ranger Version: Crew Cab Wildtrak 2.0 Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 16/05/2024 Fuel: Diesel Odometer reading (km): 81672 Chassis number: 6FPPXXMJ2PRR66584 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Pickup Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3280 Transmission: Automatic Engine capacity (cc): 1996 Engine power (kW): 151 Emission class: Euro 6e Number of doors: 5-door Exterior color: Gray</p> <p>Metallic body: Yes Interior color: Black</p> <p>Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Power seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Seat heating: Yes Other options: heated steering wheel Registration certificate: Yes, present Certificate of conformity: Yes, present</p>	100€
---	----	---	------



		<p>Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 28/10/2025 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Scratched screen Dashboard handbrake message + tire pressure Invoice amount (€ incl. VAT): €51,903.33 Invoice date (dd/mm/yyyy): 21-05-2024</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	90	<p>Make: Citroën Model: Jumper Version: 2.2 BlueHDi L4H2 Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 19/02/2021 Fuel: Diesel Odometer reading (km): 70,753 Chassis number: VF7YDCNFC12R23740 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2179 Engine power (kW): 121 Emission class: Euro 6 Exterior color: Black</p> <p>Metallic paint: No Interior color: Black Upholstery: Fabric Reversing camera: Yes</p>	100€



		<p>Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available CARPASS: Yes Available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 05/07/2025 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: various damages Condition: Used Quantity: 1</p>	
	92	<p>Make: Fiat Model: Scudo Version: L3 1.5</p> <p>Year of manufacture (yyyy): 2023</p> <p>First registration (dd/mm/yyyy): 27/03/2023</p> <p>Fuel: Diesel Odometer reading (km): 84998 Chassis number: VXFVBYHRMP7800979 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2</p>	100€



		<p>Permitted Gross Vehicle Weight (kg): 2830 Transmission: Manual transmission Engine capacity (cc): 1500 Engine power (kW): 74 Emission class: Euro 6 CO2 emissions (g/km): 178 Exterior color: White</p> <p>Metallic paint: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Additional information: Belgian license plate/registration cancelled.</p> <p>Buyer must obtain the necessary documents for import.</p> <p>Registration certificate: Not available, see additional information</p> <p>Certificate of Conformity: Yes, available Identification report: Yes, available</p> <p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 31/05/2025</p> <p>Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: dashboard</p>	
--	--	--	--



		notifications Invoice amount (€ incl. VAT): €31,961.30 Invoice date (dd/mm/yyyy): 15-06-2023 Condition: Used Quantity: 1	
	99	Make: Renault Model: Master Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 27/08/2020 Fuel: Diesel Odometer reading (km): 103785 Chassis number: VF1VB000464123168 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t Body: Tipper Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2299 Engine power (kW): 110 Emission class: Euro 6d-TEMP Exterior color: White Interior color: Gray Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Power windows: Yes Tow bar: Yes Other options: Storage compartments Tipping function Additional information: Internal dimensions of	100€



		<p>loading platform: 3210x2000x350mm Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes Available Inspection certificate valid until (dd/mm/yyyy): 20/12/2024 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Various dashboard notifications Various damage Condition: Used</p> <p>Quantity: 1</p>	
	102	<p>Make: Addax Model: MTN</p> <p>Version: MT15X Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 26/04/2021</p> <p>Fuel: Electric</p> <p>Odometer reading (km): 7751 Chassis number: YBDNUL609FA000297 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Light truck Number of axles: 2 Permitted Gross Vehicle Weight (kg): 1840 Transmission: Automatic Engine power (kW): 12.50 Number of doors: 2-door Exterior color: White</p>	100€



		<p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Leatherette Reversing camera: Yes Central locking: Yes Other options: Equipped with a battery and an internal charger</p> <p>Additional information: Start with a booster!</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 04/05/2026</p> <p>Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: Start with booster!</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	--	--