



CATALOG
Commercial vehicles

DESCRIPTION	Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.
START	19 february 2026 to 09:00 [UTC]
END DATE	26 february 2026 from 17:00 [UTC]
VIEWING	<ul style="list-style-type: none">---Wednesday February 25 2026 from 15:00 until 17:00 BE-2630 Aartselaar, Helststraat 47
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
ISSUE - COLLECTION	<ul style="list-style-type: none">---Wednesday March 04 2026 from 10:00 until 12:00 BE-2630 Aartselaar, Helststraat 47

Online bidding only!

Catalog created on 26 february 2026 to 04:00



	Item	Description	Start price
	28	<p>Make: Peugeot Model: Partner Year of manufacture (yyyy): 2014 First registration (dd/mm/yyyy): 20/03/2014 Fuel: Diesel Odometer reading (km): 267,169 Chassis number: VF37B9HF0EJ578977 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 1990 Transmission: Manual Cylinder capacity (cc): 1560 Engine power (kW): 66 Emission class: Euro 5b Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Power windows: Yes Radio: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration Certificate of Conformity: Yes, available CARPASS: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): March 24, 2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p>	100€



		<p>Vehicle damage description: various damages</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	30	<p>Make: Dodge Model: RAM</p> <p>Version: 1500 Laramie 4x4 Year of manufacture (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 15/01/2018</p> <p>Fuel: LPG + Petrol Odometer reading (km): 88,214 Chassis number: 1C6RR7NT5JS164916 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Pickup Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Automatic Engine capacity (cc): 5654 Engine power (kW): 295 Emission class: Euro 6b Number of doors: 5-door Exterior color: Gray</p> <p>Metallic body: Yes Interior color: Black</p> <p>Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes</p>	100€



		<p>Power seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Sunroof: Yes</p> <p>Panoramic roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Seat ventilation: Yes Tow bar: Yes Seat heating: Yes Other options: Electric seats with memory function Heated steering wheel Alpine sound system</p> <p>Additional information: Defective screen!</p> <p>Registration certificate: Yes, present Certificate of Conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 08/04/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Defective screen! Condition: Used Quantity: 1</p>	
	33	<p>Brand: Dodge Model: RAM Version: 1500 Rebel GT Package Night Edition Crew Cab 4x4 Year of construction (yyyy): 2023 First registration (dd/mm/yyyy): 02/02/2023 Fuel: LPG + Petrol</p>	100€



		<p>Read odometer reading (km): 32701 Chassis number: 1C6SRFLT8NN472150 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body: Pickup Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Automatic Engine capacity (cc): 5654 Engine power (kW): 295 Emission class: Euro 6 Number of doors: 5-door Exterior color: White</p> <p>Metallic body: Yes Interior color: Black</p> <p>Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Power seats: Yes Head-up display: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Sunroof: Yes Panoramic Roof: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Sports seats: Yes Seat ventilation: Yes Tow bar: Yes Seat heating: Yes Other options: Power seats with memory function Harman Kardon sound system</p> <p>GT Package</p>	
--	--	--	--



		<p>Rebel model</p> <p>Equipped with Prins VSi2 200L LPG system</p> <p>Folding trunk lid Additional information: Start with booster!</p> <p>Registration certificate: Yes, available</p> <p>Certificate of Conformity: Yes, available</p> <p>CARPASS: Yes, available Identification report: Yes, available</p> <p>Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 08/02/2026</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Booster start!</p> <p>Front bumper Invoice amount (€ incl. VAT): 87120 Invoice date (dd/mm/yyyy): 22-02-2024 Condition: Used Quantity: 1</p>	
	35	<p>Make: Ford Model: Ranger</p> <p>Version: Double Cab Wildtrak 2.0 EcoBlue Year of manufacture (yyyy): 2024</p> <p>First registration (dd/mm/yyyy): 06/11/2024</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 20,749 Chassis number: 6FPPXXMJ2PRE49636 Number of keys: 2</p>	100€



		<p>Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Pickup Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3280 Transmission: Automatic Engine capacity (cc): 1996 Engine power (kW): 150 Emission class: Euro 6e CO2 emissions (g/km): 231 Number of doors: 5-door Exterior color: Black</p> <p>Metallic body: Yes</p> <p>Interior color: Black</p> <p>Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Power seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Parking sensors Rear: Yes</p> <p>Front parking sensors: Yes</p> <p>Radio: Yes</p> <p>Sports package: Yes</p> <p>Tow bar: Yes</p> <p>Heated seats: Yes</p> <p>Other options: Heated steering wheel</p> <p>Registration certificate: Yes, present</p>	
--	--	--	--



		<p>Certificate of conformity: Yes, present Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 29/11/2025 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Dashboard oil change and tire pressure notification Invoice amount (€ incl. VAT): €52,574.51 Invoice date (dd/mm/yyyy): 05-11-2024</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	39	<p>Make: Peugeot Model: Expert Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 11/06/2020 Fuel: Diesel Odometer reading (km): 198,448 Chassis number: VF3VFAHKKL7028108 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Crew-cab van Number of seats: 6 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2940 Transmission: Manual Exterior color: Black</p> <p>Metallic paint: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning</p>	100€



		<p>Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Additional information: Start with booster!</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Not available: the buyer will receive a certificate of loss of conformity certificate. Identification report: Yes, available Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 15/09/2026 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Dashboard maintenance and engine notifications Start with booster!</p> <p>Various damages</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	--	--



	42	<p>Make: Peugeot Model: Expert Year of manufacture (yyyy): 2018 First registration (dd/mm/yyyy): 27/08/2018 Fuel: Diesel Odometer reading (km): 152117 Chassis number: VF3VFAHKHJZ077341 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p>	100€
		<p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3100 Transmission: Manual transmission Engine capacity (cc): 1997 Engine power (kW): 90 Emission class: Euro 6b CO2 emissions (g/km): 139 Exterior color: White</p>	
		<p>Metallic body: No Interior color: Black</p>	
		<p>Upholstery: Partial leather Air conditioning: Semi-automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: Q-Top roof rack Furnished cargo area Additional information: Includes remaining contents: waste.</p>	
		<p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of Conformity: Yes, available CARPASS: Yes, available Identification report: Yes, available</p>	



		<p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 25/03/2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: dashboard notifications</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	44	<p>Make: Opel Model: Combo Version: Ecoflex Year of manufacture (yyyy): 2013 First registration (dd/mm/yyyy): 28/10/2014 Fuel: Diesel Odometer reading (km): 159,414 Chassis number: W0L6WXC1AD9533772 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2330 Transmission: Manual transmission Engine capacity (cc): 1248 Engine power (kW): 66 Emission class: Euro 5 Exterior color: White</p> <p>Metallic paint: No Interior color: Gray</p> <p>Upholstery: Leatherette Central locking: Yes Power windows: Yes Radio: Yes Registration certificate: Yes, present</p>	100€



		<p>Certificate of Conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 08/08/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a You can always consult the photo report for a detailed overview of the visible damage.</p> <p>Vehicle damage description: various damages</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	46	<p>Make: Volkswagen Model: Caddy Year of manufacture (yyyy): 2014 First registration (dd/mm/yyyy): 27/03/2014 Fuel: Diesel Odometer reading (km): 280,894 Chassis number: WV1ZZZ2KZEX118651 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2310 Transmission: Manual Cylinder capacity (cc): 1598 Engine power (kW): 75 Emission class: Euro 5b Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes</p>	100€



		<p>Cruise control: Yes Power windows: Yes Radio: Yes Registration certificate: Yes, present Certificate of Conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): June 21, 2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: dashboard engine message</p> <p>Various damages</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	50	<p>Make: Renault Model: Master Version: Fourgon Grand Confort FWD L3H2 dCi 150 Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 25/05/2023 Fuel: Diesel Odometer reading (km): 83051 Chassis number: VF1MA000X70416886 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500</p>	100€



		<p>Transmission: Manual Cylinder capacity (cc): 2299 Engine power (kW): 110 Emission class: Euro 6 CO2 emissions (g/km): 239 Exterior color: White</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate Valid until (dd/mm/yyyy): 04/12/2025</p> <p>Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: maintenance to be performed Invoice amount (€ incl. VAT): €34,646.89</p> <p>Invoice date (dd/mm/yyyy): 18-04-2023</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--



	51	<p>Make: Renault Model: Master Version: Fourgon Grand Confort FWD L3H2 dCi 150 Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 21/04/2023 Fuel: Diesel Odometer reading (km): 75,013 Chassis number: VF1MA000370416891 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Cylinder capacity (cc): 2299 Engine power (kW): 110 Emission class: Euro 6 CO2 emissions (g/km): 239 Exterior color: White</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate Valid until (dd/mm/yyyy): 02/12/2025 Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p>	100€
---	----	--	------



		<p>Vehicle damage description: maintenance to be performed Various damage: severely damaged sidewalls Flat tire Moldy interior</p> <p>Invoice amount (€ incl. VAT): €34,646.89 Invoice date (dd/mm/yyyy): 28-03-2023</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	52	<p>Make: Renault Model: Master Version: Fourgon Grand Confort FWD L3H2 dCi 150 Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 21/04/2023 Fuel: Diesel Odometer reading (km): 37,881 Chassis number: VF1MA000870416868 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Engine capacity (cc): 2299 Engine power (kW): 110 Emission class: Euro 6 Exterior color: White</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes</p>	100€



		<p>Central locking: Yes Power windows: Yes Rear parking sensors: Yes Radio: Yes Additional information: Vehicle will not start!</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of conformity: Yes, available Identification report: Yes, available</p> <p>Inspection certificate: Not available</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: Vehicle does not start!</p> <p>Maintenance to be performed</p> <p>Various dashboard error messages</p> <p>Various damages</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	53	<p>Make: Renault Model: Master Version: Fourgon Grand Confort FWD L3H2 dCi 150 Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 15/12/2022 Fuel: Diesel Odometer reading (km): 79,793 Chassis number: VF1MA000870416854</p>	100€



		<p>Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2299 Engine power (kW): 110 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Additional information: Side door handle missing</p> <p>Registration certificate: Yes, available Certificate of Conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 23/12/2025 Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Side door handle missing Side cover missing</p> <p>Invoice amount (€ incl. VAT): €34,646.89 Invoice date (dd/mm/yyyy): 09-12-2022</p> <p>Condition: Used</p>	
--	--	--	--



		Quantity: 1	
	95	<p>Make: Mitsubishi Model: Canter Version: Fuso 3C13 Year of manufacture (yyyy): 2008 First registration (dd/mm/yyyy): 12/08/2008 Fuel: Diesel Odometer reading (km): 172601 Chassis number: TYBFB83BE4DU17524 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Box truck Number of axles: 2 Maximum Permissible Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2977 Number of doors: 2-door Exterior color: White</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Manual air conditioning Electric windows: Yes Other options: Equipped with a D'Hollandia tailgate Side door Registration certificate: Yes, available Certificate of Conformity: Yes, available CARPASS: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 31/05/2025 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please contact us. Always consult the photo report.</p>	100€



		<p>Vehicle damage description: chip in the windshield</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	200	<p>Make: Ford Model: Transit</p> <p>Version: Custom Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 14/04/2022 Fuel: Diesel Odometer reading (km): 69669 Chassis number: WF0YXXTTGYNY44166 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3000 Transmission: Manual transmission Engine capacity (cc): 1995 Engine power (kW): 96 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Other options: Equipped with additional van locks:</p>	100€



		<p>side and rear doors, keyless. Additional information: Side and rear doors locked, no key for the additional locks. Registration certificate: Yes, present</p> <p>Certificate of Conformity: Not present: the buyer will receive a certificate of loss of the certificate of conformity</p> <p>CARPASS: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 14/10/2025</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--