



CATALOG
Commercial vehicles

DESCRIPTION	Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.
START	26 february 2026 to 09:00 [UTC]
END DATE	5 march 2026 from 17:00 [UTC]
VIEWING	<ul style="list-style-type: none">• Lots: 11, 25, 54-57, 66, 69,100, 600 --- Wednesday March 04 2026 from 15:00 until 17:00 BE-2630 Aartselaar, Helststraat 47• Lots: 495-498 Only by appointment through the organizer. Tuesday March 03 2026 from 10:30 until 11:00 BE-4530 VILLERS LE BOUILLET, RUE DE L'INDUSTRIE 15• Lots: 500 Only by appointment through the organizer. Tuesday March 03 2026 from 09:30 until 10:00 BE-7090 BRAINE LE COMTE, CHAUSSEE D'ECAUSSINNES 110
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622



ISSUE - COLLECTION

- Lots: 11, 25, 54-57, 66, 69,100, 600

Wednesday March 11 2026 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47
- Lots: 495-498

Thursday March 12 2026 from 10:30 until 11:00
BE-4530 VILLERS LE BOUILLET, RUE DE L'INDUSTRIE
15
- Lots: 500

Thursday March 12 2026 from 09:30 until 10:00
BE-7090 BRAINE LE COMTE, CHAUSSEE
D'ECAUSSINNES 110

Online bidding only!

Catalog created on 5 march 2026 to 04:00



	Item	Description	Start price
	8	<p>Make: Citroën Model: Jumpy Version: M 1.5 BlueHDI 120 S S Year of manufacture (yyyy): 2025 First registration (dd/mm/yyyy): 18/07/2025 Fuel: Diesel Odometer reading (km): 7349 Chassis number: VF7VJYHVXSU303062 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2656 Transmission: Manual transmission Engine displacement (cc): 1499 Engine power (kW): 88 Emission class: Euro 6e Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No Excluding general wear and tear. (General wear and tear includes all damage that would be expected given the age, mileage, or hours of use.) For a detailed overview, please consult the photo report.</p>	100€



		Invoice amount (€ incl. VAT): €29,293.34 Invoice date (dd/mm/yyyy): July 14, 2025 Condition: Used Quantity: 1	
	11	Make: Peugeot Model: Boxer Version: L1H1 - 2.2 BlueHDi Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 09/02/2021 Fuel: Diesel Odometer reading (km): 84305 Chassis number: VF3YBBNFA12P57849 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3300 Transmission: Manual Cylinder capacity (cc): 2179 Engine power (kW): 103 Emission class: Euro 6 Exterior color: White Metallic paint: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes	100€



		<p>Other options: Ladder Rhino Pipetube Locks Registration certificate: Yes, available Certificate of conformity: Not available: the buyer will receive one Certificate of Loss of Conformity Inspection Certificate: Yes, present Inspection Certificate Valid Until (dd/mm/yyyy): 12/02/2026 Maintenance Booklet: Not present Visible Vehicle Damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Invoice Amount (€ incl. VAT): €20,559.27</p> <p>Invoice Date (dd/mm/yyyy): 09-02-2021</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	25	<p>Brand: Maxus Model: EV80</p> <p>Year of manufacture (yyyy): 2020</p> <p>First registration (dd/mm/yyyy): 24/12/2020</p> <p>Fuel: Electric</p> <p>Odometer reading (km): 63,835 Chassis number: LSH14J4C2LA057186 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Automatic Engine power kW: 92 Exterior color: White</p>	100€



		<p>Metallic body: No Interior color: Gray Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Equipped with electric charging cable: Available Registration certificate: Yes Certificate of conformity: Yes Identification report: Yes Inspection certificate: Yes Inspection certificate valid until (dd/mm/yyyy): 01/03/2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	26	<p>Make: Peugeot Model: Boxer Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 30/08/2019 Fuel: Diesel Odometer reading (km): 117,135 Chassis number: VF3YC2MFB12L28616 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3</p>	100€



		<p>Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Cylinder capacity (cc): 1997 Engine power (kW): 96 Emission class: Euro 6b Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Not available Maintenance booklet: Not available Present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: various damages Condition: Used</p> <p>Quantity: 1</p>	
	54	<p>Make: Renault Model: Master Version: Fourgon Grand Confort FWD L3H2 dCi 150 Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 15/12/2022 Fuel: Diesel Odometer reading (km): 90,227 Chassis number: VF1MA000170416842</p>	100€



		<p>Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Cylinder capacity (cc): 2299 Engine power (kW): 110 Emission class: Euro 6 CO2 emissions (g/km): 239 Exterior color: White</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate Valid until (dd/mm/yyyy): 23/12/2025 Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: maintenance to be performed</p> <p>Various damages</p> <p>Moldy interior</p> <p>Invoice amount (€ incl. VAT): €34,646.89</p> <p>Invoice date (dd/mm/yyyy): 09-12-2022</p>	
--	--	---	--



		Condition: Used Quantity: 1	
	55	Make: Renault Model: Master Version: Fourgon Grand Confort FWD L3H2 dCI 150 Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 21/04/2023 Fuel: Diesel Odometer reading (km): 71679 Chassis number: VF1MA000570416875 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2299 Engine power (kW): 110 Emission class: Euro 6 Exterior color: White Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available	100€



		<p>Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 28/11/2025 Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: maintenance to be performed</p> <p>brake pads to be checked</p> <p>moldy interior</p> <p>various damage</p> <p>Invoice amount (€ incl. VAT): €34,646.89</p> <p>Invoice date (dd/mm/yyyy): 28-03-2023</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	56	<p>Make: Renault</p> <p>Model: Master</p> <p>Version: Fourgon Grand Confort FWD L3H2 dCi 150</p> <p>Year of manufacture (yyyy): 2022</p> <p>First registration (dd/mm/yyyy): 25/05/2023</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 62706</p> <p>Chassis number: VF1MA000970416894</p> <p>Number of keys: 1</p> <p>Vehicle category: N1: max. weight <3.5 t</p>	100€



Body: Panel van
Number of seats: 3
Number of axles: 2
Permitted Gross Vehicle Weight (kg): 3500
Transmission: Manual
Cylinder capacity (cc): 2299
Engine power (kW): 110
Emission class: Euro 6
CO2 emissions (g/km): 239
Exterior color: White

Metallic body: No
Interior color: Black

Upholstery: Fabric
Reversing camera: Yes
Air conditioning: Manual air conditioning
Trip computer: Yes
Central locking: Yes
Power windows: Yes
Navigation: Yes
Rear parking sensors: Yes
Radio: Yes
Registration certificate: Yes, available
Certificate of conformity: Yes, available
Identification report: Yes, available
Inspection certificate: Yes, available
Inspection certificate Valid until (dd/mm/yyyy):
27/11/2025

Maintenance booklet: Not available

Visible vehicle damage: Yes, for a detailed
overview of the visible damage, please consult
the photo report.

Vehicle damage description: bumper
side mirror
star in the windshield
Invoice amount (€ incl. VAT): €34,646.89

Invoice date (dd/mm/yyyy): 18-04-2023

Condition: Used



		Quantity: 1	
	57	<p>Make: Renault Model: Master Version: Fourgon Grand Confort FWD L3H2 dCi 150 Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 21/04/2023 Fuel: Diesel Odometer reading (km): 20,896 Chassis number: VF1MA000470416866 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2299 Engine power (kW): 110 Emission class: Euro 6 CO2 emissions (g/km): 239 Exterior color: White</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate Certificate of conformity: Yes, available</p>	100€



		<p>Identification report: Yes Available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 03/05/2025 Maintenance booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the age and mileage or hours of use.) For a detailed overview, please consult the photo report. Vehicle damage description: maintenance to be performed Condition: Used Quantity: 1</p>	
	66	<p>Make: MAN Model: TGE Version: 3.180 4x2F SB Panel</p> <p>Year of manufacture (yyyy): 2024</p> <p>First registration (dd/mm/yyyy): 25/04/2024</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 39697 Chassis number: WMA03VUY0R9017591 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Automatic Cylinder capacity (cc): 1968 Engine power (kW): 130 Emission class: Euro 6 Exterior color: Black</p> <p>Metallic paint: No Interior color: Black</p>	100€



		<p>Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Multifunction steering wheel: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): April 30, 2025</p> <p>Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Invoice amount (€ incl. VAT): €53,845</p> <p>Invoice date (dd/mm/yyyy): April 26, 2024</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	69	<p>Make: Ford Model: Ranger Version: Double Cab Wildtrak 2.0TDCI Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 14/03/2023 Fuel: Diesel Odometer reading (km): 119,021 Chassis number: 6FPPXXMJ2PNR76407 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Pickup Number of axles: 2</p>	100€



		<p>Permitted Gross Vehicle Weight (kg): 3270 Transmission: Automatic Engine capacity (cc): 1996 Engine power (kW): 156 Emission class: Euro 6 Number of doors: 5-door Exterior color: Silver Metallic body: Yes Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Power seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Tow bar: Yes Seat heating: Yes Other options: Wildtrak Registration certificate: Not available: the buyer will receive a certificate of loss of registration Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 03/16/2026 Maintenance booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the age and mileage or hours driven.) For a detailed overview, please consult the photo report. Invoice amount (€ incl. VAT): €41,164.68</p> <p>Invoice date (dd/mm/yyyy): March 16, 2023</p>	
--	--	--	--



		Condition: Used Quantity: 1	
	100	Make: Addax Model: MTN Version: MT15X Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 26/04/2021 Fuel: Electric Odometer reading (km): 9177 Chassis number: YBDNUL602FA000299 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t Body: Light truck Number of axles: 2 Permitted Gross Vehicle Weight (kg): 1840 Transmission: Automatic Engine power (kW): 12.50 Number of doors: 2-door Exterior color: White Metallic paint: No Interior color: Black Upholstery: Leatherette Reversing camera: Yes Central locking: Yes Radio: Yes Other options: Equipped with a battery and an internal charger Additional information: Starts with a booster! Registration certificate: Yes, present Certificate of Conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present	100€



		<p>Inspection certificate valid until (dd/mm/yyyy): 04/05/2026</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: Start with booster!</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	495	<p>Make: Peugeot Model: Boxer Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 23/10/2020 Fuel: Diesel Odometer reading (km): 116,406 Chassis number: VF3YCCNFB12P69628(01) Number of keys: 2 Vehicle category: N1: maximum mass <3.5t</p> <p>Body type: Van Number of seats: 3 Transmission: Manual Engine displacement (cc): 2179 Engine power (kW): 121 Emission class: Euro 6d-TEMP Exterior color: Gray Upholstery: Dustproof Reversing camera: Yes Air conditioning: Manual Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Navigation: Yes Rear parking sensors: Yes</p>	2.500€



		<p>Radio: Yes Tow bar: Yes Additional information: Euro 6d-ISC Bluetooth Registration certificate: Yes, present Certificate of conformity: Yes, present Vehicle identification report: Yes, present Inspection certificate: Yes, present Vehicle inspection certificate valid until (dd/mm/yyyy): July 20, 2026 Visible vehicle damage: Yes, you can still consult the photo report for a detailed overview of the visible damage. Description of vehicle damage: Scratches present around the perimeter of the vehicle, chipped windshield, dented rear bumper, dented left front fender. Condition: Used Quantity: 1</p>	
	496	<p>Make: Peugeot Model: Boxer Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 26/02/2020 Fuel: Diesel Odometer reading (km): 138,701 Chassis number: VF3YCBNFB12N46874(01) Number of keys: 2 Vehicle category: N1: maximum mass <3.5t</p> <p>Body type: Van Number of seats: 3 Transmission: Manual Engine displacement (cc): 2179 Engine power (kW): 103 Emission class: Euro 6d-TEMP Exterior color: Gray Metallic color: No Upholstery: Dustproof Reversing camera: Yes Air conditioning: Manual Central locking: Yes</p>	2.500€



		<p>Cruise control: Yes Electric windows: Yes Fog lights: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Additional information: EURO 6d-isc AD BLUE Registration certificate: Yes, present Certificate of conformity: Yes, present Vehicle identification report: Yes, present Inspection certificate: Yes, present Vehicle inspection certificate valid until (dd/mm/yyyy): 06/07/2026 Visible damage to the vehicle: Yes, you can still consult the photo report for a detailed overview of the visible damage. Description of vehicle damage: Various scratches around the perimeter of the vehicle. Condition: Used Quantity: 1</p>	
	497	<p>Make: Peugeot Model: Boxer Year of manufacture (yyyy): 2018 First registration (dd/mm/yyyy): 05/10/2018 Fuel: Diesel Odometer reading (km): 167,028 Chassis number: VF3YC3MFC12H79474(01) Number of keys: 2 Vehicle category: N1: maximum mass <3.5t</p> <p>Body type: Van Number of seats: 3 Transmission: Manual Engine displacement (cc): 1997 Engine power (kW): 120 Emission class: Euro 6 Exterior color: Gray Upholstery: Dusty Air conditioning: Manual Central locking: Yes</p>	2.000€



		<p>Cruise control: Yes Electric windows: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Additional information: Euro 6b Registration certificate: Yes, present Certificate of conformity: Yes, present Vehicle identification report: Yes, present Inspection certificate: Yes, present Vehicle inspection certificate valid until (dd/mm/yyyy): 15/11/2025 Visible damage to the vehicle: Yes, you can still consult the photo report for a detailed overview of the visible damage. Description of vehicle damage: Various scratches and dents around the perimeter of the vehicle. Front fender liners missing.</p> <p>(DK) Car registration: The car is exempt from Danish registration tax. Condition: Used Quantity: 1</p>	
	498	<p>Make: Iveco Model: Daily HI Matic 35C21 Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 07/01/2022 Fuel: Diesel Odometer reading (km): 94156 Chassis number: ZCFC835F605453460 Number of keys: 2 Vehicle category: N1: maximum mass <3.5t</p> <p>Body type: Van Number of seats: 3 Transmission: Automatic Engine displacement (cc): 2998 Engine power (kW): 152 Emission class: Euro 6 Exterior color: Gray Upholstery: Dustproof</p>	6.500€



		<p>Rearview camera: Yes Air conditioning: Fully automatic On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Navigation: Yes Radio: Yes Tow bar: Yes Additional information: Shelving is included with the vehicle (contents not included). Registration Certificate: Yes, present Certificate of Conformity: Yes, present Identification Report: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until (dd/mm/yyyy): 27/03/2026 Visible Vehicle Damage: Yes, you can still consult the photo report for a detailed overview of the visible damage. Condition: Used Quantity: 1</p>	
	500	<p>Make: Renault Model: Master Year of manufacture (yyyy): 2017 First registration (dd/mm/yyyy): 13/06/2017 Fuel: Diesel Odometer reading (km): 100448 Chassis number: VF1MA000258424060(01) Number of keys: 2 Vehicle category: N1: maximum mass <3.5t</p> <p>Body type: Van Number of seats: 3 Number of axles: 2 Maximum authorized mass (kg): 3500 Transmission: Manual Engine displacement (cc): 2299 Engine power (kW): 96 Exterior color: Not used</p>	100€



		<p>Metallic color: Yes Reversing camera: Yes Air conditioning: Manual air conditioning Central locking: Yes Electric windows: Yes Navigation: Yes Radio: Yes Other options: Electric mirrors, AdBlue, tie-down rings in the floor, shelving (unused), tow bar Registration certificate: Yes, present Certificate of conformity: Not present. (Import within the European Union) Identification Report: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until (dd/mm/yyyy): 10/05/2026 Service Booklet: Not present Visible Vehicle Damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the vehicle's age and mileage or hours.) For a detailed overview, please refer to the photo report. Description of Vehicle Damage: Minor scratches present (see photos) Condition: Used Quantity: 1</p>	
	600	<p>Brand: BCW Model: V4/10/236</p> <p>Year of manufacture (yyyy): 1991 Trailer category: O2: max. weight >750kg - <3500kg Trailer type: Vehicle transporter Chassis number: 2505 Permitted Gross Vehicle Weight (kg): 2000 Internal dimensions (L x W x H) in mm: 4020x1950 Additional information: Vehicle is sold without vehicle documents or certificates.</p> <p>Equipped with a hand winch.</p>	10€



		<p>Inspection certificate: Not available Number of axles: 2 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Vehicle is sold without vehicle documents or certificates. Condition: Used Quantity: 1</p>	
--	--	--	--