

**CATALOG**  
CLASSIC CARS, OLD- & YOUNG TIMERS

<b>DESCRIPTION</b>	Veiling classic cars, oldtimers en young timers
<b>START</b>	28 february 2026 to 09:00 [UTC]
<b>END DATE</b>	10 march 2026 from 18:00 [UTC]
<b>VIEWING</b>	<ul style="list-style-type: none"><li>• Lots: 12-15 Only by appointment through the organizer. Thursday March 05 2026 from 10:00 until 11:00 BE-4672 SAINT-REMY</li><li>• Lots: 35 Only by appointment through the organizer. Thursday March 05 2026 from 11:00 until 12:00 BE-1360 PERWEZ</li><li>• Lots: 4 --- Wednesday March 04 2026 from 15:00 until 17:00 BE-2630 AARTSELAAR, HELSTSTRAAT 47</li><li>• Lots: 73 Only by appointment through the organizer. Monday March 09 2026 from 14:00 until 15:00 BE-1480 TUBIZE</li></ul>

<b>AUCTIM PARTNER</b>	<b>MOYERSOEN NV</b> Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoен@auctim.be BTW BE 0452 153 622
-----------------------	--




**ISSUE - COLLECTION**

- Lots: 12-15  
---  
Tuesday March 17 2026 from 10:00 until 11:00  
BE-4672 SAINT-REMY
- Lots: 35  
---  
Tuesday March 17 2026 from 11:00 until 12:00  
BE-1360 PERWEZ
- Lots: 4  
---  
Wednesday March 18 2026 from 10:00 until 12:00  
BE-2630 AARTSELAAR, HELSTSTRAAT 47
- Lots: 73  
Aanmelden tussen  
Thursday March 19 2026 from 09:00 until 10:00  
BE-1480 TUBIZE


**Online bidding only!**

Catalog created on 10 march 2026 to 04:00





	Item	Description	Start price
	4	<p>Make: Replicar Hellas Model: RCH 365 Speedster Year of manufacture (yyyy): 1970 First registration (dd/mm/yyyy): 01/01/1970 Fuel: Petrol Odometer reading (km): 1778 Chassis number: 1102095722 Number of keys: 1 Vehicle category: M1: passenger car Vehicle type: Convertible Transmission: Manual transmission Engine capacity (cc): 2332 Engine power (kW): 128 Exterior color: Silver Interior color: Black Upholstery: Partial leather Alloy wheels: Yes Sunroof: Yes Registration certificate: Yes, available</p> <p>Certificate of conformity: Not available</p> <p>Inspection certificate: Not available Inspection certificate valid until (dd/mm/yyyy): Issued on 08/08/2017 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	10.000€




	12	<p>Make: MERCEDES Model: 250 D Year of manufacture (yyyy): 1991 First registration (dd/mm/yyyy): 04/03/1991 Fuel: Diesel Odometer reading (km): 294,060 Chassis number: WDB1241851F174465 Number of keys: 2 Vehicle category: M1: Passenger car Car type: Estate Transmission: Manual transmission Engine displacement (cc): 2500 Engine power (kW): 69 Exterior color: Silver Interior color: BLUE Upholstery: Fabric Sunroof: Yes Radio: Yes Tow bar: Yes Additional information: Mercedes 250D (S124): Numerous service records Maintenance. All running gear refurbished with supporting photos. Mileage varies (the vehicle is still running). Registration Certificate: Yes, present Certificate of Conformity: Yes, present CARPASS: Yes, present Inspection Certificate: Yes, present Valid inspection certificate until (dd/mm/yyyy): 02/06/2027 Maintenance performed by: owner Visible damage to the vehicle: Yes, you can still consult the photo report for a detailed overview of the visible damage. Condition: Used Quantity: 1</p>	1.500€
---	----	---	--------




	13	<p>Make: MERCEDES Model: 230 C Year of manufacture (yyyy): 1979 First registration (dd/mm/yyyy): 13/07/1979 Fuel: Gasoline Odometer reading (km): 109,635 Chassis number: 12304310013590 Number of keys: 2 Vehicle category: M1: Passenger car Car type: Coupe Transmission: Manual transmission Engine displacement (cc): 2300 Engine power (kW): 80 Exterior color: White Interior color: Gray/Black Upholstery: Fabric Sunroof: Yes Radio: Yes Tow bar: Yes Additional information: Numerous invoices detailing the vehicle's history are available upon request. Registration Certificate: Yes, present Certificate of Conformity: Yes, present Inspection Certificate: Yes, present Valid inspection certificate until (dd/mm/yyyy): 14/08/2026 Maintenance performed by: Garage and owner Visible damage to the vehicle: Yes, you can still consult the photo report for a detailed overview of the visible damage. Condition: Used Quantity: 1</p>	1.750€
	14	<p>Make: MERCEDES Model: 300 SL Year of manufacture (yyyy): 1991 First registration (dd/mm/yyyy): 23/01/1991 Fuel: Gasoline Odometer reading (km): 200864 Chassis number: WDB1290601F026433 Number of keys: 2 Vehicle category: M1: Passenger car</p>	2.500€




		<p>Car type: Convertible Transmission: Automatic Engine displacement (cc): 2960 Engine power (kW): 140 Exterior color: Not used Interior color: Black Upholstery: Full leather Power windows: Yes Power seats: Yes Alloy wheels: Yes Fog lights: Yes Radio: Yes Additional information: The owner Extensive maintenance has been performed on the vehicle. List available upon request. The electric seats are no longer functional (relay?). Registration Certificate: Yes, present Certificate of Conformity: Yes, present CARPASS: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until (dd/mm/yyyy): 25/04/2026 Service Booklet: Not present Visible Damage to the Vehicle: Yes, you can still consult the photo report for a detailed overview of the visible damage. Condition: Used Quantity: 1</p>	
	15	<p>Make: ROVER Model: FSI Year of manufacture (yyyy): 1993 First registration (dd/mm/yyyy): 05/03/1993 Fuel: Petrol Odometer reading (km): 138,900 Chassis number: SAXXWYWMXAD625670 Number of keys: 2 Vehicle category: M1: Passenger car Car type: Saloon Transmission: Automatic Engine displacement (cc): 1600 Engine power (kW): 85</p>	375€



		<p>Exterior color: Green Interior color: Gray Upholstery: Full leather Electric windows: Yes Sunroof: Yes Radio: Yes Additional information: Maintenance invoices available upon request. Registration Certificate: Yes, present Certificate of Conformity: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until (dd/mm/yyyy): 06/02/2027 Visible Vehicle Damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Description of Vehicle Damage: Scratches on the bodywork, dents on the bumper and hood. Condition: Used Quantity: 1</p>	
	35	<p>Make: VW Model: Phaeton Year of manufacture (yyyy): 2003 First registration (dd/mm/yyyy): 24/10/2003 Fuel: LPG Odometer reading (km): 204,684 Chassis number: WVWZZZ3DZ48008467(01) Number of keys: 1 Vehicle category: M1: Passenger car Car type: Sedan Transmission: Automatic Engine displacement (cc): 3189 Engine power (kW): 177 Emission class: Euro 4 CO2 emissions (g/km): 288 Exterior color: Blue Metallic paint: Yes Interior color: Beige Upholstery: Full leather Air conditioning: Fully air-conditioned Automatic On-board computer: Yes</p>	100€



		<p>Central locking: Yes Cruise control: Yes Electric folding mirrors: Yes Electric tailgate: Yes Electric windows: Yes Electric seats: Yes Alloy wheels: Yes Massage seats: Yes Fog lights: Yes Rear parking assist: Yes Front parking sensors: Yes Radio: Yes Seat ventilation: Yes Seat heating: Yes Other options: Double glazing, LPG system, 4 seats, air suspension? Electric headrests (4), front seat position memory Registration Certificate: Yes, present Certificate of Conformity: Yes, present Identification Report: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until (dd/mm/yyyy): 30/01/2026 Service Booklet: Not present Visible Vehicle Damage: Yes, you can still consult the photo report for a detailed overview of the visible damage. Description of Vehicle Damage: Broken front bumper, scratches on bodywork Condition: Used Quantity: 1</p>	
	73	<p>Make: Piaggio Model: TM P50 (TL4T) Year of manufacture (yyyy): 1985 First registration (dd/mm/yyyy): 22/10/1985 Fuel: Gasoline Chassis number: 522772 Motorcycle type: Scooter Engine displacement (cc): 49 Engine power (kW): 2.6 Number of keys: 0</p>	500€



		<p>Additional information: Does not start. Registration certificate: Not present, see additional information Certificate of conformity: Yes, present Visible vehicle damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Description of vehicle damage: Bodywork with visible cosmetic defects (scratches, dents, dings, corrosion). Condition: Used Quantity: 1</p>	
--	--	--	--