



CATALOG

Commercial vehicles



DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

5 march 2026 to 09:00 [UTC]

END DATE

12 march 2026 from 17:00 [UTC]

VIEWING

- Lots: 4-5, 14, 34-37, 71

Wednesday March 11 2026 from 15:00 until 17:00
BE-2630 Aartselaar, Helststraat 47
- Lots: 72, 74-80
Only by appointment through the organizer.
Monday March 09 2026 from 14:00 until 15:00
BE-1480 TUBIZE, RUE DE BRUXELLES 299
- Lots: 81
Only by appointment through the organizer.
Monday March 09 2026 from 09:00 until 10:00
BE-7090 BRAINE LE COMTE, RUE DE MONS 63

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoen@auctim.be
BTW BE 0452 153 622

AUCTIM - MOYERSOEN NV

Helststraat 47
2630 Aartselaar, Belgium
VAT BE 0452 153 622

www.auctim.com
info.moyersoen@auctim.be



ISSUE - COLLECTION

- Lots: 4-5, 14, 34-37, 71


Wednesday March 18 2026 from 10:00 until 12:00
BE-2630 Aartselaar, Helststraat 47
- Lots: 72, 74-80
Aanmelden tussen
Thursday March 19 2026 from 09:00 until 10:00
BE-1480 TUBIZE, RUE DE BRUXELLES 299
- Lots: 81

Thursday March 19 2026 from 10:00 until 11:00
BE-7090 BRAINE LE COMTE, RUE DE MONS 63


Online bidding only!

Catalog created on 12 march 2026 to 04:00




	Item	Description	Start price
	4	<p>Make: Volkswagen Model: Caddy Version: Life 4 Motion Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 08/07/2021 Fuel: Diesel Odometer reading (km): 30333 Chassis number: WV2ZZZSKZMX045673 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Crew cab van Number of seats: 5 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2300 Transmission: Manual Cylinder capacity (cc): 1968 Engine power (kW): 90 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Other options: Crew cab</p> <p>4-wheel drive 4Motion Additional information: Comes with Spanish registration certificate, customs document E705, and registration application.</p> <p>Registration certificate: Registration application available. Certificate of Conformity: Not available.</p>	100€



		<p>(Import within the European Union) CARPASS: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 13/02/2027 Maintenance booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the vehicle's age and mileage or hours.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	5	<p>Make: Mercedes-Benz Model: eSprinter Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 02/12/2024 Fuel: Electric Odometer reading (km): 9671 Chassis number: W1V4UCHZ7SP773397 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Transmission: Automatic Engine power kW: 80 Exterior color: White</p> <p>Metallic paint: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes</p>	100€




		<p>Power windows: Yes Multifunction steering wheel: Yes Radio: Yes Equipped with an electric charging cable: Present Registration certificate: Yes, present Certificate of Conformity: Yes, present Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that would be expected given the age and mileage or hours of use.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	14	<p>Make: Ford Model: Ranger Version: Crew cab Wildtrak 2.0 BiTDCi 4x4 Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 20/03/2023 Fuel: Diesel Odometer reading (km): 40,031 Chassis number: 6FPPXXMJ2PNR79100 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Pickup Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3270 Transmission: Automatic Engine capacity (cc): 1996 Engine power (kW): 156 Emission class: Euro 6 Number of doors: 5-door Exterior color: Black</p> <p>Metallic body: Yes Interior color: Black</p>	100€




		<p>Upholstery: Full leather Reversing camera: Yes Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Power seats: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Sports package: Yes Tow bar: Yes</p> <p>Heated seats: Yes Other options: Wildtrak version</p> <p>Double cab</p> <p>Registration certificate: Yes, available Certificate of conformity: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 22/03/2026 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: bumper Invoice amount (€ incl. VAT): €43,562.42 Invoice date (dd/mm/yyyy): 24-03-2023</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--




	34	<p>Make: Ford Model: Transit Custom Version: L1H1</p> <p>Year of manufacture (yyyy): 2017</p> <p>First registration (dd/mm/yyyy): 15/02/2017</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 156986 Chassis number: WF0ZXXTTGZHJ48125 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Crew-cab van Number of seats: 6 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2940 Transmission: Manual Engine capacity (cc): 1995 Engine power (kW): 96 Emission class: Euro 6b Exterior color: Gray</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Full leather Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, present</p>	100€
---	----	---	------



		<p>Certificate of Conformity: Yes, present Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 10/10/2025 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	35	<p>Brand: Citroën Model: Jumpy Version: XL Year of manufacture (yyyy): 2021 First registration (dd/mm/yyyy): 10/06/2021 Fuel: Diesel Odometer reading (km): 195049 Chassis number: VF7VFEHZ8MZ061334 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Crew-cab van Number of seats: 6 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3000 Transmission: Automatic Engine capacity (cc): 1997 Engine power (kW): 130 Emission class: Euro 6 Exterior color: Black</p> <p>Metallic paint: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes</p>	100€




		<p>Central locking: Yes Cruise control: Yes Power-folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: equipped with an extra set of tires on the rims. Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 14/06/2026</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	36	<p>Make: Mercedes-Benz Model: Sprinter Version: 316 CDI L2H2 Year of manufacture (yyyy): 2017 First registration (dd/mm/yyyy): 09/01/2018 Fuel: Diesel Odometer reading (km): 245985 Chassis number: WDB9066331P577482 Number of keys: 1</p>	100€




		<p>Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2143 Engine power (kW): 120 Emission class: Euro 6b CO2 emissions g/km: 211 Exterior color: Black</p> <p>Metallic paint: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Tow bar: Yes Other options: Roof rack Ladder</p> <p>Fitted cargo area Registration certificate: Yes, available Certificate of Conformity: Yes Available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 04/07/2026 Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Description of vehicle damage: Various scratches</p> <p>Star in the windshield</p> <p>Condition: Used</p>	
--	--	---	--




		Quantity: 1	
	37	<p>Make: Ford Model: Transit</p> <p>Year of manufacture (yyyy): 2014</p> <p>First registration (dd/mm/yyyy): 20/10/2014</p> <p>Fuel: Diesel Odometer reading (km): 144909 Chassis number: WF0XXTTGXEP63025 Number of keys: 4 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Engine capacity (cc): 2198 Engine power (kW): 114 Emission class: Euro 5b CO2 emissions (g/km): 222 Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Other options: Signaling</p>	100€




		<p>Additional information: Vehicle will not start, engine damage! Glow plug broken and fell into the engine. Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 29/12/2026 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Vehicle will not start, engine damage! Glow plug broken and fell into the engine. Condition: Used</p> <p>Quantity: 1</p>	
	71	<p>Make: Fiat Model: Doblo Version: L1 Light 1.5 Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 31/05/2023 Fuel: Diesel Odometer reading (km): 40,828 Chassis number: VYFEFYHT2PN507476 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 5 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2040 Transmission: Manual transmission Engine capacity (cc): 1499 Engine power (kW): 75 Emission class: Euro 6 Exterior color: Black</p>	100€





		<p>Metallic body: No Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: equipped with Q-Top roof rail Registration certificate: Yes, available Certificate of Conformity: Yes Available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 10/07/2025 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Invoice amount (€ incl. VAT): 28041</p> <p>Invoice date (dd/mm/yyyy): 13-07-2023</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	72	<p>Make: VW Model: CADDY Year of manufacture (yyyy): 2015 First registration (dd/mm/yyyy): 03/09/2015 Fuel: Diesel Odometer reading (km): 226653 Chassis number: WV2ZZZZ2KZGX021289(01) Number of keys: 1 Vehicle category: M1: Passenger car Car type: Single-door</p>	1.250€



		<p>Number of doors: 5 Transmission: Manual transmission Engine displacement (cc): 1968 Engine power (kW): 55 Emission class: Euro 6 Exterior color: White Upholstery: Dusty On-board computer: Yes Central locking: Yes Cruise control: Yes Radio: Yes Other options: ABS, Driver/Passenger Airbag, CD Radio, Power Steering, ESP, Touchscreen, Leather Steering Wheel Registration Certificate: Yes, present Certificate of Conformity: Yes, present Identification Report: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until (dd/mm/yyyy): 03/09/2023 Visible Vehicle Damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Description of Vehicle Damage: Bodywork with visible cosmetic defects (scratches, dents, dents) Condition: Used Quantity: 1</p>	
	<p>74</p>	<p>Brand: KERENZO Model: K0750E Year of manufacture (yyyy): 2019 Trailer category: O1: maximum mass <750kg Trailer type: Equipment carrier Chassis number: YALK0750EKL000412 Maximum permissible mass (kg): 750 Interior dimensions (L x W x H) in mm: 3000*1950*500 Additional information: TRUIL KNOOT Trailer registration certificate: Not available: the buyer receives a certificate of loss of registration Trailer conformity certificate: Yes, present Inspection certificate: Not present</p>	<p>250€</p>



		<p>Number of axles: 1 Visible damage to the vehicle: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the vehicle's age and mileage or hours.) For a detailed overview, please refer to the photo report.</p> <p>Condition: Used Quantity: 1</p>	
	75	<p>Brand: COSTO Trailer Category: O1: Maximum weight <750kg Trailer Type: Motorcycle Trailer Chassis Number: ----- Interior Dimensions (L x W x H) in mm: ----- Additional Information: No documents. Inspection Certificate: Not present Number of Axles: 1 Visible Vehicle Damage: Yes, you can always consult the photo report for a detailed overview of the visible damage. Description of Vehicle Damage: Bodywork with visible cosmetic defects (scratches, dents, dents, floor, etc.) Condition: Used Quantity: 1</p>	75€
	76	<p>Make: CITROEN Model: JUMPER Year of manufacture (yyyy): 2016 First registration (dd/mm/yyyy): 20/01/2017 Fuel: Diesel Odometer reading (km): 168769 Chassis number: VF7YA1MFA12C89269(01) Number of keys: 1 Vehicle category: N1: maximum mass <3.5t</p> <p>Body type: Van Number of seats: 3</p>	750€




		<p>Transmission: Manual Engine displacement (cc): 1997 Engine power (kW): 81 Emission class: Euro 6 Exterior color: White Upholstery: Dusty Reversing camera: Yes Air conditioning: Manual On-board computer: Yes Central locking: Yes Electric windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: ABS/Driver airbags/ASR/Bluetooth/Power steering/Hands-free/ESP/Electric mirrors Additional information: Engine out of service. Vehicle not roadworthy. Cannot be driven. Full overhaul or engine replacement required. Sold as is. Registration certificate: Yes, present Certificate of conformity: Not present. (Import within the European Union) Identification Report: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until (dd/mm/yyyy): 16/10/2025 Visible Vehicle Damage: Yes, you can still consult the photo report for a detailed overview of the visible damage. Description of Vehicle Damage: Bodywork with visible cosmetic defects (scratches, dents, dents)</p> <p>Engine out of service. Vehicle not drivable. Not roadworthy. Full overhaul or engine replacement required. Sold as is.</p> <p>Condition: Used Quantity: 1</p>	
--	--	---	--




	77	<p>Make: CITROEN Model: JUMPER Year of manufacture (yyyy): 2016 First registration (dd/mm/yyyy): 20/03/2017 Fuel: Diesel Odometer reading (km): 137,672 Chassis number: VF7YC2MFC12D43889(01) Number of keys: 1 Vehicle category: N1: maximum mass <3.5t</p>	1.500€
		<p>Body type: Van Number of seats: 3 Transmission: Manual Engine displacement (cc): 1997 Engine power (kW): 96 Emission class: Euro 6 Exterior color: White Upholstery: Dust-resistant Air conditioning: Manual On-board computer: Yes Central locking: Yes Electric windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: ABS/Driver airbag/Android Auto/Traction control/Apple CarPlay/Hill start assist/Bluetooth/CD player/Rear parking camera/Voice commands/Power steering/Hands-free system/ESP/Touchscreen/MP3 player/Digital radio/Mirrors ELECTRICAL/SOUNDSYSTEM/START&STOP/USB/LEATHER STEERING WHEEL/MULTIFUNCTION STEERING WHEEL Additional Information: Vehicle is drivable but has a mechanical fault with the gearbox (a faulty gear shift). Mechanical intervention is required. No thorough testing has been carried out. Registration Certificate: Yes, present Certificate of Conformity: Yes, present Identification Report: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until (dd/mm/yyyy): 16/02/2023</p>	




		<p>Visible Vehicle Damage: Yes, you can still consult the photo report for a detailed overview of the visible damage. Description of Vehicle Damage: Bodywork with visible cosmetic defects (scratches, dents, dings) Condition: Used Quantity: 1</p>	
	78	<p>Make: NISSAN Model: NV 400 F33.10 Year of manufacture (yyyy): 2012 First registration (dd/mm/yyyy): 23/03/2012 Fuel: Diesel Odometer reading (km): 215,103 Chassis number: VNVM1FMBC46939323(01) Number of keys: 1 Vehicle category: N1: maximum mass <3.5t</p> <p>Body type: Van Number of seats: 3 Transmission: Manual Engine displacement (cc): 2299 Engine power (kW): 74 Emission class: Euro 5 Exterior color: White Upholstery: Dusty Radio: Yes Tow bar: Yes Other options: ABS/Driver airbag/Power steering/ESP Additional information: Bodywork shows signs of wear related to professional use: scratches, dents, localized corrosion, and damaged plastic parts (mirrors). Visible cosmetic defects on bumpers and side panels.</p> <p>Registration Certificate: Yes, present Certificate of Conformity: Yes, present Identification Report: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until</p>	1.000€




		<p>(dd/mm/yyyy): 02/10/2024 Visible Vehicle Damage: Yes, you can still consult the photo report for a detailed overview of the visible damage. Description of Vehicle Damage: Bodywork showing signs of wear related to professional use: scratches, dents, localized corrosion, and damaged plastic parts (mirrors). Visible cosmetic defects on bumpers and side panels. Condition: Used Quantity: 1</p>	
	79	<p>Make: OPEL Model: MOVANO Year of manufacture (yyyy): 2016 First registration (dd/mm/yyyy): 02/05/2016 Fuel: Diesel Odometer reading (km): 174,570 Chassis number: WOLMRF4YEGB103547(01) Number of keys: 1 Vehicle category: N1: maximum mass <3.5t</p> <p>Body type: Van Number of seats: 3 Transmission: Manual Engine displacement (cc): 2299 Engine power (kW): 100 Emission class: Euro 5 Exterior color: White Upholstery: Dustproof Air conditioning: Manual On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: ABS/Driver airbag/Hill start</p>	1.500€



		<p>assist/Bluetooth/Armrest/Voice control/Power steering/Hands-free system/ESP/Touchscreen/MP3/Electric mirrors/Start/Stop AUTOMATIC/USB/MULTIFUNCTION STEERING WHEEL Registration Certificate: Yes, present Certificate of Conformity: Yes, present Identification Report: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until (dd/mm/yyyy): 13/06/2024 Visible Vehicle Damage: Yes, you can still consult the photo report for a detailed overview of the visible damage. Description of Vehicle Damage: Condition of the seats. Condition: Used Quantity: 1</p>	
	80	<p>Make: PEUGEOT Model: BOXER Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 08/10/2020 Fuel: Diesel Odometer reading (km): 124,487 Chassis number: VF3YCBNFB12P68121(01) Number of keys: 1 Vehicle category: N1: maximum mass <3.5t</p> <p>Body type: Van Number of seats: 3 Transmission: Manual Engine displacement (cc): 2179 Engine power (kW): 103 Emission class: Euro 6d-TEMP Exterior color: White Upholstery: Dustproof Reversing camera: Yes Air conditioning: Manual On-board computer: Yes Central locking: Yes</p>	1.500€



		<p>Cruise control: Yes Electric windows: Yes Fog lights: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Other options: ABS/Driver airbag/Lane departure warning/Bluetooth/Voice control/Power steering/Hands-free system/Light sensor/ESP/Display TOUCHSCREEN/LED DAYTIME RUNNING LIGHTS/MP3/DIGITAL RADIO/USB/MULTIFUNCTION STEERING WHEEL Additional Information: Vehicle is drivable but has a gearbox malfunction (anomaly when shifting gears). No in-depth inspection has been carried out. Mechanical repairs are expected. Registration Certificate: Yes, present Certificate of Conformity: Yes, present Identification Report: Yes, present Inspection Certificate: Yes, present Vehicle Inspection Certificate valid until (dd/mm/yyyy): 16/03/2024 Visible Damage to the Vehicle: Yes, you can still consult the photo report for a detailed overview of the visible damage. Description of Vehicle Damage: Vehicle is drivable but has a gearbox malfunction (anomaly when shifting gears). No in-depth inspection has been carried out. Mechanical repairs are expected. Minor cosmetic defects (light scratches, dents, interior plastics) Condition: Used Quantity: 1</p>	
	81	<p>Make: NISSAN Model: INTERSTAR Year of manufacture (yyyy): 2024 First registration (dd/mm/yyyy): 13/03/2024 Fuel: Diesel Odometer reading (km): 70,545</p>	100€



		<p>Chassis number: NVVV2000570885414(01) Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: TRUCK WITH TAIL LIFTING Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual Cylinder capacity (cc): 2299 Engine power (kW): 107 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black Air conditioning: Manual air conditioning Central locking: Yes Power windows: Yes Radio: Yes Additional information: Box dimensions: 4420x2000xH1970mm Registration certificate: Application for registration: available. Certificate of Conformity: Yes, available Identification Report: Yes, available Inspection Certificate: Yes, available Inspection Certificate valid until (dd/mm/yyyy): 21/03/2026 Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that may be expected given the vehicle's age and mileage or hours.) For a detailed overview, please consult the photo report.</p> <p>Vehicle damage description: Registration certificate, part I only</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--



	900	<p>Brand: NN</p> <p>Trailer category: O1: max. weight <750kg</p> <p>Trailer type: Open trailer Chassis number: Unknown Internal dimensions (L x W x H) in mm: 2000x1200 Additional information: Chassis number unknown. No vehicle documentation. Inspection certificate: Not available Number of axles: 1 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: Loading floor. Condition: Used Quantity: 1</p>	10€
--	-----	---	-----