




CATALOG
Commercial vehicles

DESCRIPTION	Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.
START	12 march 2026 to 09:00 [UTC]
END DATE	19 march 2026 from 17:00 [UTC]
VIEWING	<ul style="list-style-type: none">• --- Wednesday March 18 2026 from 15:00 until 17:00 BE-2630 Aartselaar, Helststraat 47
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
ISSUE - COLLECTION	<ul style="list-style-type: none">• --- Wednesday March 25 2026 from 10:00 until 12:00 BE-2630 Aartselaar, Helststraat 47


Online bidding only!

Catalog created on 19 march 2026 to 04:10




	Item	Description	Start price
	3	<p>Make: Volkswagen Model: Caddy Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 17/11/2022 Fuel: Petrol Odometer reading (km): 29212 Chassis number: WV1ZZZSK5PX030781 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2150 Transmission: Automatic Cylinder capacity (cc): 1498 Engine power (kW): 84 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Full leather Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Alloy wheels: Yes Fog lights: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Not available: the buyer will receive a certificate of loss. Registration certificate Certificate of Conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present</p>	100€



		<p>Inspection certificate valid until (dd/mm/yyyy): 15/12/2026 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: various damages Condition: Used Quantity: 1</p>	
	8	<p>Make: Volkswagen Model: Caddy Maxi Version: Kombi Plus 2.0 TDI Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 25/08/2022 Fuel: Diesel Odometer reading (km): 111,875 Chassis number: WV1ZZZSK5NX064359 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: crew cab van Number of seats: 5 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2450 Transmission: Manual transmission Engine capacity (cc): 1968 Engine power (kW): 75 Emission class: Euro 6 Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Leatherette Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes</p>	100€




		<p>Multifunction steering wheel: Yes Radio: Yes Other options: Equipped with the Geodynamics trip recording and tracking system Additional information: Starting with a booster!</p> <p>12V battery malfunction. Restart not possible.</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 01/09/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Start with booster!</p> <p>Start in the windshield 12V battery malfunction. Restart not possible.</p> <p>Invoice amount (€ incl. VAT): €29,076.24</p> <p>Invoice date (dd/mm/yyyy): 02-09-2022</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	9	<p>Make: Volkswagen Model: Caddy Maxi Version: Kombi Plus 2.0 TDI Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 25/08/2022 Fuel: Diesel Odometer reading (km): 104689 Chassis number: WV1ZZZSK2NX064318</p>	100€




		<p>Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: crew cab van Number of seats: 5 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2450 Transmission: Manual transmission Engine capacity (cc): 1968 Engine power (kW): 75 Emission class: Euro 6 Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Leatherette Air conditioning: Fully automatic climate control Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Other options: Equipped with the Geodynamics trip recording and tracking system. Additional information: Starting with booster!</p> <p>12V battery malfunction. Restart not possible.</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 06/09/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p>	
--	--	---	--



		<p>Description of vehicle damage: Start with booster! 12V battery malfunction. Restart not possible.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	10	<p>Make: Volkswagen Model: Caddy Maxi Version: Kombi Plus 2.0 TDI Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 02/09/2022 Fuel: Diesel Odometer reading (km): 141,160 Chassis number: WV1ZZZSK6NX064029 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: crew cab van Number of seats: 5 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2450 Transmission: Manual transmission Engine capacity (cc): 1968 Engine power (kW): 75 Emission class: Euro 6 Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Leatherette Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes</p>	100€



		<p>Radio: Yes Other options: Equipped with the Geodynamics trip recording and tracking system Additional information: Starting with booster!</p> <p>12V battery malfunction. Restart not possible. Oil service and inspection required. Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 13/09/2026</p> <p>Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Starting with booster!</p> <p>12V battery malfunction. Restart not possible.</p> <p>Tyre pressure loss message.</p> <p>Invoice amount (€ incl. VAT): €29,076.25</p> <p>Invoice date (dd/mm/yyyy): 13-09-2022</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	16	<p>Make: Volkswagen Model: Caddy Maxi Version: Kombi Plus 2.0 TDI Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 25/08/2022</p>	100€



Fuel: Diesel
Odometer reading (km): 97,349
Chassis number: WV1ZZZSKXNX064342
Number of keys: 2
Vehicle category: N1: max. weight <3.5 t

Body: crew cab van
Number of seats: 5
Number of axles: 2
Permitted Gross Vehicle Weight (kg): 2450
Transmission: Manual transmission
Engine capacity (cc): 1968
Engine power (kW): 75
Emission class: Euro 6
Exterior color: Gray

Metallic paint: No
Interior color: Black

Upholstery: Leatherette
Air conditioning: Manual air conditioning
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power folding mirrors: Yes
Power windows: Yes
Fog lights: Yes
Multifunction steering wheel: Yes
Radio: Yes
Other options: Equipped with the Geodynamics trip recording and tracking system
Additional information: Starting with a booster!

12V battery malfunction. Restart not possible.

Registration certificate: Yes, present


Certificate of Conformity: Yes, present

Inspection certificate: Yes, present


Inspection certificate valid until (dd/mm/yyyy):
30/08/2026

Maintenance booklet: Not present



		<p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Start with booster!</p> <p>Left reversing light</p> <p>Invoice amount (€ incl. VAT): €29,076.25</p> <p>Invoice date (dd/mm/yyyy): 31-08-2022</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	17	<p>Make: Citroën Model: Berlingo</p> <p>Version: M Light 1.5 BlueHDI</p> <p>Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 10/09/2021</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 188699 Chassis number: VR7EFYHWCMN539149 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2000 Transmission: Manual transmission Engine capacity (cc): 1499 Engine power (kW): 56 Emission class: Euro 6 Exterior color: White</p>	100€



		<p>Metallic body: No Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Navigation: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): September 29, 2026</p> <p>Maintenance booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the age and mileage or hours.) For a detailed overview, please consult the photo report. Vehicle damage description: maintenance to be performed Invoice amount (€ incl. VAT): €16,448.75 Invoice date (dd/mm/yyyy): October 5, 2021</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	20	<p>Make: Citroën Model: Berlingo Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 18/04/2019 Fuel: Diesel Odometer reading (km): 118613 Chassis number: VR7EFYHZJKJ615584 Number of keys: 3 Vehicle category: N1: max. weight <3.5 t</p>	100€



Body: Panel van
Number of seats: 3
Number of axles: 2
Maximum Permissible Weight (kg): 2400
Transmission: Manual transmission
Engine capacity (cc): 1499
Engine power (kW): 96
Emission class: Euro 6
CO2 emissions g/km: 161
Exterior color: Gray

Metallic paint: No
Interior color: Black

Upholstery: Fabric
Reversing camera: Yes
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power windows: Yes
Navigation: Yes
Radio: Yes
Other options: MTS roof rack
Additional information: Includes remaining contents
Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate
Certificate of conformity: Yes, available
Inspection certificate: Yes, available

Inspection certificate valid until (dd/mm/yyyy):
22/07/2025


Maintenance booklet: Not available

Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.


Description of vehicle damage: Missing side window

Various damages




		Maintenance report Condition: Used Quantity: 1	
	30	Make: Toyota Model: Proace Version: City 1.5L Year of manufacture (yyyy): 2025 First registration (dd/mm/yyyy): 14/04/2025 Fuel: Diesel Odometer reading (km): 55,994 Chassis number: YAREDYHT2RJ033879 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t Body: Panel van Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2020 Transmission: Manual transmission Engine capacity (cc): 1499 Engine power (kW): 75 Emission class: Euro 6e CO2 emissions (g/km): 141 Exterior color: Gray Metallic body: Yes Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes	100€



		<p>Power windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate Valid until (dd/mm/yyyy): 18/04/2026</p> <p>Maintenance booklet: Not available Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the age and mileage or hours.) For a detailed overview, please consult the photo report. Vehicle damage description: dashboard notifications Invoice amount (€ incl. VAT): €23,341.55 Invoice date (dd/mm/yyyy): 17/04/2025 Condition: Used Quantity: 1</p>	
	34	<p>Make: Renault Model: Trafic Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 01/02/2021 Fuel: Diesel Odometer reading (km): 98608 Chassis number: VF1FL000366072056 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3050 Transmission: Manual transmission Engine capacity (cc): 1997 Engine power (kW): 88 Emission class: Euro 6</p>	100€




		<p>Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Semi-automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 03/05/2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Vehicle damage description: Various damage</p> <p>Maintenance to be performed</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	35	<p>Make: Renault Model: Master Version: Aerial Work Platform Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 02/09/2020 Fuel: Diesel</p>	100€




		<p>Odometer reading (km): 119302 Chassis number: VF6VF000965618247 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Aerial work platform Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Manual transmission Engine capacity (cc): 2299 Engine power (kW): 107 Emission class: Euro 6 Exterior color: White</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Central locking: Yes Power windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Other options: Equipped with a Klubb K32 aerial work platform; serial number: K3220457; year of manufacture: 2020; power: 3.4kW; maximum height: 10.5m Maximum extension length: 6.8m; capacity: max. 1 person - 120kg.</p> <p>Equipped with a remote control for the aerial work platform.</p> <p>Equipped with a Mobitec roof ladder rack with lowering function. Additional information: Operation and odometer reading of aerial work platform unknown.</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of Conformity: Yes, available</p>	
--	--	---	--



		<p>CARPASS: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 15/01/2026 Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: various damages Condition: Used</p> <p>Quantity: 1</p>	
	36	<p>Make: Opel Model: Vivaro Version: L3 Innovation 2.0 Turbo Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 29/09/2022 Fuel: Diesel Odometer reading (km): 139657 Chassis number: VXEVFEHS7N7019503 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3100 Transmission: Automatic Engine capacity (cc): 1997 Engine power (kW): 106 Emission class: Euro 6 Exterior color: Black</p> <p>Metallic paint: Yes Interior color: Black Upholstery: Fabric Reversing camera: Yes Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes</p>	100€




		<p>Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Registration certificate: Not available The buyer will receive a certificate of loss of registration certificate. Certificate of Conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 06/10/2026 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report. Invoice amount (€ incl. VAT): €38,699.19 Invoice date (dd/mm/yyyy): 19-10-2022 Condition: Used</p> <p>Quantity: 1</p>	
	45	<p>Make: Volkswagen Model: Caddy Year of manufacture (yyyy): 2017 First registration (dd/mm/yyyy): 29/03/2017 Fuel: Diesel Odometer reading (km): 113,190 Chassis number: WV1ZZZ2KZHX122068 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2141</p>	100€




		<p>Transmission: Manual transmission Engine capacity (cc): 1968 Engine power (kW): 75 Emission class: Euro 6 Exterior color: Black</p> <p>Metallic paint: No</p> <p>Interior color: Black</p> <p>Upholstery: Fabric Central locking: Yes Cruise control: Yes Power windows: Yes Radio: Yes Tow bar: Yes Additional information: Clutch defective, vehicle cannot be put into gear!</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>CARPASS: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 24/10/2025</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Clutch defective, vehicle cannot be put into gear!</p> <p>Miscellaneous damage</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--



	54	<p>Make: Iveco Model: 35C18</p> <p>Version: Hi Matic Year of manufacture (yyyy): 2018</p> <p>First registration (dd/mm/yyyy): 13/11/2018</p> <p>Fuel: Diesel</p> <p>Odometer reading (km): 54,416 Chassis number: ZCFC235D00D614603 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Box truck Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3500 Transmission: Automatic Cylinder capacity (cc): 2938 Engine power (kW): 132 Emission class: Euro 6b Exterior color: White</p> <p>Metallic body: No Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Manual air conditioning Trip computer: Yes Power windows: Yes Multifunction steering wheel: Yes Radio: Yes Other options: Equipped with a D'Hollandia tailgate, key included. Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>CARPASS: Yes, present</p>	100€



		<p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present</p> <p>Inspection certificate valid until (dd/mm/yyyy): 07/11/2026</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	55	<p>Make: MAN Model: TGL Version: 12,180 Year of manufacture (yyyy): 2012 First registration (dd/mm/yyyy): 05/12/2012 Fuel: Diesel Odometer reading (km): 98,227 Chassis number: WMAN15ZZ5DY291428 Number of keys: 3 Category: N2: max. weight >3.5 t - <12 t</p> <p>Truck type: Full combination Number of axles: 2 Length (meters): 6.8 Maximum Permissible Weight (kg): 11990 Transmission: Automatic Cylinder capacity (cc): 4580 Engine power (kW): 132 Emission class: Euro 5 Exterior color: White Interior color: Black Upholstery: Full leather Reversing camera: Yes Air conditioning: Semi-automatic air conditioning</p>	100€



		<p>Central locking: Yes Cruise control: Yes Power windows: Yes Air suspension seat: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Tachograph: Yes Other options: equipped with signaling Equipped with a D'Hollandia tail lift with key Furnished load space with cabinets, workbench and Lighting Spare tire Wheel chocks Side door Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 17/01/2027 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
--	--	--	--