



CATALOG
Commercial vehicles



DESCRIPTION

Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.

START

26 march 2026 to 09:00 [UTC]

END DATE

2 april 2026 from 16:00 [UTC]

VIEWING

- ---
Wednesday April 01 2026 from 15:00 until 17:00
BE-2630 AARTSELAAR, HELSTSTRAAT 47

AUCTIM PARTNER

MOYERSOEN NV

Helststraat 47, 2630 Aartselaar, Belgium
+32 3 827 21 31 - info.moyersoен@auctim.be
BTW BE 0452 153 622


ISSUE - COLLECTION

- ---
Wednesday April 08 2026 from 10:00 until 12:00
BE-2630 AARTSELAAR, HELSTSTRAAT 47


Online bidding only!

Catalog created on 2 april 2026 to 04:00



	Item	Description	Start price
	1	<p>Make: Nissan</p> <p>Model: Interstar</p> <p>Version: N-Connecta L2H2 2.3dCi Year of manufacture (yyyy): 2023 First registration (dd/mm/yyyy): 22/04/2024</p> <p>Fuel: Diesel Odometer reading (km's): 60258 Chassis number: VNVM1000372054447 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body style: Enclosed panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 3500</p> <p>Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 100</p> <p>Emission class: Euro 6e</p> <p>Exterior colour: White Metallic colour: No</p> <p>Interior colour: Black Upholstery: Fabric Rear view camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes</p>	100€




		<p>Radio: Yes Tow bar: Yes Other options: equipped with T-Rack roof rack and ladder Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 08/07/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p> <p>Vehicle damage description: maintenance to be performed tail light side mirror Invoice amount (€ incl. VAT): 36,286.05 Invoice date (dd-mm-yyyy): 22-04-2024 Condition: Used Quantity: 1</p>	
	5	<p>Make: MAN Model: TGE Version: 3.140</p> <p>Year of manufacture (yyyy): 2019 First registration (dd/mm/yyyy): 27/08/2019 Fuel: Diesel Odometer reading (km's): 174431 Chassis number: WMA03VUY7K9011826 Number of keys: 1 Vehicle category: N1: max. mass <3.5t. Body style: Enclosed panel van</p> <p>Number of axles: 2</p>	100€




		<p>Maximum Permissible Mass (kg): 3500</p> <p>Transmission: Manual transmission Cylinder capacity cc: 1968 Engine power kW: 103</p> <p>Emission class: Euro 6b</p> <p>Exterior colour: White Metallic colour: No</p> <p>Interior colour: Black Upholstery: Fabric Rear view camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Not present: the buyer will receive a certificate of loss of Certificate of Conformity</p> <p>Identification Report: Yes, present Inspection Certificate: Yes, present Maintenance Booklet: Not present</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Vehicle damage description: engine dashboard warning</p> <p>Condition: Used Quantity: 1</p>	
--	--	--	--



	6	<p>Make: Renault</p> <p>Model: Master Version: Grand Confort</p> <p>Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 22/06/2022 Fuel: Diesel Odometer reading (km's): 45602 Chassis number: VF1VA000268369177 Number of keys: 2 Vehicle category: N1: max. mass <3.5t.</p> <p>Body style: Aerial work platform</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 3500</p> <p>Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 107</p> <p>Emission class: Euro 6</p> <p>Exterior color: White Metallic color: No</p> <p>Interior color: Black Upholstery: Fabric Rear view camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Radio: Yes Tow bar: Yes Other options: equipped with France Elevateur 121FT aerial work platform (without stabilizers); year of manufacture: 2022; mileage: 481h; serial no.: 21.121.11629; platform height: 10m; lateral reach: 6.5m; platform load: 120kg.</p>	100€
---	---	--	------




		<p>Registration certificate: Yes, present Certificate of conformity: Not present: the buyer will receive a certificate of loss of certificate of conformity Inspection certificate: Not present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Vehicle damage description: various damages engine dashboard warning maintenance to be performed</p> <p>Invoice amount (€ incl. VAT): 75020 Invoice date (dd-mm-yyyy): 31-01-2023 Condition: Used Quantity: 1</p>	
	9	<p>Make: Peugeot</p> <p>Model: Expert Version: Long Double Cab 2.0 BlueHDi</p> <p>Year of manufacture (yyyy): 2024</p> <p>First registration (dd/mm/yyyy): 27/01/2025</p> <p>Fuel: Diesel Odometer reading (km's): 21455 Chassis number: VF3VLEHT7R7873957 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body style: Double cab van</p> <p>Number of seats: 5</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 3080</p>	100€




		<p>Transmission: Manual transmission Cylinder capacity cc: 1997 Engine power kW: 106</p> <p>Emission class: Euro 6e</p> <p>Exterior colour: Black Metallic colour: No</p> <p>Interior colour: Black Upholstery: Fabric Rear view camera: Yes Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Multifunction steering wheel: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Tow bar: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 06/02/2026 Service booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Vehicle damage description: deep scratch across the entire left side of the vehicle Invoice amount (€ incl. VAT): 38,984.31 Invoice date (dd-mm-yyyy): 06-02-2025 Condition: Used Quantity: 1</p>	
--	--	--	--




	14	<p>Make: Mercedes-Benz</p> <p>Model: Sprinter Version: 519 CDI Year of manufacture (yyyy): 2016</p> <p>First registration (dd/mm/yyyy): 20/01/2017</p> <p>Fuel: Diesel Odometer reading (km's): 320724 Chassis number: WDB9066571P356868 Number of keys: 1 Vehicle category: N1: max. mass <3.5t.</p> <p>Body style: Enclosed panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 3500</p> <p>Transmission: Automatic transmission Cylinder capacity cc: 2987 Engine power kW: 140</p> <p>Emission class: Euro 6</p> <p>Exterior colour: Black Metallic colour: No</p> <p>Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Electric windows: Yes Navigation: Yes Radio: Yes</p> <p>Other options: Tachograph Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy)::</p>	100€
---	----	---	------




		<p>02/10/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Vehicle damage description: various damages Condition: Used Quantity: 1</p>	
	18	<p>Make: Volkswagen Model: Caddy Year of manufacture (yyyy): 2012 First registration (dd/mm/yyyy): 15/06/2012 Fuel: Diesel Odometer reading (km): 291902 Chassis number: WV1ZZZ2KZCX125742 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Transmission: Manual transmission Emission class: Euro 5 Exterior color: White</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Partial leather Air conditioning: Manual air conditioning Central locking: Yes</p> <p>Power windows: Yes</p> <p>Radio: Yes Tow bar: Yes Other options: Thule roof rack Additional information: Defective screen</p> <p>Registration certificate: Not available: the buyer</p>	100€




		<p>will receive a certificate of loss of registration certificate Certificate of Conformity: Not available: the buyer will receive a certificate of loss of conformity certificate Inspection certificate: Not available Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report. Vehicle damage description: defective screen</p> <p>Condition: Used Quantity: 1</p>	
	21	<p>Make: Ifor Williams</p> <p>Model: 2CB TT3621</p> <p>Year of manufacture (yyyy): 2025</p> <p>First registration (dd/mm/yyyy): 14/06/2025</p> <p>Trailer category: O2: max. mass >750kg - <3500kg Trailer type: Tipper Chassis number: SCKD00000S5241337 Maximum Permissible Mass (kg): 3500 Internal dimensions (L x W x H) in mm: L3619xW1950 Additional information: Equipped with aluminium checker plate side walls, spare wheel, battery key, 6 keys and remote control. Trailer registration certificate: Yes, present</p> <p>Trailer certificate of conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 19/06/2026</p>	100€



		<p>Number of axles: 2 Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the age and mileage or hours.) For a detailed overview, you can always consult the photo report.</p> <p>Invoice amount (€ incl. VAT): 13,988.69 Invoice date (dd-mm-yyyy): 19-06-2025 Condition: Used Quantity: 1</p>	
	22	<p>Make: Renault Model: Kangoo Year of manufacture (yyyy): 2020 First registration (dd/mm/yyyy): 20/11/2020 Fuel: Diesel Odometer reading (km): 104,194 Chassis number: VF1WF000966332130 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 2 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 1980 Transmission: Manual Engine capacity (cc): 1461 Engine power (kW): 59 Emission class: Euro 6 Exterior color: White</p> <p>Metallic body: No</p> <p>Interior color: Black</p> <p>Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Power windows: Yes</p> <p>Radio: Yes Additional information: Includes remaining contents (waste)</p>	100€



		<p>Start with booster!</p> <p>Registration certificate: Not available: the buyer will receive a certificate of loss of registration certificate. Certificate of Conformity: Yes, available CARPASS: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 03/06/2025 Maintenance booklet: Not available Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Dashboard engine message Injection and exhaust gas messages Side mirror Hood</p> <p>Start with booster!</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	23	<p>Make: Ford Model: Transit</p> <p>Version: Custom Year of manufacture (yyyy): 2013</p> <p>First registration (dd/mm/yyyy): 02/07/2013</p> <p>Fuel: Diesel Odometer reading (km): 255975 Chassis number: WF0YXXTTGYDB63816 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p>	100€



Body: Panel van
Number of seats: 3
Number of axles: 2
Permitted Gross Vehicle Weight (kg): 2900
Transmission: Manual transmission
Engine capacity (cc): 2198
Engine power (kW): 92
Emission class: Euro 5
Exterior color: White

Metallic body: No
Interior color: Black

Upholstery: Fabric
Air conditioning: Manual air conditioning
Trip computer: Yes
Central locking: Yes
Cruise control: Yes
Power folding mirrors: Yes
Power windows: Yes
Multifunction steering wheel: Yes
Rear parking sensors: Yes
Radio: Yes
Tow bar: Yes
Other options: signaling
Additional information: Including remaining contents: waste + incomplete furniture
Dashboard engine malfunction notification
Radio malfunction screen
Registration certificate: Yes Available

Certificate of Conformity: Yes, available

CARPASS: Yes, available


Identification Report: Yes, available

Inspection Certificate: Not available


Maintenance Booklet: Not available

Visible Vehicle Damage: Yes. For a detailed overview of the visible damage, please consult the photo report.



		<p>Description of Vehicle Damage: Dashboard message: Engine defect</p> <p>Radio screen defective</p> <p>Various damages</p> <p>Cracked windshield</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	27	<p>Make: Citroën</p> <p>Model: Berlingo</p> <p>Version: M Light 1.5 BlueHDi</p> <p>Year of manufacture (yyyy): 2023</p> <p>First registration (dd/mm/yyyy): 09/05/2023</p> <p>Fuel: Diesel</p> <p>Odometer reading (km's): 52603</p> <p>Chassis number: VR7EFYHT2PJ635373</p> <p>Number of keys: 2</p> <p>Vehicle category: N1: max. mass <3.5t. Body style: Enclosed panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 2040</p> <p>Transmission: Manual transmission</p> <p>Cylinder capacity cc: 1499</p> <p>Engine power kW: 75</p> <p>Emission class: Euro 6</p>	100€




		<p>Exterior colour: White Metallic colour: No</p> <p>Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes</p> <p>Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 21/11/2026</p> <p>Service booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Invoice amount (€ incl. VAT): 21900 Invoice date (dd-mm-yyyy): 12-01-2024</p> <p>Condition: Used Quantity: 1</p>	
	46	<p>Make: Volkswagen</p> <p>Model: Caddy Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 18/06/2021</p> <p>Fuel: Diesel Odometer reading (km's): 159721</p>	100€




		<p>Chassis number: WV1ZZZSKZMX030816 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body style: Enclosed panel van</p> <p>Number of seats: 2</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 2350</p> <p>Transmission: Automatic transmission Cylinder capacity cc: 1968</p> <p>Engine power kW: 90</p> <p>Emission class: Euro 6</p> <p>Exterior colour: Black Metallic colour: No</p> <p>Interior colour: Black Upholstery: Fabric Air conditioning: Semi-automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electrically folding mirrors: Yes Electric windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 18/03/2026</p> <p>Service booklet: Not present Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that can be expected given the age and mileage or hours.) For a detailed overview, you can always consult the photo report.</p>	
--	--	--	--



		<p>Vehicle damage description: crack in the windshield various minor damages warning selector lever.</p> <p>Condition: Used Quantity: 1</p>	
	47	<p>Make: Nissan</p> <p>Model: Interstar</p> <p>Year of manufacture (yyyy): 2022</p> <p>First registration (dd/mm/yyyy): 28/09/2022 Fuel: Diesel Odometer reading (km's): 117921 Chassis number: VNVM1000469678375 Number of keys: 1 Vehicle category: N1: max. mass <3.5t.</p> <p>Body style: Enclosed panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 3500</p> <p>Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 110</p> <p>Emission class: Euro 6</p> <p>Exterior colour: White Metallic colour: No</p> <p>Interior colour: Black Upholstery: Fabric Rear view camera: Yes</p>	100€




		<p>Air conditioning: Semi-automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Navigation: Yes Rear parking sensors: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 03/10/2026</p> <p>Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Vehicle damage description: maintenance to be performed miscellaneous damages Condition: Used Quantity: 1</p>	
	48	<p>Make: Nissan</p> <p>Model: Interstar</p> <p>Year of manufacture (yyyy): 2022</p> <p>First registration (dd/mm/yyyy): 28/09/2022 Fuel: Diesel Odometer reading (km's): 154872 Chassis number: VNVM1000969678372 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body style: Enclosed van</p> <p>Number of seats: 3</p>	100€




		<p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 3500</p> <p>Transmission: Manual transmission Cylinder capacity cc: 2299 Engine power kW: 110</p> <p>Emission class: Euro 6</p> <p>Exterior colour: White Metallic colour: No</p> <p>Interior colour: Black Upholstery: Fabric Air conditioning: Semi-automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Rear parking sensors: Yes Radio: Yes Additional information: radio code unknown. Registration certificate: Yes, present</p> <p>Certificate of conformity: Yes, present</p> <p>CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 03/10/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage you can always consult the photo report.</p> <p>Vehicle damage description: radio code unknown.</p> <p>various damages dashboard notifications maintenance to be performed Condition: Used Quantity: 1</p>	
--	--	---	--



	51	<p>Make: Renault</p> <p>Model: Trafic Year of manufacture (yyyy): 2025</p> <p>First registration (dd/mm/yyyy): 11/06/2025</p> <p>Fuel: Diesel Odometer reading (km's): 60083 Chassis number: VF1FL000874992617 Number of keys: 2 Vehicle category: N1: max. mass <3.5t.</p> <p>Body style: Double cab van</p> <p>Number of seats: 5</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 3070</p> <p>Transmission: Manual transmission Cylinder capacity cc: 1997 Engine power kW: 96</p> <p>Emission class: Euro 6e</p> <p>Exterior colour: White Metallic colour: No</p> <p>Interior colour: Black Upholstery: Fabric Air conditioning: Manual air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Navigation: Yes</p> <p>Rear parking sensors: Yes</p>	100€




		<p>Front parking sensors: Yes Radio: Yes Other options: Double cab Registration certificate: Yes, present Certificate of conformity: Yes, present Inspection certificate: No present Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Vehicle damage description: dashboard notifications miscellaneous damage Condition: Used Quantity: 1</p>	
	55	<p>Make: Nissan</p> <p>Model: Interstar</p> <p>Version: 2.0 dCi L3H2</p> <p>Year of manufacture (yyyy): 2024</p> <p>First registration (dd/mm/yyyy): 23/01/2025</p> <p>Fuel: Diesel Odometer reading (km's): 41687 Chassis number: VNVNDA00274182376 Number of keys: 2 Vehicle category: N1: max. mass <3.5t. Body style: Enclosed panel van</p> <p>Number of seats: 3</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 3500</p> <p>Transmission: Manual transmission Cylinder capacity cc: 1997</p>	100€



		<p>Engine power kW: 110</p> <p>Emission class: Euro 6e</p> <p>Exterior colour: Grey Metallic colour: No</p> <p>Interior colour: Black Upholstery: Fabric Rear view camera: Yes Air conditioning: Fully automatic air conditioning On-board computer: Yes Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes</p> <p>Rear parking sensors: Yes Front parking sensors: Yes Radio: Yes Tow bar: Yes Other options: Cargo Pack Registration certificate: Not present: the buyer will receive a certificate of loss of registration certificate Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 31/01/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Vehicle damage description: maintenance to be performed miscellaneous damages Invoice amount (€ incl. VAT): 40,342.36 Invoice date (dd-mm-yyyy): 25-01-2025 Condition: Used Quantity: 1</p>	
--	--	--	--



	126	<p>Make: Addax Motors</p> <p>Model: MTN Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 26/04/2021</p> <p>Fuel: Electric Odometer reading (km's): 2225 Chassis number: YBDNUL607EA000296 Number of keys: 3 Vehicle category: N1: max. mass <3.5t. Body style: Electric utility commercial vehicle</p> <p>Number of seats: 2</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 1840</p> <p>Transmission: Automatic transmission Engine power kW: 12.5</p> <p>Exterior color: White Metallic color: No</p> <p>Interior color: Black Upholstery: Artificial leather Rear view camera: Yes Central locking: Yes Radio: Yes Other options: equipped with 2 MCD roller shutter doors and rear door.</p> <p>lighting in cargo area.</p> <p>Additional information: Equipped with Dutch registration certificate. Registration certificate: Yes, present</p> <p>Certificate of conformity: Yes, present</p>	100€
---	-----	---	------



		<p>Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 04/05/2025 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
--	--	---	--