



CATALOG
Commercial vehicles

DESCRIPTION	Auction of commercial vehicles from various bankruptcies, seizures, breaches of contract, etc.
START	19 march 2026 to 09:00 [UTC]
END DATE	26 march 2026 from 17:00 [UTC]
VIEWING	<ul style="list-style-type: none">• Lots: 52,53 Only by appointment through the organizer. Wednesday March 25 2026 from 10:00 until 11:00 BE-1070 Anderlecht• --- Wednesday March 25 2026 from 15:00 until 17:00 BE-2630 Aartselaar, Helststraat 47
AUCTIM PARTNER	MOYERSOEN NV Helststraat 47, 2630 Aartselaar, Belgium +32 3 827 21 31 - info.moyersoen@auctim.be BTW BE 0452 153 622
ISSUE - COLLECTION	<ul style="list-style-type: none">• Lots: 52,53 --- Wednesday April 01 2026 from 10:00 until 11:00 BE-1070 Anderlecht• --- Wednesday April 01 2026 from 10:00 until 12:00 BE-2630 Aartselaar, Helststraat 47

Online bidding only!

Catalog created on 26 march 2026 to 04:00




AUCTIM
ONLINE AUCTIONS


AUCTIM - MOYERSON NV
Helststraat 47
2630 Aartselaar, Belgium
VAT BE 0452 153 622

www.auctim.com
info.moyersoem@auctim.be



	Item	Description	Start price
	14	<p>Make: Volkswagen Model: Caddy Maxi Version: Kombi Plus 2.0 TDI Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 25/08/2022 Fuel: Diesel Odometer reading (km): 103,138 Chassis number: WV1ZZZSK1NX064388 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: crew cab van Number of seats: 5 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2450 Transmission: Manual transmission Engine capacity (cc): 1968 Engine power (kW): 75 Emission class: Euro 6 Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Leatherette Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Other options: Equipped with the Geodynamics trip recording and tracking system Additional information: Starting with booster!</p> <p>12V battery malfunction. Restart not possible!</p> <p>Registration certificate: Yes, present</p>	100€




		<p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 02/09/2026</p> <p>Maintenance booklet: Not present</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Start with booster!</p> <p>12V battery malfunction. Restart not possible!</p> <p>Various damages + dashboard notifications Invoice amount (€ incl. VAT): €29,076.25</p> <p>Invoice date (dd/mm/yyyy): 06-09-2022</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	19	<p>Make: Volkswagen Model: Caddy Maxi Version: Kombi Plus 2.0 TDI Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 25/08/2022 Fuel: Diesel Odometer reading (km): 61901 Chassis number: WV1ZZZSK5NX065219 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: crew cab van Number of seats: 5 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2450 Transmission: Manual transmission Engine capacity (cc): 1968</p>	100€




		<p>Engine power (kW): 75 Emission class: Euro 6 Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Leatherette Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Other options: Equipped with the Geodynamics trip recording and tracking system. Additional information: Starting with a booster!</p> <p>12V battery malfunction. Restart not possible.</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 05/09/2026 Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Start with booster!</p> <p>12V battery malfunction. Restart not possible.</p> <p>Invoice amount (€ incl. VAT): €29,076.25</p> <p>Invoice date (dd/mm/yyyy): 07-09-2022</p> <p>Condition: Used</p>	
--	--	--	--



		Quantity: 1	
	20	<p>Make: Volkswagen Model: Caddy Maxi Version: Kombi Plus 2.0 TDI Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 25/08/2022 Fuel: Diesel Odometer reading (km): 97,959 Chassis number: WV1ZZZSK3NX065607 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: crew cab van Number of seats: 5 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2450 Transmission: Manual transmission Engine capacity (cc): 1968 Engine power (kW): 75 Emission class: Euro 6 Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Leatherette Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Fog lights: Yes Multifunction steering wheel: Yes Radio: Yes Other options: Equipped with the Geodynamics trip recording and tracking system Additional information: Starting with a booster!</p> <p>12V battery malfunction. Restart not possible.</p>	100€




		<p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 01/09/2026</p> <p>Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Start with booster! 12V battery malfunction. Restart not possible.</p> <p>Invoice amount (€ incl. VAT): €29,076.25</p> <p>Invoice date (dd/mm/yyyy): 06-09-2022</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	23	<p>Make: Volkswagen Model: Caddy Maxi Version: Kombi Plus 2.0 TDI Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 13/09/2022 Fuel: Diesel Odometer reading (km): 63,853 Chassis number: WV1ZZZSK7NX065528 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: crew cab van Number of seats: 5 Number of axles: 2</p>	100€




		<p>Permitted Gross Vehicle Weight (kg): 2450 Transmission: Manual transmission Engine capacity (cc): 1968 Engine power (kW): 75 Emission class: Euro 6 Exterior color: Gray</p> <p>Metallic paint: No Interior color: Black</p> <p>Upholstery: Leatherette Air conditioning: Fully automatic air conditioning Trip computer: Yes Central locking: Yes Cruise control: Yes Power folding mirrors: Yes Power windows: Yes Multifunction steering wheel: Yes Radio: Yes Other options: Equipped with the Geodynamics trip recording and tracking system. Additional information: Starting with booster!</p> <p>12V battery malfunction. Restart not possible!</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p> <p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 22/09/2026 Maintenance booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Start with booster!</p> <p>12V battery malfunction. Restart not possible!</p> <p>Condition: Used</p>	
--	--	---	--




		Quantity: 1	
	46	<p>Make: Volkswagen Model: Caddy Year of manufacture (yyyy): 2014 First registration (dd/mm/yyyy): 27/03/2014 Fuel: Diesel Odometer reading (km): 280,894 Chassis number: WV1ZZZ2KZEX118651 Number of keys: 2 Vehicle category: N1: max. weight <3.5 t</p> <p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 2310 Transmission: Manual Cylinder capacity (cc): 1598 Engine power (kW): 75 Emission class: Euro 5b Exterior color: White</p> <p>Metallic body: No Interior color: Black Upholstery: Fabric Air conditioning: Manual air conditioning Central locking: Yes Cruise control: Yes Power windows: Yes Radio: Yes Registration certificate: Yes, present Certificate of Conformity: Yes, present CARPASS: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): June 21, 2026</p> <p>Maintenance booklet: Not available</p> <p>Visible vehicle damage: Yes, for a detailed overview of the visible damage, please consult</p>	100€



		<p>the photo report.</p> <p>Vehicle damage description: dashboard engine message</p> <p>Various damages</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
	50	<p>Make: Nissan</p> <p>Model: e-NV 200</p> <p>Year of manufacture (yyyy): 2020</p> <p>First registration (dd/mm/yyyy): 16/12/2020</p> <p>Fuel: Electric</p> <p>Odometer reading (km's): 59223</p> <p>Chassis number: VSKYAAME0U0618583</p> <p>Number of keys: 2</p> <p>Vehicle category: N1: max. mass <3.5t.</p> <p>Body style: Enclosed panel van</p> <p>Number of seats: 2</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 2220</p> <p>Transmission: Automatic transmission</p> <p>Engine power kW: 80</p> <p>Exterior colour: White</p> <p>Metallic colour: No</p> <p>Interior colour: Black</p> <p>Upholstery: Fabric</p> <p>Rear view camera: Yes</p>	100€




		<p>Air conditioning: Manual air conditioning On-board computer: Yes</p> <p>Central locking: Yes Cruise control: Yes Electric windows: Yes Multifunction steering wheel: Yes Navigation: Yes</p> <p>Rear parking sensors: Yes Radio: Yes Seat heating: Yes</p> <p>Other options: Heated steering wheel Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 22/03/2026</p> <p>Service booklet: Not present Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Vehicle damage description: various damages Condition: Used Quantity: 1</p>	
	52	<p>Make: Renault</p> <p>Model: Kangoo Version: Maxi</p> <p>Year of manufacture (yyyy): 2019</p> <p>First registration (dd/mm/yyyy): 07/08/2019</p> <p>Fuel: Diesel Odometer reading (km's): 65333 Chassis number: VF1FW51H163336516</p>	1.125€




		<p>Number of keys: 2 Vehicle category: N1: max. mass <3.5t.</p> <p>Body style: Enclosed panel van</p> <p>Number of seats: 2</p> <p>Number of axles: 2</p> <p>Maximum Permissible Mass (kg): 2200</p> <p>Transmission: Manual transmission</p> <p>Cylinder capacity cc: 1461</p> <p>Engine power kW: 66</p> <p>Emission class: Euro 6b</p> <p>Exterior color: White</p> <p>Interior color: Grey Upholstery: Fabric</p> <p>Central locking: Yes Electric windows: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	
--	--	---	--




	53	<p>Make: Renault</p> <p>Model: Kangoo Version: Maxi</p> <p>Year of manufacture (yyyy): 2021</p> <p>First registration (dd/mm/yyyy): 23/03/2021</p> <p>Fuel: Diesel Odometer reading (km's): 63547 Chassis number: VF1WF000266982742 Number of keys: 1 Vehicle category: N1: max. mass <3.5t.</p> <p>Body style: Enclosed panel van</p> <p>Number of seats: 2</p> <p>Number of axles: 2 Transmission: Manual transmission</p> <p>Cylinder capacity cc: 1461</p> <p>Engine power kW: 70</p> <p>Emission class: Euro 6d-TEMP</p> <p>Exterior color: White</p> <p>Interior color: Grey Upholstery: Fabric</p> <p>Central locking: Yes Electric windows: Yes Radio: Yes Registration certificate: Yes, present Certificate of conformity: Yes, present Identification report: Yes, present Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy):: 05/07/2026 Visible vehicle damage: Yes, for a detailed overview of the visible damage, you can always consult the photo report.</p>	1.250€
---	----	---	--------




		Condition: Used Quantity: 1	
	57	<p>Brand: Humbaur Model: Single 2015 Year of manufacture (yyyy): 2022 First registration (dd/mm/yyyy): 15/05/2024 Trailer category: O2: max. weight >750kg - <3500kg Trailer type: Horse trailer Chassis number: WHDP1642BN1133831 Permitted Gross Vehicle Weight (kg): 1600 Internal dimensions (L x W x H) in mm: L3222mm Additional information: Equipped with an observation camera. Equipped with a breast bar and rear bar. Trailer registration certificate: Yes, available</p> <p>Trailer conformity certificate: Yes, available</p> <p>Identification report: Yes, available</p> <p>Inspection certificate: Yes, available</p> <p>Inspection certificate valid until (dd/mm/yyyy): 03/06/2025 Number of axles: 2 Visible vehicle damage: No, except for general wear and tear. (General wear and tear includes all damage that may be expected given the vehicle's age and mileage or hours.) For a detailed overview, please consult the photo report.</p> <p>Condition: Used Quantity: 1</p>	100€



	58	<p>Make: Fiat Model: Ducato Version: 150 Multijet Year of manufacture (yyyy): 2012 First registration (dd/mm/yyyy): 23/01/2013 Fuel: Diesel Odometer reading (km): 180,069 Chassis number: ZFA25000002341879 Number of keys: 1 Vehicle category: N1: max. weight <3.5 t</p>	100€
		<p>Body: Panel van Number of seats: 3 Number of axles: 2 Permitted Gross Vehicle Weight (kg): 3300 Transmission: Manual transmission Engine capacity (cc): 2287 Engine power (kW): 109 Emission class: Euro 5 Exterior color: White</p> <p>Metallic paint: No Interior color: Black/Red Upholstery: Fabric Central locking: Yes Power windows: Yes Tow bar: Yes Registration certificate: Yes, available Certificate of conformity: Yes, available Identification report: Yes, available Inspection certificate: Yes, available Inspection certificate valid until (dd/mm/yyyy): 30/01/2026 Maintenance booklet: Not available Visible vehicle damage: Yes, for a detailed overview of the visible damage, please contact us. Please always consult the photo report.</p> <p>Vehicle damage description: various damages Dashboard ABS + oil message</p> <p>Condition: Used</p> <p>Quantity: 1</p>	



	59	<p>Make: MAN Model: TGM Version: 15.250 Year of manufacture (yyyy): 2011 First registration (dd/mm/yyyy): 18/03/2011 Fuel: Diesel Odometer reading (km): 391761 Chassis number: WMAN26ZZ3BY256788 Number of keys: 1 Category: N3: max. weight >12 t</p> <p>Truck type: Full combination Number of axles: 2 Length (meters): 9.1 Permitted Gross Vehicle Weight (kg): 16,000 Transmission: Manual transmission Engine capacity (cc): 6,871 Engine power (kW): 184 Emission class: Euro 5 Exterior color: White Interior color: Black Upholstery: Fabric Central locking: Yes Cruise control: Yes Power windows: Yes Air suspension seat: Yes Fog lights: Yes Radio: Yes Tachograph: Yes Other options: Equipped with a D'Hollandia tail lift, for unprecedented functionality. Additional information: Equipped with wheel chocks.</p> <p>Start with a booster!</p> <p>Registration certificate: Yes, present</p> <p>Certificate of Conformity: Yes, present</p> <p>Identification report: Yes, present</p>	100€
---	----	---	------



		<p>Inspection certificate: Yes, present Inspection certificate valid until (dd/mm/yyyy): 19/03/2026 Maintenance booklet: Not present Visible vehicle damage: Yes. For a detailed overview of the visible damage, please consult the photo report.</p> <p>Description of vehicle damage: Dashboard does not light up.</p> <p>Various damages.</p> <p>Start with booster!</p> <p>Condition: Used</p> <p>Quantity: 1</p>	
--	--	---	--